

**UNITED STATES DISTRICT COURT
NORTHERN DISTRICT OF GEORGIA**

LEONARDO CACHO, RUBEN
CHARLES, CARL CLARK, LINDA
CREA, SR., BRANDON DUELING,
ROXIE HARRIS, WENDER JEUDY,
WANDA JONES, SEAN K. LEE, TINA
MARIE, LETITIA MATTHEWS,
ROBERT MCCUMSEY, RULESHA
MCKINNEY, BIANCA ORTIZ, FRANCY
DIAZ PEREZ, JAMES POWELL,
ANTHONY PYLES, ELLERY RICHARD,
JEFFREY ROBINSON, MARCIO
SINELLI, THOMAS STEFANOPOULOS,
BETTY WALTON, JENNIFER WALKER,
HUEY WILLIAMS, and ANTONIO
WYNN, Individually and on Behalf of All
Others Similarly Situated,

Case No. 1:24-cv-02894-ELR

Plaintiffs,

v.

MERCEDES-BENZ USA, LLC,
MERCEDES-BENZ
AKTIENGESELLSCHAFT, and
MERCEDES-BENZ GROUP
AKTIENGESELLSCHAFT,

Defendants.

**DECLARATION OF GREGORY GUNTHER IN SUPPORT OF
DEFENDANTS' MOTION TO DISMISS PLAINTIFFS' CLASS ACTION
COMPLAINT**

I, Gregory Gunther, declare and state as follows:

1. The matters referred to in this Declaration are based upon my personal knowledge, and if called and sworn as a witness, I could and would competently testify as to each of them.

2. I am Senior Manager for Vehicle Compliance and Analysis for Mercedes-Benz USA, LLC (“MBUSA”). MBUSA is a limited liability company organized under the laws of Delaware with its principal place of business in Georgia. MBUSA primarily deals with advertising and operations in the USA, while Mercedes-Benz Group Aktiengesellschaft (“MBG”) and Mercedes-Benz Aktiengesellschaft (“MBAG”) are the German entities of which MBAG deals with manufacturing while MBG does not. I am familiar with the allegations in the Class Action Complaint in this case.

3. NHTSA Recall 22V-315, which we sometimes refer to as the brake booster recall, was a voluntary recall pursuant to 49 U.S.C. § 30118, conducted in cooperation with NHTSA.

4. If a recalled vehicle comes into an authorized service center for the recall, that vehicle will be inspected. If the brake booster does not show an accumulation of corrosion, the brake booster does not need to be replaced (“Category 1 Vehicles”). Otherwise, the brake booster is replaced free of charge (“Category 3 Vehicles”). *See* Ex. 1, Mar. 2023 Owner Notification Letter.

5. Early in the recall, the automotive-parts supply chain—much like supply chains for many other items—was impacted by the COVID-19 pandemic. There were questions about whether a sufficient number of parts would be immediately available. As such, vehicles with a brake booster that passed a pressure test but nonetheless showed some accumulation of corrosion, were asked to return for a follow-up inspection within two years. These vehicles were initially called “Category 2 Vehicles.” *See* Ex. 2, June 2022 Owner Notification Letter. Both because the vast majority of inspected vehicles have proved to be Category 1 Vehicles without accumulated corrosion and because of great efforts in securing parts, the follow-up inspections have been eliminated and any recalled vehicle that is not determined to be Category 1 after inspection can obtain an immediate replacement of the brake booster, free of charge to the owner or lessee. Thus Category 2 was essentially eliminated and vehicles are determined to be either Category 1 Vehicles or Category 3 Vehicles.

6. Plaintiffs misunderstand the recall and incorrectly claim in paragraphs 6 and 102 of the Class Action Complaint that some customers would be advised not to use their vehicles for two years. As Exhibit 2 shows, owners of Category 2 Vehicles were initially asked to return for a follow-up inspection within two years but were not subject to the “stop drive” order during that that two-year period, because they “passe[d] inspection” via a “diagnostic test . . . performed to ensure the functionality

of the brake booster.”

7. Today, vehicles are only subject to a “stop drive” before the customer has the vehicle brought in for inspection – after the inspection, the vehicle is either cleared or the brake booster is replaced, but either way, the “stop drive” is lifted. *See* Ex. 1.

8. MBUSA has made inspections and (where called for) replacement parts available to all customers, free of charge.

9. MBUSA records indicate that as of November 22, 2024, Plaintiff Leonardo Cacho has not had his 2006 R350 inspected pursuant to the recall. *See* Ex. 3, Cacho Vehicle Master Inquiry (status of Campaign No. 2022050015, which is the internal designation of NHTSA Recall 22V-315, is “open”).

10. MBUSA records indicate that as of November 22, 2024, Plaintiff Ruben Charles has not had his 2008 R350 inspected pursuant to the recall. *See* Ex. 4, Charles Vehicle Master Inquiry (status of Campaign No. 2022050015 is “open”).

11. MBUSA records indicate that Plaintiff Carl Clark had his 2012 GL450 inspected on June 23, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 5, Clark VIN History; Ex. 6, Clark Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

12. MBUSA records indicate that Plaintiff Lindy Crea Sr. had his 2010

ML350 inspected on July 16, 2022, and it was determined to be a Category 1 Vehicle, meaning the brake booster did not need to be replaced and no further action was required. *See* Ex. 7, Crea VIN History (“rubber sleeve for brake booster OK, no traces of rust present”); Ex. 8, Crea Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

13. MBUSA records indicate that Plaintiff Brandon Dueling had his 2009 ML320 inspected on August 10, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 9, Dueling VIN History (“[f]ound no rust of any kind”); Ex. 10, Dueling Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

14. MBUSA records indicate that as of November 22, 2024, Plaintiff Roxie Harris has not had her 2006 R350 inspected pursuant to the recall. *See* Ex. 11, Harris Vehicle Master Inquiry (status of Campaign No. 2022050015 is “open”).

15. MBUSA records indicate that Plaintiff Wender Jeudy had his 2008 R-Class inspected on July 18, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 12, Jeudy VIN History (“[C]hecked corrosion of brake booster using the removed rubber sleeve and found OK. No further actions were required.”); Ex. 13, Jeudy Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

16. MBUSA records indicate that Plaintiff Wanda Jones had her 2008 GL450 inspected on September 14, 2022, and it was determined to be a Category 1 Vehicle, meaning her brake booster did not need to be replaced and no further action was required. *See* Ex. 14, Jones VIN History; Ex. 15, Jones Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

17. MBUSA records indicate that Plaintiff Sean K. Lee had his 2008 ML-Class inspected on July 26, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 16, Lee VIN History (“[p]erformed per workshop instructions, checked OK”); Ex. 17, Lee Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

18. MBUSA records indicate that Plaintiff Tina Marie’s 2014 G-Class is not in the population of vehicles subject to the recall; this vehicle does not have an affected brake booster. *See* Ex. 18, NHTSA Report (indicating that 2014 G-Class vehicles are not in the recall population).

19. MBUSA records indicate that Plaintiff Letitia Matthews had her 2009 GL450 inspected in June 2022, and it was determined to be a Category 2 Vehicle, meaning her brake booster required replacement. *See* Ex. 19, Matthews Vehicle Master Inquiry. MBUSA records indicate that Ms. Matthews’ brake booster was replaced in November 2022, and the recall is now “closed.” *Id.*

20. MBUSA records indicate that Plaintiff Robert McCumsey's 2012 ML350 is not in the population of vehicles subject to the recall; this vehicle does not have an affected brake booster. *See* Ex. 18, NHTSA Report (2012 ML250 vehicles are not in the recall population).

21. MBUSA records indicate that Plaintiff Rulesha McKinney's 2012 ML350 is not in the population of vehicles subject to the recall; this vehicle does not have an affected brake booster. *See* Ex. 18, NHTSA Report (2012 ML350 vehicles are not in the recall population).

22. MBUSA records indicate that Plaintiff Bianca Ortiz had her 2010 GL350 inspected on August 10, 2022. Her vehicle passed an extreme-pressure test showing that the brake booster's function was unimpaired. Nonetheless, because there was some evidence of accumulated corrosion, Ms. Ortiz's 2010 GL350 was determined to be a Category 2 Vehicle at the time. *See* Ex. 20, Ortiz VIN History. Ms. Ortiz was mailed a letter like the one attached as Exhibit 1 in March 2023 informing her that parts were then available to replace her brake booster. According to MBUSA's records, Ms. Ortiz subsequently returned for the repair and the booster was replaced. Ex. 21, Ortiz Vehicle Master Inquiry (status of Campaign No. 2022050015 is "closed").

23. MBUSA records indicate that Plaintiff Francy Diaz Perez had her 2012 GL450 inspected on July 21, 2022, and her vehicle was found to be a Category 1

Vehicle, meaning her brake booster did not need to be replaced and no further action was required. *See* Ex. 22, VIN History (“Inspect booster rubber sleeve. Dispatch rubber sleeve. Connect SDS and charger. Perform brake power test. Checks OK[.]”); Ex. 23, Perez Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”). MBUSA records further indicate that Ms. Diaz Perez’s request for reimbursement was granted by MBUSA. MBUSA paid her dealer, Mercedes-Benz of Fort Myers, \$4960 to reimburse Ms. Diaz Perez on August 4, 2022.

24. Plaintiff James Powell’s 2007 GL450 cannot be located in MBUSA records, and plaintiffs did not provide a Vehicle Identification Number or other identifying information in the complaint sufficient to identify Mr. Powell’s alleged vehicle.

25. MBUSA records indicate that Plaintiff Anthony Pyles had his 2009 ML350 inspected on July 25, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 24, Pyles VIN History; Ex. 25, Pyles Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

26. MBUSA records indicate that Plaintiff Ellery Richard had his 2011 GL550 inspected on October 4, 2023, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 26, Richard Vehicle Master Inquiry (status of Campaign No.

2022050015 is “closed”); *see also* Ex. 27, Richard Repair Order (“result found corrosion measurements Does [sic] not exceed threshold”).

27. MBUSA records indicate that Plaintiff Jeffrey Robinson had his 2010 GL450 inspected pursuant to the recall on September 7, 2022, and repairs were made accordingly. *See* Ex. 28, Robinson Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”); *see also* Ex. 29, Robinson Repair Order (“inspected the corrosion on the brake booster which passed. Added white dot, symbolizing the passing of the brake booster recall”). Additionally, third-party records indicate that Robinson no longer owns the 2010 GL450, having sold it in August 2024. *See* Ex. 30, Carfax Report for VIN 4JGBF7BE2AA567293.

28. With respect to Plaintiff Marcio Sinelli’s 2007 ML-Class, MBUSA records indicate that as of November 22, 2024, Mr. Sinelli has not attempted to have his vehicle inspected pursuant to the recall. *See* Ex. 31, Sinelli Vehicle Master Inquiry (status of Campaign No. 2022050015 is “open”).

29. With respect to Plaintiff Marcio Sinelli’s 2012 ML350, MBUSA records indicate that 2012 ML-Class is not in the population of vehicles subject to the recall; this vehicle does not have an affected brake booster. *See* Ex. 18, NHTSA Report (2012 ML350 vehicles are not in the recall population).

30. MBUSA records indicate that, as of November 22, 2024, Plaintiff Thomas Stefanopoulos has not attempted to have his 2008 ML550 inspected pursuant

to the recall. *See* Ex. 32, Stefanopoulos Vehicle Master Inquiry (status of Campaign No. 2022050015 is “open”).

31. MBUSA records indicate that Plaintiff Jennifer Walker’s 2011 GLK-Class is not in the population of vehicles subject to the recall; this vehicle does not have an affected brake booster. *See* Ex. 18, NHTSA Report (indicating that 2011 GLK-Class vehicles are not in the recall population). The GLK-Class is a different model from the GL-Class and was not included in the population of vehicles subject to the recall. *Id.*

32. Plaintiff Betty Walton’s 2007 GL-Class cannot be located in MBUSA records, and plaintiffs only provided an incomplete Vehicle Identification Number in a prior complaint, which is insufficient information to locate the alleged vehicle.

33. MBUSA records indicate that Plaintiff Huey Williams had his 2011 R350 inspected on July 21, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 33, Williams VIN History; Ex. 34, Williams Vehicle Master Inquiry (status of Campaign No. 2022050015 is “closed”).

34. MBUSA records indicate that Plaintiff Antonio Wynn had his 2012 GL450 inspected on July 14, 2022, and it was determined to be a Category 1 Vehicle, meaning his brake booster did not need to be replaced and no further action was required. *See* Ex. 35, Wynn VIN History (“Performed recall by inspecting rubber

band and found no rust points on the band. From there recall is done and passed, no further testing required.”); Ex. 36, Wynn Vehicle Master Inquiry A(status of Campaign No. 2022050015 is “closed”).

35. Plaintiffs incorrectly claim that they and some other potential class members “paid and are continuing to pay out-of-pocket for rental vehicles.” Compl. ¶ 5. Plaintiffs likewise assert that they are “left without a vehicle to drive” in the allegations in their specific paragraphs in the Class Action Complaint. *See, e.g.*, Compl. ¶¶ 17, 21, 25, 29, 35. In truth, and as discussed above, plaintiffs and the proposed putative class members are, and always have been, eligible to receive funds to pay for a rental vehicle or other transportation, including prior to the time their vehicles could be inspected. As Exhibit 2 demonstrates, other expenses also are covered for vehicle owners. MBUSA has not caused plaintiffs to incur expenses related to the recall at issue.

36. All new Mercedes-Benz vehicles have a New Vehicle Limited Warranty (“NVLW”), which warrants against “defects in material or workmanship” arising during the first 48 months or 50,000 miles, whichever comes first. *See* RJN Ex. C.


37. MBUSA is an indirect subsidiary of defendant MBG, which is also the parent company of defendant MBAG. However, MBUSA observes all corporate formalities necessary for its separate and distinct legal existence.

38. MBUSA is the exclusive U.S. importer and distributor of Mercedes-

Benz passenger vehicles and genuine parts for those vehicles. MBUSA (not MBG or MBAG) determines where to distribute Mercedes-Benz passenger vehicles and genuine parts within the U.S. market. MBUSA (not MBG or MBAG) also issues the written express limited warranties for new Mercedes-Benz passenger vehicles and some preowned Mercedes-Benz passenger vehicles.

39. I declare under penalty of perjury under the laws of the United States of America that the foregoing is true and correct.

Dated December 19, 2024



Gregory Gunther

EXHIBIT 1

IMPORTANT SAFETY RECALL


This notice applies to your vehicle, VIN: [REDACTED]

Replace Brake Booster

NHTSA Recall ID: 22V315

MBUSA ID: 2022090006 & 2022090007

STOP DRIVE REMEDY



- Remedy parts are now available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealership as soon as possible.
- This repair will be provided **FREE** of charge.

March, 2023

Dear Mercedes-Benz Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2006-2011 ML-Class and MY2006-2012 GL-Class and R-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the issue?



Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance. In some cases of severe corrosion, a particularly strong or hard braking application may cause mechanical damage in the brake booster, which can result in brake failure. In this case, it would not be possible to decelerate the vehicle via the brake pedal. Reduced brake performance or brake failure can increase the risk of a crash or injury.



What will your Mercedes-Benz Dealership do?

Parts are available for all affected vehicles to repair the recall condition. An authorized Mercedes-Benz dealer will replace the brake booster, free of charge. While the repair time may be less than 3 hours, your dealer can provide you with a better estimate of the overall time for this work. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time. You will not be charged for other service or repairs unless so requested.

How do I schedule the brake booster replacement?

- Find your nearest authorized Mercedes-Benz dealership at mbusa.com/recall to schedule your recall repair.
- Please mention you are scheduling an appointment for Mercedes-Benz Recall Campaign **2022090006** or **2022090007**.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.

Don't wait. Find an authorized Mercedes-Benz dealership near you at mbusa.com/recall and schedule the recall inspection right away.




IMPORTANT SAFETY RECALL**What are next steps after the brake booster is replaced?**

Once the brake booster is replaced, the issue is resolved and no further action is required for this recall campaign.

Steps to take.

- Find your nearest authorized Mercedes-Benz dealership at mbusa.com/recall to schedule your recall repair if the vehicle is not at the original inspecting dealership.
- Please mention you are scheduling an appointment to replace the Brake Booster for Recall Campaign **2022090006** or **2022090007**.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.

**What if I no longer own or drive the vehicle?**

In the event you no longer own or drive this vehicle, please visit mbusa.com/recalls to update your information by submitting your VIN using our VIN recall lookup tool and filling out the "no longer own" section on the website. If possible, please provide any contact information of the current owner/driver so we can contact them.

Additional Information for Owners:

A VIN-based recall lookup tool is available at mbusa.com/recalls, which can be used to check whether a vehicle has been subject to a safety recall, or had the remedy performed. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealership.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Should an authorized Mercedes-Benz dealership be unable to address your concerns please contact us at **1-888-548-8514**. We are always happy to hear from you.

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, Pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <https://www.safercar.gov>.

Don't wait. Find an authorized Mercedes-Benz dealership near you at mbusa.com/recall and schedule the recall inspection right away.



IMPORTANT SAFETY RECALL**Reimbursement to Customers for Repairs Performed Prior to Recall**

If you have already paid to have this recall condition corrected you may be eligible to receive reimbursement. Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. The following documentation must be presented to your dealer for reimbursement.

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when it was done and who repaired it.
- The total cost of the repair expense that is being claimed.
- Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- Reimbursement will be made by check from your dealer.

Please speak with your dealer concerning this matter. Thank you for your cooperation.

We apologize for any inconvenience this may have caused and look forward to taking care of this important safety recall immediately.

Sincerely,
Mercedes-Benz USA

Don't wait. Find an authorized Mercedes-Benz dealership near you
at mbusa.com/recall and schedule the recall inspection right away.



EXHIBIT 2

IMPORTANT SAFETY RECALL**This notice applies to your vehicle, VIN: [REDACTED]****Inspect Brake Booster****NHTSA Recall ID: 22V315****MBUSA ID: 2022050014 & 2022050015****STOP DRIVE ORDER!**

2022050014

2022050015

June, 2022

Dear Mercedes-Benz Owner:

STOP DRIVE – Your vehicle can be towed to an authorized dealer and a mobility solution provided or a mobile repair may be possible

- An Inspection procedure is available
- Schedule an appointment with your authorized Mercedes-Benz dealership as soon as possible.
- This repair will be provided FREE of charge.

What is the issue?

Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance. In some cases of severe corrosion, a particularly strong or hard braking application may cause mechanical damage in the brake booster, which can result in brake failure. In this case, it would not be possible to decelerate the vehicle via the brake pedal. Reduced brake performance or brake failure can increase the risk of a crash or injury.

Owners are advised not to drive their vehicles until the inspection is performed.

**What will your Mercedes-Benz Dealership do?**

An authorized Mercedes-Benz dealer will inspect the brake booster housing. While the repair time may be less than 1 hour, your dealer can provide you with a better estimate of the overall time for this inspection. After the inspection, your vehicle will fall into one of three categories:

Category 1: Vehicles will have an aesthetic rubber sleeve removed to eliminate further risk of corrosion. Vehicles that do not show advanced corrosion may continue to be driven with no further action.

Category 2: If, after the rubber sleeve is removed advanced corrosion is present, an additional diagnostic test will be performed to ensure the functionality of the brake booster. If the vehicle passes inspection, it may be driven but must return for an additional test and repair within two years. A certificate will be provided by the performing dealership. When the brake booster parts are available or the vehicle needs to be re-tested, an additional reminder owner notification letter will be mailed.

Category 3: Vehicles that do not pass the additional diagnostic test will require a brake booster replacement and the stop drive will remain in effect. At this time, parts are not available for an immediate replacement. When parts are available, an additional owner notification letter will be sent.

In the event your vehicle does not pass the diagnostic test, the vehicle may be stored at your residence or be towed to a dealership storage location. If the inspection was performed via mobile service and you choose to have the vehicle towed to a storage location, please contact the dealership to initiate the tow.

Don't wait. Find an authorized Mercedes-Benz dealership near you at mbusa.com/recall and schedule the recall inspection right away.



IMPORTANT SAFETY RECALL

If the dealership is unable to assist, please call 1-888-548-8514 to arrange a tow. In the event a brake booster repair is necessary, your authorized Mercedes-Benz dealer will help coordinate an individualized mobility solution since replacement parts are not available at this time. **This service will be provided free of charge.**

How do I schedule an inspection?

MBUSA strongly encourages you to schedule a mobile inspection with your local dealer. In the event a mobile inspection cannot be performed, a tow to your nearest authorized Mercedes-Benz dealership will be provided free of charge. To locate authorized dealers see www.MBUSA.com/recall. Please mention you are scheduling an appointment to inspect the brake booster housing under Recall Campaign #2022050014 or 2022050015. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

I need alternate transportation, what are my options?

When available, a dealer may be able to provide a loaner vehicle. If no loaner vehicles are available, other solutions may be offered such as taxi/rideshare, public transportation cost reimbursement, and/or rental reimbursement. Please discuss with your dealer the conditions and availability of each option.

Will this affect other brake system components?

This recall relates to potential advanced corrosion on the brake booster housing. If other brake system component(s) are in need of repair/replacement such that they would impair or hinder inspecting the brake booster housing, the repair/replacement must be completed first to allow the brake booster housing to be inspected. These parts and labor costs are not covered under this recall and are the responsibility of the owner.

I no longer feel safe in my car. What if I no longer want to drive this vehicle?

We ensure you that the inspection program has been thoroughly vetted. If you still have concerns please contact our customer service center at 1-888-548-8514.

Steps to take.

- Find your nearest authorized Mercedes-Benz dealership at mbusa.com/recall to schedule your recall inspection.
- Please mention you are scheduling an appointment for the Mercedes-Benz Brake Booster Recall Campaign 2022050014 or 2022050015.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.
- Based on the outcome of your vehicle's inspection, further steps will be provided as outlined above.

**What if I no longer own or drive the vehicle?**

In the event you no longer own or drive this vehicle, please visit mbusa.com/recalls to update your information by submitting your VIN using our VIN recall lookup tool and filling out the "no longer own" section on the website. If possible, please provide any contact information of the current owner/driver so we can contact them.

Additional Information for Owners:

A VIN-based recall lookup tool is available at mbusa.com/recalls, which can be used to check whether a vehicle has been subject to a safety recall, or had the remedy performed. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealership.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Don't wait. Find an authorized Mercedes-Benz dealership near you at mbusa.com/recall and schedule the recall inspection right away.



IMPORTANT SAFETY RECALL

Should an authorized Mercedes-Benz dealership be unable to address your concerns please contact us at 1-888-548-8514. We are always happy to hear from you.

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, Pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <https://www.safercar.gov>.

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already paid to have this recall condition corrected you may be eligible to receive reimbursement. Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. The following documentation must be presented to your dealer for reimbursement.

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when it was done and who repaired it.
- The total cost of the repair expense that is being claimed.
- Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- Reimbursement will be made by check from your dealer.

Please speak with your dealer concerning this matter. Thank you for your cooperation.

We apologize for any inconvenience this may have caused and look forward to taking care of this important safety recall immediately.

Sincerely,
Mercedes-Benz USA

Don't wait. Find an authorized Mercedes-Benz dealership near you
at mbusa.com/recall and schedule the recall inspection right away.



EXHIBIT 3

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB65E86A025015**

VIN: 4JGCB65E86A025015 **Owner:** NONE **Engine No:** 27296730312212
FIN: 4JG2511651A025015 **Transmission No:** 72290600565956

Vehicle Info

Model/Year: R350 2006 **Upholstery:** 201-Black Leather **Paint:** 775-Iridium Silver Metallic

Warranty & Sale

Warranty Start: 04/22/2006 **Retail Date:** 04/22/2006 **Selling Dealer:** 14318

Production Info

Radio Code: 32411 **Serial No:** 60310720 **Prod Date:** 03/24/2006

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2022050015	22P4290005	05/27/2022	OPEN	RECALL
2006090001	0604P54A47	09/13/2006	CLOSED	SERVICE
2007090001	0706P81A74	09/28/2007	CLOSED	SERVICE
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2008070002	0710P20B12	08/17/2008	CLOSED	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
WTY EXT	SEAT HEATER WARR EXT	05/16/2018	05/16/2020	0	180000		
MBCPO	24 MO CPO - 36 TOTAL	04/22/2011	04/21/2013	14937	100000	22420	1125696
MBCPO	BASE - CPO	08/23/2008	04/21/2011	14937	100000	22420	1125696
WTY EXT	AIR BAG WIRING HARNESS	04/22/2006	04/21/2016	0	100000	N/A	

Option Codes

Option	Description	Option	Description
-FL		A05	
A21		A28	
M35		R41	
U12		U61	
182		232	
280		301	
318		326	
359		413	
427		461	
477		494	
519		524	
530		551	
560		580	
636		669	
731		763	
806		810	
819		840	
848		873	
876		890	
900		989	

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB65E86A025015**

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 59900 02 7	Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	22420	465020	B	052050797	10/22/2012	10/22/2012	29830	02-KDM (Campaign)	
0 82851 90 8	COMAND /head unit High Software status	22420	414216	A	045749977	04/02/2009	04/02/2009	20217	03-Warranty	
0 20920 10 7	Campaign 2008 070002, Rep V-Belt Upper Guide Pulley	14340	143230	2	044486375	08/30/2008	08/30/2008	17063	02-KDM (Campaign)	
0 78121 51 7	Sliding roof motor Incorrect setting	22420	404753	G	044414992	08/18/2008	08/18/2008	14945	03-Warranty	
0 83219 38 7	Hose clamp, heater hose, return flow Loose	22420	404753	F	044414992	08/18/2008	08/18/2008	14945	03-Warranty	
0 81910 33 7	Campaign 2007 090001, Lubricate folding mechanism R /L outside mirrors	14318	187140	D	044106836	06/25/2008	06/25/2008	14362	02-KDM (Campaign)	
0 82876 90 8	Control unit, emergency call system Software status	14318	187140	B	044106836	06/25/2008	06/25/2008	14362	03-Warranty	
0 54970 32 8	Campaign 2006 090001, Coating on gear selector actuator motor	14318	164331	D	040825041	02/07/2007	02/07/2007	6342	02-KDM (Campaign)	
0 54575 90 8	Control unit, gasoline engine Software status	14318	164331	A	040834801	02/07/2007	02/07/2007	6342	03-Warranty	
0 54575 90 8	Control unit, gasoline engine Software status	14318	151358	B	038378754	04/07/2006	04/07/2006	11	03-Warranty	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
22420	574782	08/25/2020	08/25/2020	0049640	001	PERFORM OIL AND FILTER CHANGE, USING GENUINE MB FILTER AND MOBIL 1 SYNTHETIC OIL, TOP OFF FLUIDS AND INFLATE TIRES TO PROPER INFLATION.
22420	574782	08/25/2020	08/25/2020	0049640	039	PERFORMED FREE MULTI-POINT INSPECTION SEE YOUR SERVICE CONSULTANT FOR A PRINTED OR DIGITAL COPY.
22420	574782	08/25/2020	08/25/2020	0049640	042	REPLACE WIPER BLADES WITH GENUINE MERCEDES BLADES
22420	574782	08/25/2020	08/25/2020	0049640	056	TIRE REPLACEMENT DECLINED. SEE YOUR SERVICE CONSULTANT FOR DETAILS.
22420	574782	08/25/2020	08/25/2020	0049640	A0001802609	TS FILTER INSERT
22420	574782	08/25/2020	08/25/2020	0049640	A0009897902 19BIFU	MB 229.5 SAE 5W-40 Bulk
22420	574782	08/25/2020	08/25/2020	0049640	A1698201745	WIPER BLADE
22420	574782	08/25/2020	08/25/2020	0049640	A2518200100	TS WIPER BLADE
22420	574782	08/25/2020	08/25/2020	0049640	A2518200100 95	TS WIPER BLADE - STARPART
22420	494171	12/27/2014	12/27/2014	0034188	001	BASIC MAINTENANCE SYNTHETIC OIL & FILTER CHANGE (GASOLINE)\$110.00
22420	494171	12/27/2014	12/27/2014	0034188	009	CUSTOMER STATES ENGINE OIL LEAK
22420	494171	12/27/2014	12/27/2014	0034188	020	COMPLIMENTARY CAR WASH- INCLUDES WASH, DRY, CLEAN WINDOWS AND VACUUM, \$14.00 VALUE AT NO CHARGE
22420	494171	12/27/2014	12/27/2014	0034188	A0001802609	TS FILTER INSERT


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGCB65E86A025015**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
22420	494171	12/27/2014	12/27/2014	0034188	A0004661880	GASKET
22420	494171	12/27/2014	12/27/2014	0034188	A0004661880	GASKET
22420	494171	12/27/2014	12/27/2014	0034188	A0009985690	EXPANSION PLUG
22420	494171	12/27/2014	12/27/2014	0034188	A0009986590	CLOSING COVER
22420	494171	12/27/2014	12/27/2014	0034188	BQ1090144	Mobil 1 Formula M 5w40 Bu
22420	494171	12/27/2014	12/27/2014	0034188	BQ1460001	POWER STEERING FLUID
22420	494171	12/27/2014	12/27/2014	0034188	N007603014106	SEAL RING,VLRUB
22420	465020	10/22/2012	10/22/2012	0029830	020	COMPLIMENTARY CAR WASH- INCLUDES WASH, DRY, CLEAN WINDOWS AND VACUUM, \$14.00 VALUE AT NO CHARGE
22420	465020	10/22/2012	10/22/2012	0029830	025	PERFORM AUTOHAUS ON EDENS SERVICE A FROM \$250 APPLICABLE TAXES. (SLK, S,SL, AMG, DIESEL &V12 MODELS PRICED SLIGHTLY HIGHER). SERVICE INCL. ROTATETIRES & INSPECT ENGINE & SUSPENSION
22420	465020	10/22/2012	10/22/2012	0029830	097	PERFORMED COURTESY MULTI POINT INSPECTION
22420	465020	10/22/2012	10/22/2012	0029830	A0001802609	TS FILTER INSERT
22420	465020	10/22/2012	10/22/2012	0029830	A0009892545 12	GASOLINE FUEL ADDITIVES
22420	465020	10/22/2012	10/22/2012	0029830	A0019868071 17	WINDSHIELD WASHER FLUID
22420	465020	10/22/2012	10/22/2012	0029830	BQ1090144	Mobil 1 Formula M 5w40 Bu
22420	465020	10/22/2012	10/22/2012	0029830	N007603014106	SEAL RING,VLRUB
22420	449865	09/19/2011	09/19/2011	0028602	020	\$99.00 Basic Maintenance Package
22420	449865	09/19/2011	09/19/2011	0028602	020	\$99.00 Basic Maintenance Package
22420	449865	09/19/2011	09/19/2011	0028602	097	PERFORMED COURTESY MULTI POINT INSPECTION
22420	449865	09/19/2011	09/19/2011	0028602	A0001802609	TS FILTER INSERT
22420	449865	09/19/2011	09/19/2011	0028602	BQ1090144	Mobil 1 Formula M 5w40 Bu
22420	449865	09/19/2011	09/19/2011	0028602	N007603014106	SEAL RING,VLRUB
22420	439486	12/28/2010	12/28/2010	0024844	001	N/A
22420	439486	12/28/2010	12/28/2010	0024844	020	N/A
22420	439486	12/28/2010	12/28/2010	0024844	097	N/A
22420	439486	12/28/2010	12/28/2010	0024844		
22420	439486	12/28/2010	12/28/2010	0024844	A0001802609	TS FILTER INSERT
22420	439486	12/28/2010	12/28/2010	0024844	N007603014106	SEAL RING,VLRUB
22420	439486	12/28/2010	12/28/2010	0024844	NA	
22420	419725	08/15/2009	08/15/2009	0021379	001	N/A
22420	419725	08/15/2009	08/15/2009	0021379	01	PERFORM AUTOHAUS ON EDENS SERVICE 3 FROM \$488 + APPLICABLE TAXES. (SLK,S, SL, AMG, DIESEL AND V12 PRICED SLIGHTLY HIGHER).
22420	419725	08/15/2009	08/15/2009	0021379	012	N/A
22420	419725	08/15/2009	08/15/2009	0021379	018	N/A
22420	419725	08/15/2009	08/15/2009	0021379	097	N/A
22420	419725	08/15/2009	08/15/2009	0021379	12	*** OPCODE NOT ON REPORT ***
22420	419725	08/15/2009	08/15/2009	0021379	18	*** OPCODE NOT ON REPORT ***
22420	419725	08/15/2009	08/15/2009	0021379	97	PERFORMED COURTESY MULTI POINT INSPECTION
22420	419725	08/15/2009	08/15/2009	0021379	A0001802609	TS FILTER INSERT
22420	419725	08/15/2009	08/15/2009	0021379	A0009892545 12	GASOLINE FUEL ADDITIVES
22420	419725	08/15/2009	08/15/2009	0021379	A0019868071 17	WINDSHIELD WASHER FLUID
22420	419725	08/15/2009	08/15/2009	0021379	A1120940048	EXCHANGE SENSOR
22420	419725	08/15/2009	08/15/2009	0021379	A1120940604	TS FILTER INSERT
22420	419725	08/15/2009	08/15/2009	0021379	A1648300218 64	COMBINATION FILTER
22420	419725	08/15/2009	08/15/2009	0021379	A2720940080	GASKET
22420	419725	08/15/2009	08/15/2009	0021379	B0141	
22420	419725	08/15/2009	08/15/2009	0021379	N007603014106	SEAL RING,VLRUB
22420	419725	08/15/2009	08/15/2009	0021379	NA	
22420	407343	10/11/2008	10/11/2008	0018855		
14340	143230	08/30/2008	08/30/2008	0017063	01	OIL/FILTER/SAFETY CK
14340	143230	08/30/2008	08/30/2008	0017063	A0001802609	TS FILTER INSERT
14340	143230	08/30/2008	08/30/2008	0017063	A0019868071 17	WINDSHIELD WASHER FLUID
14340	143230	08/30/2008	08/30/2008	0017063	N007603014106	SEAL RING,VLRUB
14340	143230	08/30/2008	08/30/2008	0017063	ZLOILS	
22420	405114	08/28/2008	08/28/2008	0014940	88	ACCESSORIES
22420	405188	08/26/2008	08/26/2008	0014941	98	SUBLET CHARGES
22420	405188	08/26/2008	08/26/2008	0014941	98	SUBLET REPAIRS
22420	404939	08/19/2008	08/19/2008	0001500	72	
22420	404753	08/18/2008	08/18/2008	0014945	01	PERFORM AUTOHAUS ON EDENS SERVICE 3 FROM \$472 + SHOP SUPPLIES AND TAX. (SLK, S, SL, AMG AND V12 PRICED SLIGHTLY HIGHER).



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
22420	404753	08/18/2008	08/18/2008	0014945	09	PERFORM 4 WHEEL ALIGNMENT AND SET TO PROPER VEHICLE SPECIFICATION.
22420	404753	08/18/2008	08/18/2008	0014945	09	TIRES/ALIGNMENT
22420	404753	08/18/2008	08/18/2008	0014945	12	BRAKES
22420	404753	08/18/2008	08/18/2008	0014945	39	PERFORM CERTIFIED USED CAR VEHICLE INSPECTION
14318	187140	06/25/2008	06/25/2008	0014362	73	LOKEY LOANER CAR
14318	187140	06/25/2008	06/25/2008	0014362	87	27 POINT INSPECTION
14318	187140	06/25/2008	06/25/2008	0014362	98	SEE TECH NOTES
14318	187140	06/25/2008	06/25/2008	0014362	A0055411001	BATTERY
14318	187140	06/25/2008	06/25/2008	0014362	A1648350007	BLOWER
14318	187140	06/25/2008	06/25/2008	0014362	B8699	

EXHIBIT 4

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB65E88A068630**

VIN: 4JGCB65E88A068630 Owner: NONE Engine No: 27296730743024
FIN: 4JG2511651A068630 Transmission No: 72290601384568

Vehicle Info

Model/Year: R350V4 2008 Upholstery: Paint:

Warranty & Sale

Warranty Start: 10/26/2007 Retail Date: 10/26/2007 Selling Dealer: 51147

Production Info

Radio Code: 22622 Serial No: 70901265 Prod Date: 10/03/2007

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2022050015	22P4290005	05/27/2022	OPEN	RECALL
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2008110009	0807P54A67	11/21/2008	CLOSED	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	02/11/2008	08/11/2008	0	999999	G3	
WTY EXT	UPSTREAM OXYGEN SENSOR	10/26/2007	10/25/2017	0	UNLM	N/A	

Option Codes

Option	Description	Option	Description
-NJ		A05	
A05		A21	
A21		A39	
A39		A44	
A44		FV	
GA		H04	
H04		K14	
K14		L	
M35		M35	
P02		R02	
R02		R10	
R10		U10	
U10		U12	
U12		V36	
V36		057	
112		140	
144		182	
182		218	
218		220	
220		225	
225		226	
226		232	
232		242	
242		249	
249		275	
275		280	
280		293	
293		301	



Option	Description	Option	Description
301		359	
359		389	
389		413	
413		427	
427		438	
438		441	
441		461	
461		470	
470		488	
488		494	
494		500	
500		519	
519		524	
524		530	
530		536	
536		551	
551		580	
580		636	
636		666	
666		669	
669		673	
673		705	
723		723	
763		763	
772		772	
7XX		808	
808		810	
810		819	
819		840	
840		847	
847		848	
848		873	
873		890	
890		900	
900		989	
989			

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
1 46270 74 7	Contact spiral /volute spring, steering wheel Contact fault /open circuit	51209	692031	C	068862288	03/18/2021	03/19/2021	188330	04-Parts Warranty	
1 21616 00 0	RAP program	80149	3447817	1	105443502	12/08/2020	12/08/2020		RAPS	
0 59900 02 7	Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	51114	687519	7	052094921	10/24/2012	10/24/2012	64231	02-KDM (Campaign)	
0 82137 74 7	Light source, front fog lamp Contact fault /open circuit	56106	362184	A	048384319	09/20/2010	09/20/2010	45734	03-Warranty	
0 82280 74 7	Light source, side-marker lamp Contact fault/open circuit	56106	362184	B	048390209	09/20/2010	09/20/2010	45734	03-Warranty	
0 05N03 04 7	Solenoid, intake camshaft, right Leaks	51147	264470	B	048114298	07/26/2010	07/26/2010	45208	03-Warranty	
0 78166 GC 8	Guide rail, headliner /roller blind, panoramic sliding sunroof Noise on rough roads	51147	264470	A	048114298	07/26/2010	07/26/2010	45208	03-Warranty	



Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 05A04 73 7	Solenoid, exhaust camshaft, left Electrical fault	51126	117566	B	047580104	03/31/2010	03/31/2010	40499	03-Warranty	
0 20241 36 7	V-belt tensioning pulley Noise	51126	117566	H	047580104	03/31/2010	03/31/2010	40499	03-Warranty	
0 05N03 73 7	Solenoid, intake camshaft, right Electrical fault	51126	117566	G	047580104	03/31/2010	03/31/2010	40499	03-Warranty	
0 82282 73 7	Light source, taillight Electrical fault	51126	117566	A	047580104	03/31/2010	03/31/2010	40499	03-Warranty	
0 14212 73 7	Oxygen sensor upstream of catalytic converter Electrical fault	51126	107616	B	046345701	08/01/2009	08/01/2009	30887	03-Warranty	
0 18336 73 7	Sensor, engine oil monitoring Electrical fault	51126	107132	D	046290109	07/22/2009	07/22/2009	30088	03-Warranty	
0 05N04 73 7	Solenoid, exhaust camshaft, right Electrical fault	51126	107132	A	046290109	07/22/2009	07/22/2009	30088	03-Warranty	
0 32672 38 8	Carrier, air compressor, air suspension, level control system Loose	51126	107132	F	046290109	07/22/2009	07/22/2009	30088	03-Warranty	
0 54951 41 8	Campaign 2008 110009, Update rear SAM software	51126	102478	D	045699066	03/24/2009	03/24/2009	24143	02-KDM (Campaign)	
0 82757 EQ 7	CD changer /DVD changer No loading /ejecting of CD	51126	94947	G	044597065	09/18/2008	09/18/2008	14445	03-Warranty	
0 49016 36 8	Center muffler Noise	51126	94947	D	044597065	09/18/2008	09/18/2008	14445	03-Warranty	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51209	692031	03/18/2021	03/19/2021	0188330	001	MINOR MAINTENANCE
51209	692031	03/18/2021	03/19/2021	0188330	015	ADDITIONAL BATTERIES REPLACE (AFTER CHECK)
51209	692031	03/18/2021	03/19/2021	0188330	098	f19-
51209	692031	03/18/2021	03/19/2021	0188330	N000000004039	BATTERY
51209	690852	03/01/2021	03/05/2021	0187976	001	MINOR MAINTENANCE
51209	690852	03/01/2021	03/05/2021	0187976	001	MINOR MAINTENANCE
51209	690852	03/01/2021	03/05/2021	0187976	009	PERFORM COMPUTERIZED FOUR WHEEL ALIGNMENT
51209	690852	03/01/2021	03/05/2021	0187976	A0029903820	ECCENTRIC SCREW
51209	690852	03/01/2021	03/05/2021	0187976	A1644400001	STEERING COLUMN SWITCH
51209	690852	03/01/2021	03/05/2021	0187976	A1645458716 70	CORE CONTROL UNIT / MRSIM
51209	690852	03/01/2021	03/05/2021	0187976	A1645458716 80	REMAN CONTROL UNIT
51209	690852	03/01/2021	03/05/2021	0187976	A1714640918	CONTACT SPIRAL
51209	690852	03/01/2021	03/05/2021	0187976	N00000000327664	NUT
51209	686392	12/09/2020	03/02/2021	0187975	001	MINOR MAINTENANCE
51209	686392	12/09/2020	03/02/2021	0187975	001	MINOR MAINTENANCE
51209	686392	12/09/2020	03/02/2021	0187975	001	MINOR MAINTENANCE
51209	686392	12/09/2020	03/02/2021	0187975	001	MINOR MAINTENANCE
51209	686392	12/09/2020	03/02/2021	0187975	013	CHECK & REPLACE REAR BRAKE PADS & ROTORS (LIGHT TRUCK)
51209	686392	12/09/2020	03/02/2021	0187975	015	DISCONNECT/CONNECT GROUND LINEOF BATTERY FOR 12 V ON-BOARD ELECTRICAL SYSTEM (DURING REPAIR OPERATIONS)
51209	686392	12/09/2020	03/02/2021	0187975	039	PERFORM COURTESY INSPECTION



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51209	686392	12/09/2020	03/02/2021	0187975	057	REPLACE TRANSM. Electro-Hydraulic Control Unit assembly. Includes: R&R transm pan, R&R valve body, repl conductor plate; fill & program transm; perform adaptations.
51209	686392	12/09/2020	03/02/2021	0187975	057	SERVO MODULE REMOVE/INSTALL AND, IF NECESSARY, REPLACE
51209	686392	12/09/2020	03/02/2021	0187975	057	WIRING HARNESS FOR:..... REPLACE
51209	686392	12/09/2020	03/02/2021	0187975	058	PERFORM INITIAL DIAGNOSIS OF CLIENT COMPLAINT: READ DTCs, FOLLOW GUIDED TESTS - REPORT. (ADDITIONAL TESTING MAY BE REQUIRED)
51209	686392	12/09/2020	03/02/2021	0187975	071	REMOVE/INSTALL LOWER ENGINE COMPARTMENT PANELING AT REAR
51209	686392	12/09/2020	03/02/2021	0187975	A0002701852 70	CORE SWITCHING UNIT
51209	686392	12/09/2020	03/02/2021	0187975	A0002701852 80	REMAN SWITCHING UNIT
51209	686392	12/09/2020	03/02/2021	0187975	A0002702600 70	CORE RS CTRR. UNIT ELECTR
51209	686392	12/09/2020	03/02/2021	0187975	A0002702600 80	REMAN RS CTRR. UNIT ELECT
51209	686392	12/09/2020	03/02/2021	0187975	A0019828208	STARTER BATTERY
51209	686392	12/09/2020	03/02/2021	0187975	A0019896803 14	TRANSMISSION OIL
51209	686392	12/09/2020	03/02/2021	0187975	A0019896803 15	TRANSMISSION OIL
51209	686392	12/09/2020	03/02/2021	0187975	A0019896803 15	TRANSMISSION OIL
51209	686392	12/09/2020	03/02/2021	0187975	A0049903512	SCREW
51209	686392	12/09/2020	03/02/2021	0187975	A0049903512	SCREW
51209	686392	12/09/2020	03/02/2021	0187975	A0049903512	SCREW
51209	686392	12/09/2020	03/02/2021	0187975	A0049907512	SCREW W COLLAR A DRIVE
51209	686392	12/09/2020	03/02/2021	0187975	A0199975845	SEAL RING
51209	686392	12/09/2020	03/02/2021	0187975	A1644200620	TS BRAKE SHOE
51209	686392	12/09/2020	03/02/2021	0187975	A1644202720 90	TS DISK BRAKE PAD-STARPAR
51209	686392	12/09/2020	03/02/2021	0187975	A1644231312 90	BRAKE DISK, VENTED-STARPA
51209	686392	12/09/2020	03/02/2021	0187975	A1645401017	SENSOR
51209	686392	12/09/2020	03/02/2021	0187975	A2092500702 80	TORQUE CONVERTER
51209	686392	12/09/2020	03/02/2021	0187975	A2202703106 70	CORE CTRR. UNIT ELECTROHY
51209	686392	12/09/2020	03/02/2021	0187975	A2202703106 87	REMAN CTRR. UNIT ELECTROH
51209	686392	12/09/2020	03/02/2021	0187975	A2202710380	GASKET
51209	686392	12/09/2020	03/02/2021	0187975	A2202710380	GASKET
51209	686392	12/09/2020	03/02/2021	0187975	A2203700093	OIL GUIDE PIPE
51209	686392	12/09/2020	03/02/2021	0187975	A2204210171	PAN HEAD FIT BOLT
51209	686392	12/09/2020	03/02/2021	0187975	A2212770200	GEAR OIL FILTER
51209	686392	12/09/2020	03/02/2021	0187975	A2212770200	GEAR OIL FILTER
51209	686392	12/09/2020	03/02/2021	0187975	A2512703001 80	AUTOMATIC TRANSMISSION
51209	686392	12/09/2020	03/02/2021	0187975	A2512710097	PIPE
51209	686392	12/09/2020	03/02/2021	0187975	A2721502033	ELECTRIC CABLE
51209	686392	12/09/2020	03/02/2021	0187975	N007603012102	RING,GENERAL,METAL
51209	686392	12/09/2020	03/02/2021	0187975	N007603012102	RING,GENERAL,METAL
51113	585165	10/23/2017	10/23/2017	0158941	001	EXPRESS SERVICE VEHICLE
51113	585165	10/23/2017	10/23/2017	0158941	028	MAINTENANCE SERVICE
51113	585165	10/23/2017	10/23/2017	0158941	057	ACCESSORY ELECTRIC
51114	717650	03/10/2014	03/21/2014	0084386	007	ROTATE
51114	717650	03/10/2014	03/21/2014	0084386	026	FLEX B SERVICE
51114	717650	03/10/2014	03/21/2014	0084386	039	CHECKFLUIDS/TIRES
51114	717650	03/10/2014	03/21/2014	0084386	079	REPLACE CABIN FILTER
51114	717650	03/10/2014	03/21/2014	0084386	083	BRAKE FLUSH
51114	717650	03/10/2014	03/21/2014	0084386	098	CHECK OFR NOISE
51114	717650	03/10/2014	03/21/2014	0084386	098	CLIENT IS WAITING
51114	717650	03/10/2014	03/21/2014	0084386	A0001802609	TS FILTER INSERT
51114	717650	03/10/2014	03/21/2014	0084386	A0009890807 01	BRAKE FLUID
51114	717650	03/10/2014	03/21/2014	0084386	A0019868071 17	WINDSHIELD WASHER FLUID
51114	717650	03/10/2014	03/21/2014	0084386	A1648300218 64	COMBINATION FILTER
51114	717650	03/10/2014	03/21/2014	0084386	N007603014106	SEAL RING,VLRUB
51114	713251	01/07/2014	01/13/2014	0080841	020	LEVEL
51114	713251	01/07/2014	01/13/2014	0080841	039	CHECKFLUIDS/TIRES
51114	713251	01/07/2014	01/13/2014	0080841	054	BELT_6CYL
51114	713251	01/07/2014	01/13/2014	0080841	065	ENGINE OIL LEAK
51114	713251	01/07/2014	01/13/2014	0080841	098	CHECK OFR NOISE
51114	713251	01/07/2014	01/13/2014	0080841	098	TRANSPORTATION INFO
51114	713251	01/07/2014	01/13/2014	0080841	A0004602583	OIL TANK
51114	713251	01/07/2014	01/13/2014	0080841	A0004661880	GASKET
51114	713251	01/07/2014	01/13/2014	0080841	A0009985690	EXPANSION PLUG
51114	713251	01/07/2014	01/13/2014	0080841	A0009986590	CLOSING COVER
51114	713251	01/07/2014	01/13/2014	0080841	A0019931896	V-BELT
51114	713251	01/07/2014	01/13/2014	0080841	A0054662201	EXCHANGE POWER STEERING P
51114	713251	01/07/2014	01/13/2014	0080841	A0279979548	SEAL RING




Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51114	713251	01/07/2014	01/13/2014	0080841	A2113280058	SEAL HOLDER
51114	713251	01/07/2014	01/13/2014	0080841	A2513200425	AIR SPRING
51114	713251	01/07/2014	01/13/2014	0080841	A2720100631	HOUSING COVER W COUPLING
51114	713251	01/07/2014	01/13/2014	0080841	A2722000270	BELT TIGHTENER
51114	713251	01/07/2014	01/13/2014	0080841	BQ1460001	POWER STEERING FLUID
51114	713251	01/07/2014	01/13/2014	0080841	NA	
51113	494436	03/20/2013	03/22/2013	0071408	019	AUTO TRANS
51113	494436	03/20/2013	03/22/2013	0071408	065	TURBO/AIR INTAKE SYS
51113	494436	03/20/2013	03/22/2013	0071408	073	ALTERNATE TRANSPORTATION PROVIDED BY MB OF MORRISTOWN. LOANER VEHICLE MUST BE RETURN AS SOON AS POSSIBLE AFTER COMPLETION OF REPAIRS. \$50.00 WILLBE CHARGE FOR EACH ADDITIONAL DAY
51113	494436	03/20/2013	03/22/2013	0071408	083	PERFORM MECHANICAL FLUSH OF ALL BRAKE SYSTEM COMPONENTS TO REMOVE CONTAMINATED FLUID. REFILL WITH NEW FLUID
51113	494436	03/20/2013	03/22/2013	0071408	A0019896803 13	GEAR OIL
51113	494436	03/20/2013	03/22/2013	0071408	A0049903512	SCREW
51113	494436	03/20/2013	03/22/2013	0071408	A2202710380	GASKET
51113	494436	03/20/2013	03/22/2013	0071408	A2212770195	OIL FILTER
51113	494436	03/20/2013	03/22/2013	0071408	A2512710097	PIPE
51113	494436	03/20/2013	03/22/2013	0071408	A2730940404	TS AIR FILTER ELEMENT
51113	494436	03/20/2013	03/22/2013	0071408	N007603012102	RING,GENERAL,METAL
51113	494314	03/18/2013	03/20/2013	0071402	001	EXPRESS SERVICE VEHICLE
51113	494314	03/18/2013	03/20/2013	0071402	001	CLIENT REQUEST OIL & FILTER CHANGE USING MOBIL SYNTHETIC OIL.
51113	494314	03/18/2013	03/20/2013	0071402	009	CLIENT REQUEST FRONT & REAR WHEEL ALIGNMENT
51113	494314	03/18/2013	03/20/2013	0071402	055	TIRES/WHEELS
51113	494314	03/18/2013	03/20/2013	0071402	066	REAR AXLE ASSY
51113	494314	03/18/2013	03/20/2013	0071402	A0001802609	TS FILTER INSERT
51113	494314	03/18/2013	03/20/2013	0071402	A0003330771	SCREW
51113	494314	03/18/2013	03/20/2013	0071402	A0003520076	WASHER
51113	494314	03/18/2013	03/20/2013	0071402	A0029903820	ECCENTRIC SCREW
51113	494314	03/18/2013	03/20/2013	0071402	BQ1090144	Mobil 1 Formula M 5w40 Bu
51113	494314	03/18/2013	03/20/2013	0071402	N000000003276	NUT
51113	494314	03/18/2013	03/20/2013	0071402	N007603014106	SEAL RING,VLRUB
51114	688254	11/14/2012	11/14/2012	0064851	008	REPLACE LAMPS
51114	688254	11/14/2012	11/14/2012	0064851	010	AIR SUSPENSION
51114	688254	11/14/2012	11/14/2012	0064851	065	ENGINE LEAK
51114	688254	11/14/2012	11/14/2012	0064851	065	ENGINE NOISE
51114	688254	11/14/2012	11/14/2012	0064851	098	TRANSPORTATION INFO
51114	688254	11/14/2012	11/14/2012	0064851	A0001802609	TS FILTER INSERT
51114	688254	11/14/2012	11/14/2012	0064851	A0019931896	V-BELT
51114	688254	11/14/2012	11/14/2012	0064851	A0039899820 10	SEALANT MB
51114	688254	11/14/2012	11/14/2012	0064851	A1119970330	SCREW PLUG
51114	688254	11/14/2012	11/14/2012	0064851	A2513200158	VALVE BLOCK
51114	688254	11/14/2012	11/14/2012	0064851	A2720100828	OIL PAN
51114	688254	11/14/2012	11/14/2012	0064851	A2722021419	GUIDE PULLEY
51114	688254	11/14/2012	11/14/2012	0064851	N000000006373	BULB
51114	688254	11/14/2012	11/14/2012	0064851	N000000006373	BULB
51114	688254	11/14/2012	11/14/2012	0064851	N007603014106	SEAL RING,VLRUB
51114	688254	11/14/2012	11/14/2012	0064851	N910142010005	SCREW
51114	687519	10/24/2012	10/24/2012	0064231	008	REPLACE LAMPS
51114	687519	10/24/2012	10/24/2012	0064231	010	AIR SUSPENSION
51114	687519	10/24/2012	10/24/2012	0064231	039	21 POINT INSPECTION
51114	687519	10/24/2012	10/24/2012	0064231	045	TEST SRS SYS.
51114	687519	10/24/2012	10/24/2012	0064231	065	ENGINE NOISE
51114	687519	10/24/2012	10/24/2012	0064231	098	TRANSPORTATION INFO
56106	362184	09/20/2010	09/20/2010	0045734	097	N/A
56106	362184	09/20/2010	09/20/2010	0045734	098	N/A
51126	117566	03/31/2010	03/31/2010	0040499	020	N/A
51126	117566	03/31/2010	03/31/2010	0040499	025	N/A
51126	117566	03/31/2010	03/31/2010	0040499	073	N/A
51126	117566	03/31/2010	03/31/2010	0040499	098	N/A
51126	117566	03/31/2010	03/31/2010	0040499	20	MISCELLANEOUS
51126	117566	03/31/2010	03/31/2010	0040499	25	SERVICE 1 / A FLEX FACTORY SERVICE (EVERY 10,000 / 13,000 MILES)
51126	117566	03/31/2010	03/31/2010	0040499	73	CUSTOMER STATES PROVIDE A MERCEDES-BENZ LOANER VEHICLE.
51126	117566	03/31/2010	03/31/2010	0040499	98	RETYPE CUSTOMER CONCERN HERE !!!!!!!



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51126	117566	03/31/2010	03/31/2010	0040499	A0001802609	TS FILTER INSERT
51126	117566	03/31/2010	03/31/2010	0040499	A0019868071 17	WINDSHIELD WASHER FLUID
51126	117566	03/31/2010	03/31/2010	0040499	A1515000000	
51126	117566	03/31/2010	03/31/2010	0040499	B607272	
51126	117566	03/31/2010	03/31/2010	0040499	N000000000853	BULB
51126	117566	03/31/2010	03/31/2010	0040499	N007603014106	SEAL RING,VLRUB
51126	117566	03/31/2010	03/31/2010	0040499	WASTE	
51126	107616	08/01/2009	08/01/2009	0030887	073	N/A
51126	107616	08/01/2009	08/01/2009	0030887	73	LOANER CAR
51126	107132	07/22/2009	07/22/2009	0030088	020	N/A
51126	107132	07/22/2009	07/22/2009	0030088	020	N/A
51126	107132	07/22/2009	07/22/2009	0030088	039	N/A
51126	107132	07/22/2009	07/22/2009	0030088	073	N/A
51126	107132	07/22/2009	07/22/2009	0030088	084	N/A
51126	107132	07/22/2009	07/22/2009	0030088	20	INFORMATION
51126	107132	07/22/2009	07/22/2009	0030088	20	MISCELLANEOUS
51126	107132	07/22/2009	07/22/2009	0030088	39	TIRE MEASUREMENTS
51126	107132	07/22/2009	07/22/2009	0030088	73	LOANER CAR
51126	107132	07/22/2009	07/22/2009	0030088	84	***BRAKES ARE AT 7MM***
51126	107132	07/22/2009	07/22/2009	0030088		
51126	102478	03/24/2009	03/24/2009	0024143	009	N/A
51126	102478	03/24/2009	03/24/2009	0024143	020	N/A
51126	102478	03/24/2009	03/24/2009	0024143	026	N/A
51126	102478	03/24/2009	03/24/2009	0024143	073	N/A
51126	102478	03/24/2009	03/24/2009	0024143		
51126	102478	03/24/2009	03/24/2009	0024143	A0001802609	TS FILTER INSERT
51126	102478	03/24/2009	03/24/2009	0024143	A0003330771	SCREW
51126	102478	03/24/2009	03/24/2009	0024143	A0003330871	SCREW
51126	102478	03/24/2009	03/24/2009	0024143	A0009890807 13	BRAKE FLUID
51126	102478	03/24/2009	03/24/2009	0024143	A0019868071 14	WINDSHIELD WASHER FLUID
51126	102478	03/24/2009	03/24/2009	0024143	A0049907882	WASHER
51126	102478	03/24/2009	03/24/2009	0024143	A1120940604	TS FILTER INSERT
51126	102478	03/24/2009	03/24/2009	0024143	A1648300218 64	COMBINATION FILTER
51126	102478	03/24/2009	03/24/2009	0024143	N007603014106	SEAL RING,VLRUB
51126	102478	03/24/2009	03/24/2009	0024143	NA	
51126	94947	09/18/2008	09/18/2008	0014445	07	PERFORM COMPUTERIZED ROAD FORCE BALANCE
51126	94947	09/18/2008	09/18/2008	0014445	20	MISCELLANEOUS
51126	94947	09/18/2008	09/18/2008	0014445	25	SERVICE 1 / A FLEX FACTORY SERVICE (EVERY 10,000 / 13,000 MILES)
51126	94947	09/18/2008	09/18/2008	0014445	73	LOANER CAR
51126	94947	09/18/2008	09/18/2008	0014445	98	SEE ESTIMATE
51126	94947	09/18/2008	09/18/2008	0014445	A0001802609	TS FILTER INSERT
51126	94947	09/18/2008	09/18/2008	0014445	A0019868071 14	WINDSHIELD WASHER FLUID
51126	94947	09/18/2008	09/18/2008	0014445	A1515000000	
51126	94947	09/18/2008	09/18/2008	0014445	BBSWEIGHTS	
51126	94947	09/18/2008	09/18/2008	0014445	N007603014106	SEAL RING,VLRUB
51126	94947	09/18/2008	09/18/2008	0014445	VAL5/	
51126	94947	09/18/2008	09/18/2008	0014445	WASTE	
51147	231112	05/22/2008	05/22/2008	0008482	25	"A" SERVICE / 12 & 13 SERVICE / 1 & 3 SERVICE.

EXHIBIT 5

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF7BE0CA796834									
					"OUT-OF-FUEL"--- Special regulation		SPECIAL DAMAGE CODES		
3461060	9/19/2016	100198296	22131	2140300	SIGN AND DRIVE, "OUT-OF-FUEL"--- Special regulation	21	MBUSA SPECIAL DAMAGE CODES	59,121	
230400	5/29/2019	65758270	62106	9194002	Campaign 2019030018 - Replace Driver-Side Airbag---	91	Seats, Bunks, Restraint Systems	95,086	Open Campaign 2019030018 - 19P9194002 DRIVERS SIDE AIR BAG;CAMP.;REPLACED DRIVER STEERING AIR BAG,RECALL
274517	6/23/2022	70648456	62106	4290005	UNDEFINED---	42	Brakes	122,739	Open Campaign 2022050015 - 22P4290005 INSPECT BRAKE BOOSTER;OPEN CAMPAIGN;CHECKED AND FOUND RUBBER SLEEVE PRESENT. REMOVED RUBBER S LEEVE AND INSPECTED FOR SIGNS OF CORROSION. RUBBER SLEEVE HAS ONE SMALL SPOT OF RUST AND IS ACCEPTABLE. VEHICLE CURRENTLY PASSES IN SPECTION. RETURNED RUBBER SLEEVE TO THE PARTS DEPARTMENT AND SENT PICTURES OF VIN, RUBBERSLEEVE, AND MARKED THE BRAKE BOOSTER. NO F URTHER ACTION REQUIRED.

EXHIBIT 6


**Vehicle Master Inquiry (VMI) Dealer : 09115
FOR INTERNAL USE ONLY VIN: 4JGBF7BE0CA796834**

VIN: 4JGBF7BE0CA796834 Owner: NONE Engine 27392330464272
FIN: 4JG1648711A796834 Transmission No: 72290404057294
No:

Vehicle Info

Model/Year: GL450 2012 Upholstery: 151 Paint: 792

Warranty & Sale

Warranty Start: 05/21/2012 Retail Date: 05/21/2012 Selling Dealer: 55164

Production Info

Radio Code: 42321 Serial No: C0412251 Prod Date: 05/03/2012

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2019030018	19P9194002	03/25/2019	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages


Type	Code	Start Date	End Date	Miles Fm	Miles To DLR or GEN	Contract #	Cust. Name
MBCPO	BASE - CPO	08/12/2014	05/20/2017	0020682	0999999	84102	STRUNK, TESSINA
MNT	STAR	05/14/2012	08/12/2014	0000000	0119999	55172	Name is not available
	MNT20K						
	PPMS-2YR -						
	20,000 MILE						
	PREPAID						
	MAINTEN						
MNT	PPMSU-2	08/13/2014	09/05/2015	0020682	0999000	84102	STRUNK, TESSINA
	Services - 2						
	Service Used						
	Car PPM (For 200						

Option Codes

Option	Description	Option	Description
-NY	Wholesale state NY	A05	
A21		A22	
A49		A52	
A89		B12	Tyre-change tool kit
FV	SEDAN ELONGATED	GA	AUTOMATIC TRANSMISSION

EXHIBIT 7

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBB8GB5AA542615									
							CODES		
847231	12/2/2014	56899361	56119	2120600	"SIGN AND DRIVE, "JUMPSTART"Prgrm Eligible"--Special regulation	21	MBUSA SPECIAL DAMAGE CODES	29,879	CLIENT CALLED ROAD SIDE FOR JUMP START #1328580900; ROAD SIDE CALL SIGN AND DRIVE JUMP START;
42692	7/12/2019	65995741	56119	9193103	Campaign 2018120012 - Replace Driver-Side Airbag---	91	Seats, Bunks, Restraint Systems	70,100	customer states please perform open campaign for drivers side airbag---- 2018120012 Cause RECALL Correction REPLACE DRIVER'S AIRBAG 05CB5C
8358790	7/16/2022	70714373	67227	4290005	UNDEFINED---	42	Brakes	98,476	22P4290005 PERFORM RECALL 2022050015 VEHICLE WAS TOWED IN;F;98476 PERFORMED RECALL AS PER BULLETIN 2022050015. RUBBER SLEEVE FOR BR AKE BOOSTER OK, NO TRACES OF RUST PRESENT.

EXHIBIT 8


**Vehicle Master Inquiry (VMI) Dealer : 09115
FOR INTERNAL USE ONLY VIN: 4JGBB8GB5AA542615**

VIN: 4JGBB8GB5AA542615 Owner: NONE Engine 27296731292358
FIN: 4JG1641861A542615 Transmission No: 72290602328842
No:

Vehicle Info

Model/Year: ML350W4 2010 Upholstery: 154 Paint: 197

Warranty & Sale

Warranty Start: 09/16/2009 Retail Date: 09/16/2009 Selling Dealer: 55107

Production Info

Radio Code: 22543 Serial No: 90552732 Prod Date: 08/10/2009

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
SE	SIRIUS TRAFFIC SERVICE HAS BEEN PRE-ACTIVATED, CALL 888-465-8528 WITH CUST TO UPDATE CUST ACCOUNT
67	Vehicle has been at the following Dealer: 67227 within the previous 45 days- review for possible completion of repairs and campaigns
65	Vehicle eligible for extended emissions coverage based on the retail state
CA	CAC CASE EXISTS

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2018120012	18P9193103	12/13/2018	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To DLR or GEN	Contract Cust. Name
SIRI T	SIRI T	08/03/2009	07/08/2010	0000000	0999999 G3	03182433355 6
MBCPO	BASE - CPO	07/20/2012	09/15/2014	0017384	0100000 56119	1755694 GROSSMAN, SUSAN

Option Codes

Option	Description	Option	Description
-NY	Wholesale state NY	A05	
A21		A54	
FW	SEDAN	GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE	J1A	
J58	CONTROL CODE	K15	
L	L.H.D	M35	CAPACITY 3,5 LITRE
P01	INVALID / SALES CODE FOR PRICE	P94	Appearance Package
P96	Sports Package - exterior	R02	All season tyres


EXHIBIT 9

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF25E99A498225									
274899	12/17/2012								INTERIOR SWITCH. HOOKED UP BATTERY CHARGER AND PERFORMED SHORT TEST. HAD CODES FOR LOCK ACTUATOR MALFUNCTION;
		52518259	08512	8212673	Burner, Xenon--- Electrical fault	82	Electrical System - Body	25,325	THE TECHNICIAN NOTED THAT THE PASSENGER XENON BULB DOESN'T IGNITE AT TIMES. ARAF 15684, JU 9:10AM; RIGHT XENON BULB DISCOLORED; 25325 *ON SERVICE INSPECTION NOTED THE RIGHT SIDE XENON BULB WAS FLASHING ON IGNITION AND WAS DISCOLORED. PERFORMED REPLACEMENT OF THE RIGHT SIDE XENON BULB. VERIFIED OPERATION AND COLOR AFTER;
275403	11/7/2018	64699487	08103	9193102	Campaign 2018100010 - Replace Driver-Side Airbag---	91	Seats, Bunks, Restraint Systems	90,161	2018100010 - REPLACE DRIVER-SIDE AIRBAG; ; PERFORMED RECALL #2018100010 REPLACE THE DRIVER AIRBAG
276238	8/1/2022	70830234	08109	4290005	UNDEFINED---	42	Brakes	102,106	CAMPAIGN# 2022050015 Inspect Brake Booster without Pedal Rework; NEED TO PERFORM BRAKE BOOSTER INSPECTION CAMPAIGN; PERFORMED BRAKE BOOSTER INSPECTION CAMPAIGN REMOVED RUBBER SLEEVE AND INSPECTED AND FOUND NO RUST OF ANY KIND NO FURTHER ACTION REQUIRED. TESTED OK TEST DROVE OK
		70830234	08109	4992012	"Campaign 2020050021, Emissions Modification---	49	Exhaust System	102,106	CAMPAIGN# 2020050021. Emission Modification Category 5; NEED TO PERFORM EMISSIONS MODIFICATION CAT 5 CAMPAIGN; CONNECTED SDS AND PERFORM PRE INSPECTION AND INITIAL SHORT TEST DISCONNECTED BATTERY GROUND. Replace charge air distribution line right and left, charge air cross pipe, clean air line, exhaust gas recirculation valve, exhaust gas recirculation cooler and exhaust pipe. R&R O2 SENSOR. Replace components of the exhaust system (DPF/DOC and SCR catalyst). WHEN TRANSFERRING 2 METAL PIPES TO NEW DPF, THREADS ON ONE END OF METAL LINES CAME OUT HARSHLY AND THREADS WERE DAMAGED TO METAL LINE BUT THREADS ABLE TO BE REPAIRED. STARTED STRAIGHT TIME AT 9:56AM MILEAGE 102076 REPAIRED THREADS TO METAL LINE WITH THREAD FILE AND INST LINES. FINISH AT 12:00PM MILEAGE 102076 R&R both NOx sensors. R&R the DEF injection nozzle. CONNECTED BATTERY GROUND. CHECKED FOR FUSE 119 FOUND AND REMOVED. CONNECTED BATTERY CHARGER AND SDS PerformXentry Procedure: Service Measure Exhaust Aftertreatment System (includes update of CDI, VGS, and SCR software) UPDATE ALL CONTROL UNITS AND INIT ENGINE CONTROL UNIT Replaced the engine control unit AND PERFORMED ALL TEACH IN AND LEARNING PROCESSES PER SDS. ATTACHED LABEL & FINAL SHORT TEST AND PERFORMED 2 TRIP TEST DRIVE.
		70830234	08109	1450273	NOx sensor downstream of catalytic converter--- Electrical fault	14	Exhaust Manifold, Engine Brake, Emission Control System	102,106	PARTS WARRANTY FAULTY DOWNSTREAM NOX SENSOR; AFTER COMPLETING EMP CAMPAIGN. CHECK ENGINE LIGHT RETURNED ON FOR OPEN/SHORT TO GROUND TO DOWNSTREAM NOX SENSOR. FOUND INTERNAL ELEC SHORT TO DOWNSTREAM NOX SENSOR. NEED TO REPLACE DOWNSTREAM NOX SENSOR REPAIR IS COVERED BY PARTS WARRANTY; RAISED VEHICLE, REMOVED RIGHT SIDE BODY PANELING. R&R DOWNSTREAM NOX SENSOR. REINSTALLED RIGHT SIDE BODY PANELING. CLEARED DTCS AND PERFORM TEACH IN TO NOX SENSOR. PERFORMED 2 TRIP TEST DRIVE AND

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF25E99A498225					MY 2009	GL Class		Series 164	GL320BTC
276238	8/1/2022								NOWALL OK AT THIS TIME.
278821	10/4/2022	71097009	08109	4730573	Delivery module, AdBlue(R) tank---Electrical fault	47	Fuel System	104,835	CHECK ENGINE LIGHT RETURNED AFTER INITIAL REPAIR PARTS WARRANTY;AFTER REPLACING ADBLUE DELIVERY MODULE. FOUND PUMP ONLY PASSED SDS TEST ONE TIME AND THEN FAILED EVERY TEST AFTER AND WOULD NOT PRESSURIZE! FAULTY NEW ADBLUE DELIVERY MODULE. NEED TO REPLACE ADBLUE DELIVERY MODULE REPAIR IS COVERED UNDER PARTS WARRANTY;RAISED VEHICLE. LOOSEND AND LOWERED REAR EXHAUST ASSEMBLY . REMOVED COVER F OR ADBLUE TANK ASSY. LOWERED ADBLUE TANK ASSEMBLY AND R&R ADBLUE DELIVERY MODULE. RAISED ADBLUE TANK AND SECURED AND INSTALLED COVE R AND REINSTALLED REAR EXHAUST ASSEMBLY. PERFORMED GUIDE TEST OF ADBLUE DELIVERY MODULE AND CLEARED DTCS. DELIVERY MODULE NOW HAS PROPER PRESSURE EVERY TIME AND PASSED GUIDE TESTS EVERY TIME. IS NOW TO SPEC. PERFORM 2 TRIP TEST DRIVE AND ALL OK NOW AT THIS TIME REPAIR IS COVERED UNDER PARTS WARRANTY
		71097009	08109	4901M01	BlueTec II Extended Modification Warranty---Follow-up operations	49	Exhaust System	104,835	CHECK ENGINE LIGHT ON -- PERFORM DIAGNOSIS EMP JUST PERFORMED (p20ee);RAN SHORT TEST AND FOUND CODES 148000 UPPERMILIT OF NOX SENSO R EXCEEDED 178200 EFFICIENCY OF SCR CAT AND 131E00 RAIL PRESSURE DEVIATION PER SDS NEED TO PERFORM TEST OF ADBLUE DELIVERY PUMP PER FORMED SDS TEST OF ADBLUE DELIVERY PUMP AND ADBLUE DELIVERY PUMP FAILED TEST NEED TO REPLACE ADBLUE DELIVERY PUMP ASSY;RAISED VEHICLE . LOWER REAR EXHAUST ASSEMBLY AND REMOVED ADBLUE TANK COVER. DETACHED AND LOWERED ADBLUE TANK AND R&R ADBLUE DELIVERY PUMP. REINSTALLED ADBLUE TANK AND COVER. REATTACHED REAR EXHAUST ASSEMBLY. FILLED WITH 2.00 GAL OF ADBLUE TO FULL AND PERFORMED TEACH IN OF NEW LEVEL AND RESET VALUES. PERFORMED TEST OF NEW ADBLUE DELIVERY PUMP AND NOW PASSES. TEST DROVE 2 TRIPS OK

EXHIBIT 10


**Vehicle Master Inquiry (VMI) Dealer : 14340
FOR INTERNAL USE ONLY VIN: 4JGBF25E99A498225**

VIN: 4JGBF25E99A498225 Owner: NONE Engine 64282040794609
FIN: 4JG1648251A498225 Transmission No: 72290202030504
No:

Vehicle Info

Model/Year: GL320BTC 2009 Upholstery: 204 Paint: 040

Warranty & Sale

Warranty Start: 12/20/2008 Retail Date: 12/20/2008 Selling Dealer: 08512

Production Info

Radio Code: 61113 Serial No: 80822916 Prod Date: 12/04/2008

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
SA	SIRIUS TRAFFIC SERVICE CURRENTLY ON AUTO RENEW PLAN. NO ACTION REQUIRED.
67	Vehicle has been at the following Dealer: 08109 within the previous 45 days- review for possible completion of repairs and campaigns
OR	OPEN REPAIR ORDER EXISTS

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2009070002	0905P54B12	08/17/2009	CLOSED	SERVICE
2009090002	0907P54B62	09/18/2009	CLOSED	SERVICE
2010110005	1007P54A83	12/10/2010	CLOSED	SERVICE
2012070004	1204P54A82	08/02/2012	CLOSED	SERVICE
2018100010	1810P91C96	10/29/2018	CLOSED	RECALL
2020050021	19P4992012	01/12/2022	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To DLR or GEN	Contract Cust. Name #
SIRI T	SIRI T	12/21/2008	12/31/2999	0000000	0999999 G3	02973886982 1

Option Codes

Option	Description	Option	Description
-CO	Wholesale state CO	A05	
A21		A22	
A49		A52	
A57		FV	SEDAN ELONGATED
F16		GA	AUTOMATIC TRANSMISSION
G90		J52	

EXHIBIT 11

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB65E56A005207**

VIN: 4JGCB65E56A005207 Owner: NONE Engine No: 27296730159978
FIN: 4JG2511651A005207 Transmission No: 72290600249969

Vehicle Info

Model/Year: R 350 4MATIC 2006 Upholstery: Paint:

Warranty & Sale

Warranty Start: 01/22/2006 Retail Date: 01/22/2006 Selling Dealer: 05752

Production Info

Radio Code: 11162 Serial No: 50903079 Prod Date: 10/07/2005

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2006040007	0512P40B46	06/14/2006	CLOSED	SERVICE
2006040002	0603P59A45	05/09/2006	CLOSED	RECALL
2006090001	0604P54A47	09/13/2006	CLOSED	SERVICE
2006060005	0512P49B48	08/25/2006	CLOSED	SERVICE
2007090001	0706P81A74	09/28/2007	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	OPEN	RECALL
2008070002	0710P20B12	08/17/2008	CLOSED	SERVICE
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
WTY EXT	AIR BAG WIRING HARNESS	01/22/2006	01/21/2016	0	100000	N/A	
ELW	24 MO ELW COM	01/22/2006	01/21/2012	238	100000	05752	0938787

Option Codes

Option	Description	Option	Description
-CA		A05	
A21		A28	
FV		GA	
H04		L	
M35		R41	
U12		08I	
100		108	
182		232	
280		293	
301		349	
359		413	
427		461	
477		494	
519		524	
530		536	
551		560	
575		581	
582		596	
636		669	
705		763	
7XX		806	
810		819	



Option	Description	Option	Description
840		848	
890		904	
989			

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
1 21402 00 0	ROADSIDE-JUMP START - (DAY-TIME)	05257	693734	A	101843023	04/21/2018	04/21/2018		RAPS	
0 59900 02 7	Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	05171	542461	D	052330082	11/26/2012	11/26/2012	79730	02-KDM (Campaign)	
0 32511 04 7	Spring strut /air spring, rear Leaks	05171	522561	A	050498287	12/12/2011	12/12/2011	69019	08-POW/ELW	
0 33113 36 7	Supporting ball joint, lower, front axle Noise	05171	522561	B	050498287	12/12/2011	12/12/2011	69019	08-POW/ELW	
0 05A03 73 7	Solenoid, intake camshaft, left Electrical fault	05171	517010	C	049983454	08/31/2011	08/31/2011	66594	08-POW/ELW	
0 74311 73 7	Door lock /liftgate latch, rear-end door /liftgate Electrical fault	05171	510048	B	049368729	04/12/2011	04/12/2011	62474	08-POW/ELW	
0 09148 06 7	Flange, crankcase ventilation system Broken	05171	505445	I	048971997	01/19/2011	01/19/2011	59795	08-POW/ELW	
0 82331 73 7	Cigarette lighter Electrical fault	05171	505445	B	048971997	01/19/2011	01/19/2011	59795	08-POW/ELW	
0 82853 36 7	Navigation processor Noise	05171	505445	C	048971997	01/19/2011	01/19/2011	59795	08-POW/ELW	
0 05007 82 7	Closing cover camshaft Oil loss	05171	505445	H	048971997	01/19/2011	01/19/2011	59795	08-POW/ELW	
0 20253 36 7	Guide pulley Noise	05171	483715	A	046933017	11/27/2009	11/27/2009	46069	03-Warranty	
0 50105 73 7	Fill level sensor, coolant Electrical fault	05171	474546	A	046147728	06/23/2009	06/23/2009	41875	03-Warranty	
0 82380 74 7	Socket, light source, taillamp Contact fault /open circuit	05171	474453	A	046147720	06/19/2009	06/19/2009	41844	03-Warranty	
0 82285 73 7	Light source, license plate lamp Electrical fault	05171	465320	F	045399227	01/30/2009	01/30/2009	37996	03-Warranty	
0 78T00 36 7	Slide shoe, right, panoramic sunroof Noise	05171	465320	H	045399227	01/30/2009	01/30/2009	37996	03-Warranty	
0 20920 10 7	Campaign 2008 070002, Rep V-Belt Upper Guide Pulley	05171	465320	J	045399227	01/30/2009	01/30/2009	37996	02-KDM (Campaign)	
0 46521 04 7	Oil tank, power steering pump Leaks	05171	465320	I	045399227	01/30/2009	01/30/2009	37996	03-Warranty	
0 81910 33 7	Campaign 2007 090001, Lubricate folding mechanism R /L outside mirrors	05171	450324	B	044187785	07/10/2008	07/10/2008	31970	02-KDM (Campaign)	



Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 82C01 38 7	Taillamp left Loose	05171	438296	B	043265554	02/07/2008	02/07/2008	24556	03-Warranty	
0 82621 73 7	Servo motor, electric central locking Electrical fault	05171	438296	A	043265554	02/07/2008	02/07/2008	24556	03-Warranty	
0 54970 32 8	Campaign 2006 090001, Coating on gear selector actuator motor	05171	418260	H	041272067	04/10/2007	04/10/2007	13986	02-KDM (Campaign)	
0 74321 51 7	Lock striker, liftgate Incorrect setting	05171	418260	D	041272067	04/10/2007	04/10/2007	13986	03-Warranty	
0 49900 32 7	Campaign 2006 060005, Inst shim plates, ft exhaust brackets and transmission	05171	405630	C	039534892	08/29/2006	08/29/2006	6946	02-KDM (Campaign)	
0 59910 35 7	Campaign 2006 040002, Insp starter wiring harness, rep or repl if req. 251, MY06	05171	405630	A	039534892	08/29/2006	08/29/2006	6946	02-KDM (Campaign)	
0 40910 31 8	Campaign 2006 040007, Insp tire air valve, rep spare tire if req, 251 MY 06	05171	405630	B	039534892	08/29/2006	08/29/2006	6946	02-KDM (Campaign)	
0 69P01 38 7	Rain strip /water deflector right Loose	05752	6684	C	037998846	02/22/2006	02/22/2006	1249	03-Warranty	
0 21327 00 8	???	05752	6684	B	037998846	02/22/2006	02/22/2006	1249	03-Warranty	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05733	836027	02/16/2022	02/24/2022	0153494	018	COOLANT SYSTEM SERVICE/FLUSH - \$149.95
05733	836027	02/16/2022	02/24/2022	0153494	020	COMPLIMENTARY CAR WASH (\$19.95 VALUE) CLEAN EXTERIOR, DRESS TIRES, VACUUM INTERIOR AND CLEAN ALL WINDOWS INSIDE AND OUTSIDE
05733	836027	02/16/2022	02/24/2022	0153494	065	ENGINE TIMING, VALVE TRAIN
05733	836027	02/16/2022	02/24/2022	0153494	097	
05733	836027	02/16/2022	02/24/2022	0153494	098	THIS LINE CREATED FOR ADDITIONAL INFORMATION ENTRY
05733	836027	02/16/2022	02/24/2022	0153494	098	CLIENT IS PROVIDING HIS/HER OWN TRANSPORTATION
05733	836027	02/16/2022	02/24/2022	0153494	098	CHECK AND CORRECT AS NECESSARY-- ALL TIRES FOR CORRECT PRESSURES
05733	836027	02/16/2022	02/24/2022	0153494	098	THIS LINE FOR ESTIMATE PURPOSES AS NECESSARY
05733	836027	02/16/2022	02/24/2022	0153494	098	MISC. SHOP CHARGES
05733	836027	02/16/2022	02/24/2022	0153494	A2720100172 64	OIL DIPSTICK
05733	836027	02/16/2022	02/24/2022	0153494	A2720510177	MAGNET
05733	836027	02/16/2022	02/24/2022	0153494	BQ1030004	Anticorrosion/Antifreeze
05257	718044	04/16/2019	04/23/2019	0134376	017	A/C AND CLIMATE SYSTEMS OPERATIONS
05257	718044	04/16/2019	04/23/2019	0134376	055	SET TIRE PRESSURES TO FACTORY SPECIFICATIONS;RIGHT FRONT ____ LEFT FRONT ____ RIGHT REAR ____ LEFT REAR
05257	718044	04/16/2019	04/23/2019	0134376	A0139977545	SEAL RING
05257	718044	04/16/2019	04/23/2019	0134376	A2518301215	PIPE LINE
05257	718044	04/16/2019	04/23/2019	0134376	A2518301215	PIPE LINE
05257	718044	04/16/2019	04/23/2019	0134376	BQ4830192	REFRIGERANT 30LB CYLINDER
05257	717469	04/08/2019	04/18/2019	0134279	007	MOUNT AND BALANCE 1 TIRE
05257	717469	04/08/2019	04/18/2019	0134279	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05257	717469	04/08/2019	04/18/2019	0134279	010	SUSPENSION OPERATIONS
05257	717469	04/08/2019	04/18/2019	0134279	012	BRAKE OPERATIONS


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGCB65E56A005207**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05257	717469	04/08/2019	04/18/2019	0134279	025	PERFORM FLEX "A" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05257	717469	04/08/2019	04/18/2019	0134279	057	ENGINE ELECTRICAL AND BATTERY OPERATIONS
05257	717469	04/08/2019	04/18/2019	0134279	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05257	717469	04/08/2019	04/18/2019	0134279	098	MISC. SHOP CHARGES
05257	717469	04/08/2019	04/18/2019	0134279	A0001802609	TS FILTER INSERT
05257	717469	04/08/2019	04/18/2019	0134279	A0009862000 09	WINDSHIELD WASHER FLUID
05257	717469	04/08/2019	04/18/2019	0134279	A0009898301 USB9	MB Genuine Engine Oil 5w-
05257	717469	04/08/2019	04/18/2019	0134279	A2113280058	SEAL HOLDER
05257	717469	04/08/2019	04/18/2019	0134279	A2513200425	AIR SPRING
05257	717469	04/08/2019	04/18/2019	0134279	BQ8402429	CONTINENTAL 255/55R18 SKU
05257	717469	04/08/2019	04/18/2019	0134279	N000000008155	BULB
05257	717469	04/08/2019	04/18/2019	0134279	N007603014106	SEAL RING,VLRUB
05257	693734	04/21/2018	04/26/2018	0127231	015	CALIF FEE FOR AUTO BATTERY SALE
05257	693734	04/21/2018	04/26/2018	0127231	057	ENGINE ELECTRICAL AND BATTERY OPERATIONS
05257	693734	04/21/2018	04/26/2018	0127231	098	MISC. SHOP CHARGES
05257	693734	04/21/2018	04/26/2018	0127231	A0045418601	BATTERY
05257	692815	04/09/2018	04/16/2018	0127200	007	MOUNT AND BALANCE 4 TIRES
05257	692815	04/09/2018	04/16/2018	0127200	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05257	692815	04/09/2018	04/16/2018	0127200	012	BRAKE OPERATIONS
05257	692815	04/09/2018	04/16/2018	0127200	026	PERFORM FLEX "B" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05257	692815	04/09/2018	04/16/2018	0127200	083	PERFORM BRAKE FLUID EXCHANGE PER MERCEDES BENZ REQUIRED MAINTENANCE SCHEDULE
05257	692815	04/09/2018	04/16/2018	0127200	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05257	692815	04/09/2018	04/16/2018	0127200	098	DISPOSABLE FEE FOR USED OIL WITH OR WITHOUT FILTER
05257	692815	04/09/2018	04/16/2018	0127200	098	DISPOSAL FEE FOR SOLVENTS OR ANTI FREEZE
05257	692815	04/09/2018	04/16/2018	0127200	098	DISPOSAL FEE FOR USED TIRES
05257	692815	04/09/2018	04/16/2018	0127200	098	MISC. SHOP CHARGES
05257	692815	04/09/2018	04/16/2018	0127200	A0001802609	TS FILTER INSERT
05257	692815	04/09/2018	04/16/2018	0127200	A0009862000 09	WINDSHIELD WASHER FLUID
05257	692815	04/09/2018	04/16/2018	0127200	A0009890807 01	BRAKE FLUID
05257	692815	04/09/2018	04/16/2018	0127200	A0009898301 USB9	MB Genuine Engine Oil 5w-
05257	692815	04/09/2018	04/16/2018	0127200	A0019899451 09	BRAKE PASTE
05257	692815	04/09/2018	04/16/2018	0127200	A0019899451 09	BRAKE PASTE
05257	692815	04/09/2018	04/16/2018	0127200	A0084205320	TS DISK BRAKE PAD
05257	692815	04/09/2018	04/16/2018	0127200	A1644202220 64	TS DISK BRAKE PAD
05257	692815	04/09/2018	04/16/2018	0127200	A1644211312	BRAKE DISK, VENTED
05257	692815	04/09/2018	04/16/2018	0127200	A1644231212	BRAKE DISC, UNVENTED
05257	692815	04/09/2018	04/16/2018	0127200	A1645401017	SENSOR
05257	692815	04/09/2018	04/16/2018	0127200	A1645401017	SENSOR
05257	692815	04/09/2018	04/16/2018	0127200	A1648300218 64	COMBINATION FILTER
05257	692815	04/09/2018	04/16/2018	0127200	A2204210171	PAN HEAD FIT BOLT
05257	692815	04/09/2018	04/16/2018	0127200	A2204210171	PAN HEAD FIT BOLT
05257	692815	04/09/2018	04/16/2018	0127200	BQ8402429	CONTINENTAL 255/55R18 SKU
05257	692815	04/09/2018	04/16/2018	0127200	N000000001081	SCREW
05257	692815	04/09/2018	04/16/2018	0127200	N007603014106	SEAL RING,VLRUB
05257	692815	04/09/2018	04/16/2018	0127200	N910106014012	SCREW
05257	692815	04/09/2018	04/16/2018	0127200	NA	
05257	692815	04/09/2018	04/16/2018	0127200	NA	
05257	692815	04/09/2018	04/16/2018	0127200	NA	
05257	692815	04/09/2018	04/16/2018	0127200	NA	
05257	668268	03/24/2017	03/27/2017	0116254	025	PERFORM FLEX "A" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05257	668268	03/24/2017	03/27/2017	0116254	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05257	668268	03/24/2017	03/27/2017	0116254	098	DISPOSABLE FEE FOR USED OIL WITH OR WITHOUT FILTER
05257	668268	03/24/2017	03/27/2017	0116254	A0001802609	TS FILTER INSERT


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGCB65E56A005207**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05257	668268	03/24/2017	03/27/2017	0116254	A0008280388 10	Keyless remote coin batte
05257	668268	03/24/2017	03/27/2017	0116254	A0009862000 09	WINDSHIELD WASHER FLUID
05257	668268	03/24/2017	03/27/2017	0116254	A0009898301 USB9	MB Genuine Engine Oil 5w-
05257	668268	03/24/2017	03/27/2017	0116254	N007603014106	SEAL RING,VLRUB
05257	639354	12/21/2015	12/28/2015	0108226	057	ENGINE ELECTRICAL AND BATTERY OPERATIONS
05257	639354	12/21/2015	12/28/2015	0108226	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____ RIGHT FRONT ____ LEFT REAR ____ RIGHT REAR ____
05257	639354	12/21/2015	12/28/2015	0108226	A1647400735	LOCK
05257	639354	12/21/2015	12/28/2015	0108226	A1649005401	EXCHANGE CONTROL UNIT
05257	623352	04/23/2015	04/25/2015	0102966	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05257	623352	04/23/2015	04/25/2015	0102966	026	PERFORM FLEX "B" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05257	623352	04/23/2015	04/25/2015	0102966	083	PERFORM BRAKE FLUID EXCHANGE PER MERCEDES BENZ REQUIRED MAINTENANCE SCHEDULE
05257	623352	04/23/2015	04/25/2015	0102966	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____ RIGHT FRONT ____ LEFT REAR ____ RIGHT REAR ____
05257	623352	04/23/2015	04/25/2015	0102966	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05257	623352	04/23/2015	04/25/2015	0102966	A0001802609	TS FILTER INSERT
05257	623352	04/23/2015	04/25/2015	0102966	A0009890807 01	BRAKE FLUID
05257	623352	04/23/2015	04/25/2015	0102966	A0009898301 USB9	MB Genuine Engine Oil 5w-
05257	623352	04/23/2015	04/25/2015	0102966	A0019868071 17	WINDSHIELD WASHER FLUID
05257	623352	04/23/2015	04/25/2015	0102966	A1648300218 64	COMBINATION FILTER
05257	623352	04/23/2015	04/25/2015	0102966	N007603014106	SEAL RING,VLRUB
05257	623352	04/23/2015	04/25/2015	0102966	NA	
05171	572244	04/16/2014	04/16/2014	0097464	020	CLIENT AUTHORIZES MERCEDES BENZ OF ENCINO TO OPERATE VEHICLE DURING AND AFTER BUSINESS HOURS FOR TEST PURPOSES
05171	572244	04/16/2014	04/16/2014	0097464	055	SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:RIGHT FRONT ____ LEFT FRONT ____ RIGHT REAR ____ LEFT REAR ____
05171	572244	04/16/2014	04/16/2014	0097464	057	ELECTRICIAL OPERATIONS 6 CYL
05171	571889	04/10/2014	04/14/2014	0094581	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05171	571889	04/10/2014	04/14/2014	0094581	012	BRAKE OPERATIONS 6 CYL
05171	571889	04/10/2014	04/14/2014	0094581	018	COOLANT SYSTEM SERVICE:REMOVE OLD COOLANT & REPLACE WITH NEW COOLANT FORTIFIED WITH WATERPUMP LUBE, CORROSION CONTROL AND SYSTEM SEALER
05171	571889	04/10/2014	04/14/2014	0094581	019	AUTO TRANS OPERATIONS 6 CYL
05171	571889	04/10/2014	04/14/2014	0094581	025	PERFORM FLEX "A" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05171	571889	04/10/2014	04/14/2014	0094581	055	ALL TIRE OPERATIONS
05171	571889	04/10/2014	04/14/2014	0094581	057	ELECTRICIAL OPERATIONS 6 CYL
05171	571889	04/10/2014	04/14/2014	0094581	065	ENGINE OPERATIONS 6 CYL
05171	571889	04/10/2014	04/14/2014	0094581	083	PERFORM BRAKE FLUID EXCHANGE PER MERCEDES BENZ REQUIRED MAINTENANCE SCHEDULE
05171	571889	04/10/2014	04/14/2014	0094581	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____ RIGHT FRONT ____ LEFT REAR ____ RIGHT REAR ____
05171	571889	04/10/2014	04/14/2014	0094581	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	571889	04/10/2014	04/14/2014	0094581	A0001802609	TS FILTER INSERT
05171	571889	04/10/2014	04/14/2014	0094581	A0009890807 01	BRAKE FLUID
05171	571889	04/10/2014	04/14/2014	0094581	A0019868071 17	WINDSHIELD WASHER FLUID
05171	571889	04/10/2014	04/14/2014	0094581	A0019899451	BRAKE PASTE
05171	571889	04/10/2014	04/14/2014	0094581	A0044205220	SET OF BRAKEPADS
05171	571889	04/10/2014	04/14/2014	0094581	A1644200820	PARTS KIT BRAKE PAD
05171	571889	04/10/2014	04/14/2014	0094581	A1645401017	SENSOR
05171	571889	04/10/2014	04/14/2014	0094581	A1662400618	TRANSMISSION BEARING
05171	571889	04/10/2014	04/14/2014	0094581	A2518200121	BLINKER LAMP
05171	571889	04/10/2014	04/14/2014	0094581	A2730940404	TS AIR FILTER ELEMENT
05171	571889	04/10/2014	04/14/2014	0094581	BQ1030004	Anticorrosion/Antifreeze
05171	571889	04/10/2014	04/14/2014	0094581	BQ1090144	Mobil 1 Formula M 5w40 Bu



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05171	571889	04/10/2014	04/14/2014	0094581	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	571889	04/10/2014	04/14/2014	0094581	N000000007651	FUSE LINK
05171	571889	04/10/2014	04/14/2014	0094581	N000000008140	BULB
05171	571889	04/10/2014	04/14/2014	0094581	N007603014106	SEAL RING,VLRUB
05171	571889	04/10/2014	04/14/2014	0094581	NA	
05171	571889	04/10/2014	04/14/2014	0094581	NA	
05171	550517	04/02/2013	04/08/2013	0083128	007	MOUNT AND BALANCE 2 TIRES
05171	550517	04/02/2013	04/08/2013	0083128	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05171	550517	04/02/2013	04/08/2013	0083128	026	PERFORM FLEX "B" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05171	550517	04/02/2013	04/08/2013	0083128	055	SET TIRE PRESSURES TO FACTORY SPECIFICATIONS;RIGHT FRONT ____ LEFT FRONT ____ RIGHT REAR ____ LEFT REAR
05171	550517	04/02/2013	04/08/2013	0083128	057	ELECTRICAL OPERATIONS 6 CYL
05171	550517	04/02/2013	04/08/2013	0083128	073	PROVIDE CLIENT WITH MERCEDES-BENZ LOAN VEHICLE AS ALTERNATIVE TRANSPORTATION AS A GOODWILL GESTURE. CLIENT AGREES TO BE LIABLE FOR ANY DAMAGE, PARKING VIOLATIONS, AND ANY GASOLINE
05171	550517	04/02/2013	04/08/2013	0083128	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	550517	04/02/2013	04/08/2013	0083128	A0001802609	TS FILTER INSERT
05171	550517	04/02/2013	04/08/2013	0083128	A0019868071 17	WINDSHIELD WASHER FLUID
05171	550517	04/02/2013	04/08/2013	0083128	A0079976182	HOSE,HEATER ELEMENT,VLRUB
05171	550517	04/02/2013	04/08/2013	0083128	A1648300218 64	COMBINATION FILTER
05171	550517	04/02/2013	04/08/2013	0083128	A2721402401	EXCHANGE INTAKE MANIFOLD
05171	550517	04/02/2013	04/08/2013	0083128	A2721412280	GASKET
05171	550517	04/02/2013	04/08/2013	0083128	A2721412380	GASKET
05171	550517	04/02/2013	04/08/2013	0083128	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	550517	04/02/2013	04/08/2013	0083128	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	550517	04/02/2013	04/08/2013	0083128	N000000000853	BULB
05171	550517	04/02/2013	04/08/2013	0083128	N000000002723	BULB
05171	550517	04/02/2013	04/08/2013	0083128	N007603014106	SEAL RING,VLRUB
05171	550517	04/02/2013	04/08/2013	0083128	NA	
05171	550517	04/02/2013	04/08/2013	0083128	NA	
05171	545232	01/10/2013	01/10/2013	0081018	055	SET TIRE PRESSURES TO FACTORY SPECIFICATIONS;RIGHT FRONT ____ LEFT FRONT ____ RIGHT REAR ____ LEFT REAR
05171	545232	01/10/2013	01/10/2013	0081018	057	ELECTRICAL OPERATIONS 6 CYL
05171	545232	01/10/2013	01/10/2013	0081018	A0001502780	IGNITION COIL
05171	545232	01/10/2013	01/10/2013	0081018	A0009985690	EXPANSION PLUG
05171	545232	01/10/2013	01/10/2013	0081018	A0009986590	CLOSING COVER
05171	545232	01/10/2013	01/10/2013	0081018	A0019931896	V-BELT
05171	545232	01/10/2013	01/10/2013	0081018	A2722000270	BELT TIGHTENER
05171	542461	11/26/2012	11/26/2012	0079730	010	SUSPENSION OPERATIONS 6 CYL
05171	542461	11/26/2012	11/26/2012	0079730	057	ELECTRICAL OPERATIONS 6 CYL
05171	542461	11/26/2012	11/26/2012	0079730	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____ RIGHT FRONT ____ LEFT REAR ____ RIGHT REAR
05171	542461	11/26/2012	11/26/2012	0079730	A0025422619	RELAY
05171	542461	11/26/2012	11/26/2012	0079730	A0025427619	RELAY
05171	542461	11/26/2012	11/26/2012	0079730	A2113280058	SEAL HOLDER
05171	542461	11/26/2012	11/26/2012	0079730	A2513200425	AIR SPRING
05171	542461	11/26/2012	11/26/2012	0079730	A2513202604	EXCHANGE COMPRESSOR
05171	536442	08/17/2012	08/17/2012	0076700	057	ELECTRICAL OPERATIONS 6 CYL
05171	536442	08/17/2012	08/17/2012	0076700	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____ RIGHT FRONT ____ LEFT REAR ____ RIGHT REAR
05171	536442	08/17/2012	08/17/2012	0076700	A0001502780	IGNITION COIL
05171	529727	05/23/2012	05/23/2012	0073004	012	BRAKE OPERATIONS 6 CYL
05171	529727	05/23/2012	05/23/2012	0073004	018	COOLANT SYSTEM SERVICE:REMOVE OLD COOLANT & REPLACE WITH NEW COOLANT FORTIFIED WITH WATERPUMP LUBE, CORROSION CONTROL AND SYSTEM SEALER
05171	529727	05/23/2012	05/23/2012	0073004	026	PERFORM FLEX "B" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes>BenzMaintenance System (USA)
05171	529727	05/23/2012	05/23/2012	0073004	055	ALL TIRE OPERATIONS
05171	529727	05/23/2012	05/23/2012	0073004	057	ELECTRICAL OPERATIONS 6 CYL


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGCB65E56A005207**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05171	529727	05/23/2012	05/23/2012	0073004	061	STEERING OPERATIONS 6 CYL
05171	529727	05/23/2012	05/23/2012	0073004	083	PERFORM BRAKE FLUID EXCHANGE
05171	529727	05/23/2012	05/23/2012	0073004	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05171	529727	05/23/2012	05/23/2012	0073004	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	529727	05/23/2012	05/23/2012	0073004	A0001802609	TS FILTER INSERT
05171	529727	05/23/2012	05/23/2012	0073004	A0004602583	OIL TANK
05171	529727	05/23/2012	05/23/2012	0073004	A0004661880	GASKET
05171	529727	05/23/2012	05/23/2012	0073004	A0009890807 01	BRAKE FLUID
05171	529727	05/23/2012	05/23/2012	0073004	A0019868071 17	WINDSHIELD WASHER FLUID
05171	529727	05/23/2012	05/23/2012	0073004	A0019899451	BRAKE PASTE
05171	529727	05/23/2012	05/23/2012	0073004	A0019899451	BRAKE PASTE
05171	529727	05/23/2012	05/23/2012	0073004	A0019976990	HOSE CLAMP
05171	529727	05/23/2012	05/23/2012	0073004	A0044205220	SET OF BRAKEPADS
05171	529727	05/23/2012	05/23/2012	0073004	A1644200820	PARTS KIT BRAKE PAD
05171	529727	05/23/2012	05/23/2012	0073004	A1644211312	BRAKE DISK, VENTED
05171	529727	05/23/2012	05/23/2012	0073004	A1644231212	BRAKE DISC, UNVENTED
05171	529727	05/23/2012	05/23/2012	0073004	A1645401017	SENSOR
05171	529727	05/23/2012	05/23/2012	0073004	A1645401017	SENSOR
05171	529727	05/23/2012	05/23/2012	0073004	A1648300218 64	COMBINATION FILTER
05171	529727	05/23/2012	05/23/2012	0073004	A2730940404	TS AIR FILTER ELEMENT
05171	529727	05/23/2012	05/23/2012	0073004	BQ1030002	ANTIFREEZE Glysantin G4
05171	529727	05/23/2012	05/23/2012	0073004	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	529727	05/23/2012	05/23/2012	0073004	BQ1460001	POWER STEERING FLUID
05171	529727	05/23/2012	05/23/2012	0073004	N000000001081	SCREW
05171	529727	05/23/2012	05/23/2012	0073004	N000000004039	BATTERY
05171	529727	05/23/2012	05/23/2012	0073004	N007603014106	SEAL RING, VLRUB
05171	529727	05/23/2012	05/23/2012	0073004	N910106014012	SCREW
05171	529727	05/23/2012	05/23/2012	0073004	NA	
05171	529727	05/23/2012	05/23/2012	0073004	NA	
05171	529727	04/16/2012	04/16/2012	0073004	012	BRAKE OPERATIONS 6 CYL
05171	529727	04/16/2012	04/16/2012	0073004	018	COOLANT SYSTEM SERVICE: REMOVE OLD COOLANT & REPLACE WITH NEW COOLANT FORTIFIED WITH WATERPUMP LUBE, CORROSION CONTROL AND SYSTEM SEALER
05171	529727	04/16/2012	04/16/2012	0073004	026	PERFORM FLEX "B" SERVICE AS INDICATED BY SERVICE SHEET for Mercedes-Benz Maintenance System (USA)
05171	529727	04/16/2012	04/16/2012	0073004	055	ALL TIRE OPERATIONS
05171	529727	04/16/2012	04/16/2012	0073004	057	ELECTRICAL OPERATIONS 6 CYL
05171	529727	04/16/2012	04/16/2012	0073004	061	STEERING OPERATIONS 6 CYL
05171	529727	04/16/2012	04/16/2012	0073004	083	PERFORM BRAKE FLUID EXCHANGE
05171	529727	04/16/2012	04/16/2012	0073004	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05171	529727	04/16/2012	04/16/2012	0073004	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	529727	04/16/2012	04/16/2012	0073004	A0001802609	TS FILTER INSERT
05171	529727	04/16/2012	04/16/2012	0073004	A0004602583	OIL TANK
05171	529727	04/16/2012	04/16/2012	0073004	A0004661880	GASKET
05171	529727	04/16/2012	04/16/2012	0073004	A0009890807 01	BRAKE FLUID
05171	529727	04/16/2012	04/16/2012	0073004	A0019868071 17	WINDSHIELD WASHER FLUID
05171	529727	04/16/2012	04/16/2012	0073004	A0019899451	BRAKE PASTE
05171	529727	04/16/2012	04/16/2012	0073004	A0019899451	BRAKE PASTE
05171	529727	04/16/2012	04/16/2012	0073004	A0019976990	HOSE CLAMP
05171	529727	04/16/2012	04/16/2012	0073004	A0044205220	SET OF BRAKEPADS
05171	529727	04/16/2012	04/16/2012	0073004	A1644200820	PARTS KIT BRAKE PAD
05171	529727	04/16/2012	04/16/2012	0073004	A1644211312	BRAKE DISK, VENTED
05171	529727	04/16/2012	04/16/2012	0073004	A1644231212	BRAKE DISC, UNVENTED
05171	529727	04/16/2012	04/16/2012	0073004	A1645401017	SENSOR
05171	529727	04/16/2012	04/16/2012	0073004	A1645401017	SENSOR
05171	529727	04/16/2012	04/16/2012	0073004	A1648300218 64	COMBINATION FILTER
05171	529727	04/16/2012	04/16/2012	0073004	A2730940404	TS AIR FILTER ELEMENT
05171	529727	04/16/2012	04/16/2012	0073004	BQ1030002	ANTIFREEZE Glysantin G4
05171	529727	04/16/2012	04/16/2012	0073004	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	529727	04/16/2012	04/16/2012	0073004	BQ1460001	POWER STEERING FLUID
05171	529727	04/16/2012	04/16/2012	0073004	N000000001081	SCREW
05171	529727	04/16/2012	04/16/2012	0073004	N000000004039	BATTERY



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05171	529727	04/16/2012	04/16/2012	0073004	N007603014106	SEAL RING,VLRUB
05171	529727	04/16/2012	04/16/2012	0073004	N910106014012	SCREW
05171	529727	04/16/2012	04/16/2012	0073004	NA	
05171	529727	04/16/2012	04/16/2012	0073004	NA	
05171	522561	12/12/2011	12/12/2011	0069019	010	SUSPENSION OPERATIONS 6 CYL
05171	522561	12/12/2011	12/12/2011	0069019	055	ALL TIRE OPERATIONS
05171	522561	12/12/2011	12/12/2011	0069019	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05171	517010	08/31/2011	08/31/2011	0066594	009	PRE ALIGNMENT INSPECTION: INSPECT THE VEHICLE FOR ALIGNMENT, CHECK TO SEE IF THE ALIGNMENT IS SET TO FACTORY SPECS.
05171	517010	08/31/2011	08/31/2011	0066594	010	SUSPENSION OPERATIONS 6 CYL
05171	517010	08/31/2011	08/31/2011	0066594	055	ALL TIRE OPERATIONS
05171	517010	08/31/2011	08/31/2011	0066594	073	
05171	517010	08/31/2011	08/31/2011	0066594	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05171	510048	04/12/2011	04/12/2011	0062474	007	MOUNT AND BALANCE 4 TIRES
05171	510048	04/12/2011	04/12/2011	0062474	009	ALIGN PERFORM 4 WHEEL ALIGNMENT
05171	510048	04/12/2011	04/12/2011	0062474	026	
05171	510048	04/12/2011	04/12/2011	0062474	055	ALL TIRE OPERATIONS
05171	510048	04/12/2011	04/12/2011	0062474	057	ELECTRICL OPERATIONS 6 CYL
05171	510048	04/12/2011	04/12/2011	0062474	073	
05171	510048	04/12/2011	04/12/2011	0062474	097	PERFORM COMPLIMENTARY 28 POINT INSPECTION AND SET TIRE PRESSURES TO FACTORY SPECIFICATIONS:LEFT FRONT ____RIGHT FRONT ____LEFT REAR ____RIGHT REAR
05171	510048	04/12/2011	04/12/2011	0062474	098	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	510048	04/12/2011	04/12/2011	0062474	A0001802609	TS FILTER INSERT
05171	510048	04/12/2011	04/12/2011	0062474	A0019868071 17	WINDSHIELD WASHER FLUID
05171	510048	04/12/2011	04/12/2011	0062474	A1648300218 64	COMBINATION FILTER
05171	510048	04/12/2011	04/12/2011	0062474	A2204000170	LOCK SREW
05171	510048	04/12/2011	04/12/2011	0062474	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	510048	04/12/2011	04/12/2011	0062474	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	510048	04/12/2011	04/12/2011	0062474	N007603014106	SEAL RING,VLRUB
05171	510048	04/12/2011	04/12/2011	0062474	NA	
05171	510048	04/12/2011	04/12/2011	0062474	NA	
05171	505445	01/19/2011	01/19/2011	0059795	057	N/A
05171	505445	01/19/2011	01/19/2011	0059795	097	N/A
05171	505445	01/19/2011	01/19/2011	0059795	098	N/A
05171	505445	01/19/2011	01/19/2011	0059795		
05171	505445	01/19/2011	01/19/2011	0059795	A0041594903	SPARK PLUG
05171	505445	01/19/2011	01/19/2011	0059795	A0045418601	BATTERY
05171	505445	01/19/2011	01/19/2011	0059795	BQ6460264	Alpine NTG2 Version 8
05171	505445	01/19/2011	01/19/2011	0059795	N000000004205	FUSE LINK
05171	491769	04/26/2010	04/26/2010	0052134	012	N/A
05171	491769	04/26/2010	04/26/2010	0052134	026	N/A
05171	491769	04/26/2010	04/26/2010	0052134	039	N/A
05171	491769	04/26/2010	04/26/2010	0052134	057	N/A
05171	491769	04/26/2010	04/26/2010	0052134	060	N/A
05171	491769	04/26/2010	04/26/2010	0052134	083	N/A
05171	491769	04/26/2010	04/26/2010	0052134	098	N/A
05171	491769	04/26/2010	04/26/2010	0052134	12	BRAKE OPERATIONS 6 CYL
05171	491769	04/26/2010	04/26/2010	0052134	26	
05171	491769	04/26/2010	04/26/2010	0052134	39	PERFORM 28 POINT INSPECTION
05171	491769	04/26/2010	04/26/2010	0052134	57	ELECTRICL OPERATIONS 6 CYL
05171	491769	04/26/2010	04/26/2010	0052134	60	MOC SYN PWR STEERING FLUID EXCHANGE:REMOVE OLD FLUID & INSTALL SYNTHETICFLUID FORTIFIED WITH SPECIAL ANTIOXIDANT & ANTI WEAR INGREDIENTS
05171	491769	04/26/2010	04/26/2010	0052134	83	PERFORM BRAKE FLUID EXCHANGE
05171	491769	04/26/2010	04/26/2010	0052134	98	DISPOSABLE FEE FOR OIL,COOLANT, FILTER, TIRES.
05171	491769	04/26/2010	04/26/2010	0052134	A0001802609	TS FILTER INSERT
05171	491769	04/26/2010	04/26/2010	0052134	A0009890807 01	BRAKE FLUID
05171	491769	04/26/2010	04/26/2010	0052134	A0019868071 17	WINDSHIELD WASHER FLUID
05171	491769	04/26/2010	04/26/2010	0052134	A0044205220	SET OF BRAKEPADS
05171	491769	04/26/2010	04/26/2010	0052134	A1120940604	TS FILTER INSERT



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05171	491769	04/26/2010	04/26/2010	0052134	A1644200820 28	BRAKE SHOE
05171	491769	04/26/2010	04/26/2010	0052134	A1644231212	BRAKE DISC, UNVENTED
05171	491769	04/26/2010	04/26/2010	0052134	A1645401017	SENSOR
05171	491769	04/26/2010	04/26/2010	0052134	A1645401017	SENSOR
05171	491769	04/26/2010	04/26/2010	0052134	A1648300218 64	COMBINATION FILTER
05171	491769	04/26/2010	04/26/2010	0052134	B01061	
05171	491769	04/26/2010	04/26/2010	0052134	B01901	
05171	491769	04/26/2010	04/26/2010	0052134	B02161	
05171	491769	04/26/2010	04/26/2010	0052134	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	491769	04/26/2010	04/26/2010	0052134	BQ1460001	POWER STEERING FLUID
05171	491769	04/26/2010	04/26/2010	0052134	N000000001081	SCREW
05171	491769	04/26/2010	04/26/2010	0052134	N007603014106	SEAL RING,VLRUB
05171	491769	04/26/2010	04/26/2010	0052134	NA	
05171	491769	04/26/2010	04/26/2010	0052134	NA	
05171	491769	04/26/2010	04/26/2010	0052134	NA	
05171	491769	04/26/2010	04/26/2010	0052134	NA	
05171	465320	02/25/2010	02/25/2010	0037996	007	N/A
05171	465320	02/25/2010	02/25/2010	0037996	009	N/A
05171	465320	02/25/2010	02/25/2010	0037996	012	N/A
05171	465320	02/25/2010	02/25/2010	0037996	019	N/A
05171	465320	02/25/2010	02/25/2010	0037996	019	N/A
05171	465320	02/25/2010	02/25/2010	0037996	025	N/A
05171	465320	02/25/2010	02/25/2010	0037996	055	N/A
05171	465320	02/25/2010	02/25/2010	0037996	073	N/A
05171	465320	02/25/2010	02/25/2010	0037996	098	N/A
05171	465320	02/25/2010	02/25/2010	0037996	098	N/A
05171	465320	02/25/2010	02/25/2010	0037996	A0001802609	TS FILTER INSERT
05171	465320	02/25/2010	02/25/2010	0037996	A0019868071 17	WINDSHIELD WASHER FLUID
05171	465320	02/25/2010	02/25/2010	0037996	A0019896803 10	TRANSMISSION OIL
05171	465320	02/25/2010	02/25/2010	0037996	A0049903512	SCREW
05171	465320	02/25/2010	02/25/2010	0037996	A1644200820 28	BRAKE SHOE
05171	465320	02/25/2010	02/25/2010	0037996	A1644210412	BRAKE DISC
05171	465320	02/25/2010	02/25/2010	0037996	A1698200445	WIPER BLADE
05171	465320	02/25/2010	02/25/2010	0037996	A2202710380	GASKET
05171	465320	02/25/2010	02/25/2010	0037996	A2205401517	BRAKE WEAR SENSOR
05171	465320	02/25/2010	02/25/2010	0037996	A2212770195	OIL FILTER
05171	465320	02/25/2010	02/25/2010	0037996	A2512710097	PIPE
05171	465320	02/25/2010	02/25/2010	0037996	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	465320	02/25/2010	02/25/2010	0037996	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	465320	02/25/2010	02/25/2010	0037996	N007603012102	RING,GENERAL,METAL
05171	465320	02/25/2010	02/25/2010	0037996	N007603014106	SEAL RING,VLRUB
05171	465320	02/25/2010	02/25/2010	0037996	NA	
05171	465320	02/25/2010	02/25/2010	0037996	NA	
05171	483715	02/25/2010	02/25/2010	0046069	039	N/A
05171	483715	11/27/2009	11/27/2009	0046068	39	PERFORM 28 POINT INSPECTION
05171	474453	06/19/2009	06/19/2009	0041844	065	N/A
05171	474453	06/19/2009	06/19/2009	0041844	65	ENGINE OPERATIONS 6 CYL
05171	474453	06/19/2009	06/19/2009	0041844	A2515000049	COMPENSATING TANK
05171	465320	01/30/2009	01/30/2009	0037997	07	MOUNT AND BALANCE 2 TIRES
05171	465320	01/30/2009	01/30/2009	0037997	09	ALIGN PERFORM 4 WHEEL ALIGNMENT
05171	465320	01/30/2009	01/30/2009	0037997	12	BRAKE OPERATIONS 6 CYL
05171	465320	01/30/2009	01/30/2009	0037997	19	AUTO TRANS OPERATIONS 6 CYL
05171	465320	01/30/2009	01/30/2009	0037997	19	TRAN1 - SERVICE AUTOMATIC TRANSMISSION, REPALACE FLUID, FILTER & GASKET
05171	465320	01/30/2009	01/30/2009	0037997	25	
05171	465320	01/30/2009	01/30/2009	0037997	55	ALL TIRE OPERATIONS
05171	465320	01/30/2009	01/30/2009	0037997	73	
05171	465320	01/30/2009	01/30/2009	0037997	98	BODY OPERATIONS 6 CYL
05171	465320	01/30/2009	01/30/2009	0037997	98	DISPOSABLE FEE FOR OIL, FILTER, BATTERY , TIRES.
05171	465320	01/30/2009	01/30/2009	0037997	A0001802609	TS FILTER INSERT
05171	465320	01/30/2009	01/30/2009	0037997	A0019868071 17	WINDSHIELD WASHER FLUID
05171	465320	01/30/2009	01/30/2009	0037997	A0019896803 10	TRANSMISSION OIL
05171	465320	01/30/2009	01/30/2009	0037997	A0049903512	SCREW
05171	465320	01/30/2009	01/30/2009	0037997	A1644200820 28	BRAKE SHOE
05171	465320	01/30/2009	01/30/2009	0037997	A1644210412	BRAKE DISC
05171	465320	01/30/2009	01/30/2009	0037997	A1698200445	WIPER BLADE
05171	465320	01/30/2009	01/30/2009	0037997	A2202710380	GASKET
05171	465320	01/30/2009	01/30/2009	0037997	A2205401517	BRAKE WEAR SENSOR
05171	465320	01/30/2009	01/30/2009	0037997	A2212770195	OIL FILTER
05171	465320	01/30/2009	01/30/2009	0037997	A2512710097	PIPE




Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05171	465320	01/30/2009	01/30/2009	0037997	A9244015394	
05171	465320	01/30/2009	01/30/2009	0037997	B01901	
05171	465320	01/30/2009	01/30/2009	0037997	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	465320	01/30/2009	01/30/2009	0037997	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	465320	01/30/2009	01/30/2009	0037997	N007603012102	RING,GENERAL,METAL
05171	465320	01/30/2009	01/30/2009	0037997	N007603014106	SEAL RING,VLRUB
05171	465320	01/30/2009	01/30/2009	0037997	STEM	
05171	465320	01/30/2009	01/30/2009	0037997	TIRE	
05171	450324	07/10/2008	07/10/2008	0031971	07	MOUNT AND BALANCE 1 TIRE
05171	450324	07/10/2008	07/10/2008	0031971	98	DISPOSABLE FEE FOR OIL, FILTER, BATTERY , TIRES.
05171	450324	07/10/2008	07/10/2008	0031971	A9244015394	
05171	450324	07/10/2008	07/10/2008	0031971	BQ8400360	TIRE CON 255/55R18 SKU 15
05171	450324	07/10/2008	07/10/2008	0031971	STEM	
05171	450324	07/10/2008	07/10/2008	0031971	TIRE	
05171	438296	02/07/2008	02/07/2008	0024557	09	ALIGN PERFORM 4 WHEEL ALIGNMENT
05171	438296	02/07/2008	02/07/2008	0024557	12	BRAKE OPERATIONS 6 CYL
05171	438296	02/07/2008	02/07/2008	0024557	26	
05171	438296	02/07/2008	02/07/2008	0024557	50	CABIN AIR FILTER:REPLACE A/C CABIN AIR FILTER
05171	438296	02/07/2008	02/07/2008	0024557	57	ELECTRICL OPERATIONS 6 CYL
05171	438296	02/07/2008	02/07/2008	0024557	98	DISPOSABLE FEE FOR OIL, FILTER, BATTERY , TIRES.
05171	438296	02/07/2008	02/07/2008	0024557	98	BODY OPERATIONS 6 CYL
05171	438296	02/07/2008	02/07/2008	0024557	A0009862350 5349	PAINT PIN
05171	438296	02/07/2008	02/07/2008	0024557	A0019868071 14	WINDSHIELD WASHER FLUID
05171	438296	02/07/2008	02/07/2008	0024557	A0044205220	SET OF BRAKEPADS
05171	438296	02/07/2008	02/07/2008	0024557	A1648300218 64	COMBINATION FILTER
05171	438296	02/07/2008	02/07/2008	0024557	A2205401517	BRAKE WEAR SENSOR
05171	438296	02/07/2008	02/07/2008	0024557	B01901	
05171	438296	02/07/2008	02/07/2008	0024557	B06011	
05171	438296	02/07/2008	02/07/2008	0024557	BQ1090144	Mobil 1 Formula M 5w40 Bu
05171	438296	02/07/2008	02/07/2008	0024557	N007603014106	SEAL RING,VLRUB
05171	438296	02/07/2008	02/07/2008	0024557	STEM	
05171	438296	02/07/2008	02/07/2008	0024557	TIRE	

EXHIBIT 12

Vehicle History Detail

RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGCB22E58A073958									
					MY 2008		R Class		Series 251
I151660	12/3/2007	42870689	14123	21852ZZ	DEALER PRE-DELIVERY (PDI)---Special cost settlement	21	MBUSA SPECIAL DAMAGE CODES	1	PRE DELIVERY INSPECTION PRE DELIVERY INSPECTION PRE DELIVERY INSPECTION
105151	6/4/2008	43987457	14123	2132700	UNDEFINED---	21	MBUSA SPECIAL DAMAGE CODES	2,480	FIRST SERVICE VISIT- PERFORM; ; 2480 W PERFORMED 1ST 1000-3000 MILE VISIT.;
125777	7/15/2009	46261082	14123	5495141	"Campaign 2008 110009, Update rear SAM software---	54	Electrical System, Equipment And Instruments	13,060	PERFORM CAMPAIGN # 2008110009; RECALL 2008110009, REAR SAM SOFTWARE UPDATE REQUIRED; 13060 CAMPAIGN 2008110009 PERFORM CAMPAIGN # 2008110009, FLASHED REAR SAM;
126107	7/23/2009	46299914	14123	47006P4	Fill level sensor, fuel tank--- Towing	47	Fuel System	13,260	TOWING ON RO 125777. LUCYS TRANSPORT INV 5202
		46299914	14123	4700673	Fill level sensor, fuel tank--- Electrical fault	47	Fuel System	13,260	CUST STATES ENGINE WOULD CRANK BUT NOT START-CHECK HISTORY; FUEL LEVEL SENSORS(BOTH)LEFT AND RIGHT,ELECT-FAULT; 13260 CRANK NO START*AT TIMES PERFORMED SHORT TEST NO CODES FOUND, PERFORMED FUEL PRESSURE TEST-OK, PERFORMED CURRENT DRAW TEST-9.5AMPS, PERFORMED ROAD*TEST AND LET CAR SIT, WHEN ABLE TO DUPLICATE;
236113	9/25/2014	56726983	14123	1437053	Diesel particulate filter--- Insufficient effect/power	14	Exhaust Manifold, Engine Brake, Emission Control System	50,346	PON INSPECTION FOUND CHECK ENGINE LIGHT ONFOR CODE#2626-001 DIESEL PARTICULATE FILTER; ; 50333 ENG LIGHT ON W DC-14370F77, AUT-336 4286 WAR 8-80 AFTER REPLACE TURBO, PERFORM ROAD TEST, WHEN DRIVING ENG LIGHT COMING ON PERFORM SHORT TEST, FOUND CODES, 2079-001, 2626-001 CHECK INSIDE PARTICULAR FILTER FOR SOOT, REPLACE PARTICULAR FILTER PERFORM ADAPTATION, PERFORM ROAD TEST, AFTER 5 MILE ENG *LOSS POWER AND ENG LIGHT ON COMING ON, FOUND CODES 2051-001, 2047-001 (THE RAIL PRESSURE IS TOO LOW)
		56736224	14123	5458152	Control unit, diesel engine--- Does not operate correctly	54	Electrical System, Equipment And Instruments	50,346	CUST STATES CHECK ENGINE LIGHT IS ON; R A; 50308 ENG LIGHT ON W DC 54581527, AUT 3344434, SHORT TEST PERFORM, FOUND MANY CODES, 207 8-001, 2079-001, 2051-001, 2047-001.2979-004. 2526-002, 2526-004, 2154-002, CHECK ME FOR POWER AND FOUND CONNECTOR AND CDI4 WITH OI L, CLEAN CONNECTOR REPLACE CDI4 AS PER GK, PERFORM CDI PROGRAM, PERFORM INJECTOR PROGRAM AND RESEAT PARTICULAR FILTER ADAPTATION, *PERFORM ROAD TEST, CHECK FOR CODES, HAS CODES AGAIN
136824	7/18/2022	70778612	17148	4290005	UNDEFINED---	42	Brakes	151,614	RECALL # 2022050015 INSPECT BRAKE BOOSTER WITHOUT PEDAL REWORK; SLEEVE PASSED/PIC RECEIVED; 151614 INSPECTED BRAKE BOOSTER TECH 6906 INSPECTED

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGCB22E58A073958					MY 2008	R Class		Series 251	R 320 CDI 4MATIC
									WATER DRAIN AND FOUND OK. REMOVED THE BRAKE BOOSTER RUBBER SLEEVE. TOOK A PHOTO OF THE RUBBER SLEEVE WITH THE VIN LABEL O F THE B-PILLAR. CHECKED CORROSION OF BRAKE BOOSTER USING THE REMOVED RUBBER SLEEVE AND FOUND OK. NO FURTHER ACTIONS WERE REQUIRED

EXHIBIT 13

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB22E58A073958**

VIN: 4JGCB22E58A073958 **Owner:** NONE **Engine No:** 64295040557512
FIN: 4JG2511221A073958 **Transmission No:** 72290201490942

Vehicle Info

Model/Year: R 320 CDI 4MATIC 2008 **Upholstery:** 144 **Paint:** 723

Warranty & Sale

Warranty Start: 12/21/2007 **Retail Date:** 12/21/2007 **Selling Dealer:** 14123

Production Info

Radio Code: 34342 **Serial No:** 71103501 **Prod Date:** 11/30/2007

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
CA	CAC CASE EXISTS

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2008110009	0807P54A67	11/21/2008	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	12/29/2007	07/01/2008	0000000	0999999	G3	022779473831

Option Codes

Option	Description	Option	Description
-FL	Wholesale state FL	A05	
A21		A22	
A38		A44	
A49		FV	SEDAN ELONGATED
GA	AUTOMATIC TRANSMISSION	H04	Wood finish, fineline bird's e
J52		K15	
L	L.H.D	M30	DISPLACEMENT 3.0 LITRE
R02	All season tyres	R10	18" 5-twin-spoke "Star" design
U10	Front passenger seat with weig	U12	Velour floor mats
U41	Fuel/water separator and lubri	V36	
140	Packet 1	144	Packet 5
220	PARKTRONIC system (PTS)	232	Garage door opener
245	Compass	280	Leather-covered steering wheel
293	Sidebag in rear left and right	301	Ashtray package
359	Teleaid Low Cost	389	Preinst. for mobile (UHI) for
396	LINGUATRONIC American	414	Electric sunroof, glass versio
427	7-speed automatic transmission	438	Neck-Pro head restraints, 1st
461	Instrument with mileage readin	470	Tyre press monitoring system,
474	Diesel Particulate filter	488	Chassis with steel/air suspens
494	US version	519	Rear audio system
524	Paint protection - preservatio	528	COMAND
536	Sirius satellite radio	551	Anti-theft warning system
560	Electrically adjustable front	580	Automatic air conditioning
636	Omission of warning triangle	666	Prod. prot. f. freight pkging
669	Collapsible spare wheel (inste	673	High-capacity battery
7XX		705	
723	EASY-PACK load compartment cov	763	Radio remote control with pani
772	AMG bodystyling	808	Technical modifications
810	Harman Kardonb Logic 7b Surrou	819	CD changer, MP3-capable, for 6
840	Dark-tinted rear windscr./rear	847	THIRD ROW OF SEATS


EXHIBIT 14

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF71E28A370362									
					MY 2008		GL Class		Series 164
628868	5/17/2011	49546883	51121	3230104	Front shock absorber---Leaks	32	Suspension	42,158	CUST REQUEST- CHECK FRONT SUSPENSION DOWN (TOWED IN); VERIFIED RIGHT FRONT AIRMATIC STRUT BAG BLOWN DC:32301047; CONNECT SDS, PERFOR M*INITIAL QUICK TEST, FOUND CODE IN AIRMATI C 5507 SUSPENSION STRUT IS IMPLAUSIBLE, RAISE VEHICLE, VISUAL INSPECTION CONFIRMS RIGHT FR ONT AIRMATIC STRUT BAG BLOWN, REMOVE RIGHT FRONT WH;
SE48556	6/18/2012	51811063	22131	2161600	Allstate Tow_ New RAP Program (MB HOME OFFICE USE ONLY)---Special regulation	21	MBUSA SPECIAL DAMAGE CODES	52,316	;*
58130	2/11/2013	52934810	51121	2140200	SIGN AND DRIVE, "JUMPSTART"---Special regulation	21	MBUSA SPECIAL DAMAGE CODES	72,695	1192601438; JUMP STARTED BATTERY;
75173	6/25/2013	53748469	51121	5990002	"Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid---	59	Electrical harness connectors	78,358	CAMPAIGN #2012070002; UPDATE; 78358 PERFORMED CAMPAIGN;
94029	11/18/2013	54617613	51121	2140200	SIGN AND DRIVE, "JUMPSTART"---Special regulation	21	MBUSA SPECIAL DAMAGE CODES	86,801	CUSTOMER REQUESTED MERCEDES BENZ ROADSIDE ASSISTANCE. JUMPSTART
1245031	9/14/2022	71072193	56113	4290005	UNDEFINED---	42	Brakes	163,592	CUSTOMER STATES PERFORM OPEN CAMPAIGN 2022050015 - 22P4290005; F;163592 CUSTOMER REQUESTED CAMPAIGN NUMBER 2022050015 BE PERFORMED. PERFORMED A VEHICLE MASTER INQUIRY TO FIND AND VERIFY AN OPEN CAMPAIGN. THE FUNCTION OF THE BRAKE BOOSTER MIGHT THE DRAINS THEN REMOVED THE RUBBER SLEEVE AROUND THE BRAKE BOOSTER AND TOOK PHOTOS OF THE SLEEVE AND VIN LABEL ON THE B PILLAR TO ATTACH TO THE WARRANTY CLAIM IN EVA. WITH THE SLEEVE REMOVED INSPECTED THE CORROSION ON THE BRAKE BOOSTER SLEEVE WHICH CORROSION WAS PRESENT CORROSION MEASURED TO BE 0.05 mm AND 0.01 mm TEST (A) PASSED. THE SYSTEM IS OPERATING AS DESIGNED.// due to a shooting 1 block away i left in a hurry i had the customer text me the picture of her vin plate and i took a picture of the rubber sleeve showing the little bit of rust

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF71E28A370362					MY 2008	GL Class		Series 164	GL450
1245031	9/14/2022	71072193	56113	9980301	Technical retrofit as of B2009---Follow-up operations	99	Printed Matter	163,592	MOBILE SERVICE VAN USED FOR BRAKE BOOSTER STOP DRIVE;F

EXHIBIT 15

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBF71E28A370362**

VIN: 4JGBF71E28A370362 **Owner:** NONE **Engine No:** 27392330214492
FIN: 4JG1648711A370362 **Transmission No:** 72290401541715

Vehicle Info

Model/Year: GL450 2008 **Upholstery:** 104 **Paint:** 650

Warranty & Sale

Warranty Start: 02/13/2008 **Retail Date:** 02/13/2008 **Selling Dealer:** 55138

Production Info

Radio Code: 15545 **Serial No:** 71238821 **Prod Date:** 01/04/2008

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2008110009	0807P54A67	11/21/2008	CLOSED	SERVICE
2009070002	0905P54B12	08/17/2009	CLOSED	SERVICE
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages


Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	02/14/2008	12/31/2999	0000000	0999999	G3	023647364220

Option Codes

Option	Description	Option	Description
-NY	Wholesale state NY	A05	
A21		A22	
A38		A44	
A49		FV	SEDAN ELONGATED
GA	AUTOMATIC TRANSMISSION	H04	Wood finish, fineline bird's e
J58		K14	
L	L.H.D	M46	CAPACITY 4,6 LITRE
R02	All season tyres	R31	Light-alloy wheel 5-hole styl
U10	Front passenger seat with weig	U12	Velour floor mats
U40	Retaining net for dividing lug	U71	DVD-PLAYER WITH REGIONAL-CODE
V41		100	CONTROL CODE NULLSERIES VEHICL
104	Cashmere beige ARTICO man-made	218	Reversing camera
220	PARKTRONIC system (PTS)	231	
232	Garage door opener	242	Front seat right, electr.adjust
249	Automatically dimming ext. and	275	Memory package el.adjust.drive
280	Leather steering wheel	293	Sidebag in rear left and right
301	Ashtray package	345	Windscreen wiper with rain sen
359	Teleaid Low Cost	389	Preinst. for mobile (UHI) for
414	Electric sunroof, glass versio	427	7-speed automatic transmission
438	Neck-Pro head restraints, 1st	441	Steering column electr. adjust
461	Instrument with mileage readin	470	Tyre press monitoring system,
489	Airmatic package	494	US version
500	Electrically folding exterior	519	Rear audio system
524	Paint protection - preservatio	530	COMAND APS USA
536	Sirius satellite radio	551	Anti-theft warning system
580	Automatic air conditioning	636	Omission of warning triangle
650	Calcite white	666	Prod. prot. f. freight pkgng
673	High-capacity battery	690	Emergency wheel (mini spare)
7XX		705	

EXHIBIT 16

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBB86E18A439567									
221536	8/5/2014				Module---		Body		
3204033	2/18/2019	103117548	80149	2161400	Allstate Towing_Cost Of Sale(MB HOME OFFICE USE ONLY)--Special regulation	21	MBUSA SPECIAL DAMAGE CODES	46,276	
193641	8/31/2020	104887616	78102	2168500	2020 Summer Savings Campaign---GENERIC	21	MBUSA SPECIAL DAMAGE CODES	173,465	MERCEDES BENZ \$150.00 DISCOUNT OFFER
221219	7/26/2022	70791602	78118	4290005	UNDEFINED---	42	Brakes	196,248	2022050015 -- INSPECT BRAKE BOOSTER WITHOUT PEDAL REWORK;RECALL;196248 DC:42 900 06 OP CODE:02-0036 ---0.2 HOURS--- OP CODE:02-0037 ---0.1 HOURS--- PERFORMED PER WORKSHOP INSTRUCTIONS, CHECKED OK.

EXHIBIT 17

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBB86E18A439567**

VIN: 4JGBB86E18A439567 **Owner:** NONE **Engine No:** 27296730975648
FIN: 4JG1641861A439567 **Transmission No:** 72290601817498

Vehicle Info

Model/Year: ML350 2008 **Upholstery:** 141-Black MB-Tex **Paint:** 040-Black

Warranty & Sale

Warranty Start: 07/11/2008 **Retail Date:** 07/11/2008 **Selling Dealer:** 05759

Production Info

Radio Code: 12113 **Serial No:** 80622812 **Prod Date:** 06/17/2008

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
S3	SIRIUS AUDIO SERVICE WAS AUTO ACTIVATED BY SIRIUS, CALL 888-465-8528 TO GET A REHIT AND ENSURE CUSTO
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2009020004	0810P82B24	02/20/2009	CLOSED	SERVICE
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	09/15/2008	01/15/2009	0000000	0999999	G3	026257089600

Option Codes

Option	Description	Option	Description
-CA	Wholesale state CA	A05	
A21		A39	
A44		FW	SEDAN
GA	AUTOMATIC TRANSMISSION	H04	Wood finish, fineline bird's e
J58		K14	Factory Code
L	L.H.D	M35	CAPACITY 3,5 LITRE
P96	Sports Package - exterior	R02	All season tyres
R39	5 spoke light-alloy wheel 48.3	U10	Front passenger seat with weig
U12	Velour floor mats	V59	Speed and Load Index
040	Black	140	Packet 1
141	Packet 2	182	CONVERTER WITH DEV. CHARACTERI
218	Reversing camera	232	Garage door opener
280	Leather steering wheel	293	Sidebag in rear left and right
301	Ashtray package	345	Windscreen wiper with rain sen
359	Teleaid Low Cost	389	Preinst. for mobile (UHI) for
414	Electric sunroof, glass versio	427	7-speed automatic transmission
438	Neck-Pro head restraints, 1st	461	Instrument with mileage readin
470	Tyre press monitoring system,	494	US version
519	Rear audio system	524	Paint protection - preservatio
530	COMAND APS USA	536	Sirius satellite radio
551	Anti-theft warning system	560	Electrically adjustable front
580	Automatic air conditioning	636	Omission of warning triangle
666	Prod. prot. f. freight pkging	673	High-capacity battery
690	Emergency wheel (mini spare)	691	Blue tint.g1.allr./single-l.sa
7XX		705	
720	Roof rails/pre-installation fo	723	EASY-PACK load compartment cov
763	Radio remote control with pani	808	Technical modifications
810	Harman Kardonb Logic 7b Surrou	840	Dark-tinted rear windscr./rear

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBB86E18A439567**

Option	Description	Option	Description
890	EASY-PACK-tailgate	989	Identification label under win

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 42900 05 8		78118	221219	A	070791602	07/26/2022	07/26/2022	000196248	02-KDM (Campaign)	0001
1 21685 00	2020 Summer Savings Campaign	78102	193641	A	104887616	08/31/2020	08/31/2020		RAPS	0001
1 21614 00 0	Cost of sale	80149	3204033	1	103117548	02/18/2019	02/18/2019		RAPS	0001
0 82900 39 7	"Campaign 2009 020004, Replace	05737	221536	G	056162114	08/05/2014		000046275	02-KDM (Campaign)	0001
0 14002 07 7	Upper section, intake manifold	05737	221536	A	056155273	08/05/2014		000046275	03-Warranty	0001
0 59900 02 7	"Campaign 2012070002, Retrofit	05737	221536	F	056147798	08/05/2014		000046275	02-KDM (Campaign)	0001
0 82282 73 7	Light source, taillight Electr	05737	142884	AA	049348999	04/01/2011		000019046	03-Warranty	0002
0 82380 74 7	Socket, light source, taillamp	05737	142884	A	049348999	04/01/2011		000019046	03-Warranty	0001
0 82380 74 7	Socket, light source, taillamp	05759	553242	A	047202537	01/16/2010		000010443	03-Warranty	0001
0 54157 74 7	Electrical fuse, general Conta	05759	553242	C	047202537	01/16/2010		000010443	03-Warranty	0002

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
78118	221219	07/26/2022	07/26/2022	0196248	075	Check for Open Recalls, Open Recall Identified, Customer Authorized work to be performed
78118	221219	07/26/2022	07/26/2022	0196248	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	193641	08/31/2020	08/31/2020	0173465	065	ENGINE SYSTEM REPAIR
78102	193641	08/31/2020	08/31/2020	0173465	075	Check for Open Recalls & no open recalls at this time
78102	193641	08/31/2020	08/31/2020	0173465	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	193641	08/31/2020	08/31/2020	0173465	098	MISC. SHOP CHARGES
78102	193641	08/31/2020	08/31/2020	0173465	A1649810406	ANGUL.CONTACT BALL BEAR.
78102	186110	02/10/2020	02/11/2020	0165399	001	
78102	186110	02/10/2020	02/11/2020	0165399	075	Check for Open Recalls & no open recalls at this time
78102	186110	02/10/2020	02/11/2020	0165399	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	186110	02/10/2020	02/11/2020	0165399	A0001802609 90	TS FILTER INSERT-STARPART
78102	186110	02/10/2020	02/11/2020	0165399	N007603014106	SEAL RING,VLRUB
78102	180156	09/10/2019	09/10/2019	0157818	001	
78102	180156	09/10/2019	09/10/2019	0157818	075	Check for Open Recalls & no open recalls at this time
78102	180156	09/10/2019	09/10/2019	0157818	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	180156	09/10/2019	09/10/2019	0157818	A0001802609 90	TS FILTER INSERT-STARPART
78102	180156	09/10/2019	09/10/2019	0157818	N007603014106	SEAL RING,VLRUB
78102	171454	01/29/2019	01/29/2019	0145372	057	ELECTRICAL AND ELECTRONICS
78102	171454	01/29/2019	01/29/2019	0145372	070	BODY AND TRIM
78102	171454	01/29/2019	01/29/2019	0145372	075	Check for Open Recalls & no open recalls at this time
78102	171454	01/29/2019	01/29/2019	0145372	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	171239	01/23/2019	01/23/2019	0000000	057	ELECTRICAL AND ELECTRONICS
78102	171239	01/23/2019	01/23/2019	0000000	075	Check for Open Recalls & no open recalls at this time
78102	171239	01/23/2019	01/23/2019	0000000	097	COMPLIMENTARY MULTI-POINT INSPECTION
78102	171239	01/23/2019	01/23/2019	0000000	A0007660900	KEY MECHANIC
78102	171239	01/23/2019	01/23/2019	0000000	A2049051104 9999	KEY 315MHZ PANIC-ALARM VA

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBB86E18A439567**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
78102	171239	01/23/2019	01/23/2019	0000000	N000000008156	BULB
78102	170386	12/29/2018	12/31/2018	0145198	0S1	PERFORM SALT LAKE COUNTY EMISSION TESTING
78102	170386	12/29/2018	12/31/2018	0145198	028	
78102	170386	12/29/2018	12/31/2018	0145198	039	PREMIUM USED CAR LANDCAR INSPECTION
78102	170386	12/29/2018	12/31/2018	0145198	039	UTAH STATE SAFETY INSPECTION
78102	170386	12/29/2018	12/31/2018	0145198	056	REPLACE 4 TIRES MOUNT AND BALANCE
78102	170386	12/29/2018	12/31/2018	0145198	057	ELECTRICAL AND ELECTRONICS
78102	170386	12/29/2018	12/31/2018	0145198	058	REPLACE LIGHT BULBS AS NEEDED
78102	170386	12/29/2018	12/31/2018	0145198	065	ENGINE SYSTEM REPAIR
78102	170386	12/29/2018	12/31/2018	0145198	072	PERFORM COMPLETE USED CAR DETAIL
78102	170386	12/29/2018	12/31/2018	0145198	088	ANTI-THEFT ACID ETCH WINDOWS
78102	170386	12/29/2018	12/31/2018	0145198	098	MISC. SHOP CHARGES
78102	170386	12/29/2018	12/31/2018	0145198	A0001802609	TS FILTER INSERT
78102	170386	12/29/2018	12/31/2018	0145198	A0009897902 19BIFU	MB 229.5 SAE 5W-40 Bulk
78102	170386	12/29/2018	12/31/2018	0145198	A0009985690	EXPANSION PLUG
78102	170386	12/29/2018	12/31/2018	0145198	A0009986590	CLOSING COVER
78102	170386	12/29/2018	12/31/2018	0145198	A1648260007	REPAIR KIT
78102	170386	12/29/2018	12/31/2018	0145198	A2720100631	HOUSING COVER W COUPLING
78102	170386	12/29/2018	12/31/2018	0145198	A2721800510	COMBINED FILTER - COOLER
78102	170386	12/29/2018	12/31/2018	0145198	A2722000415	COOLANT THERMOSTAT
78102	170386	12/29/2018	12/31/2018	0145198	BQ1030004	Anticorrosion/Antifreeze
78102	170386	12/29/2018	12/31/2018	0145198	BQ8401126	SKU, 290123507, 107H, GRA
78102	170386	12/29/2018	12/31/2018	0145198	N00000000814064	BULB
78102	170386	12/29/2018	12/31/2018	0145198	N000000008149	BULB
78102	170386	12/29/2018	12/31/2018	0145198	N000000008156	BULB
78102	170386	12/29/2018	12/31/2018	0145198	N007603014106	SEAL RING,VLRUB
78102	157876	01/05/2018	01/20/2018	0120436	057	ELECTRICAL AND ELECTRONICS
78102	157876	01/05/2018	01/20/2018	0120436	097	COMPLIMENTARY MULTI-POINT INSPECTION
05737	221536	08/05/2014	08/08/2014	0046275	020	COMPLIMENTARY CAR WASH-EXTERIOR HAND WASH, VACUUM INTERIOR, CLEAN WINDOWS
05737	221536	08/05/2014	08/08/2014	0046275	039	CHECK AND ADJUST TIRE PRESSURE AS NEEDED
05737	221536	08/05/2014	08/08/2014	0046275	097	PERFORM COMPLIMENTARY MULTI-POINT INSPECTION - COPY PROVIDED UPON REQUEST
05737	221536	08/05/2014	08/08/2014	0046275	098	We accept Visa, MasterCard, American Express, Discover, Debit Cards, and Cash. We DO NOT accept personal or business checks.
05737	142884	04/01/2011	04/01/2011	0019046	039	CHECK AND ADJUST TIRE PRESSURE AS NEEDED
05737	142884	04/01/2011	04/01/2011	0019046	097	PERFORMED WORLD CLASS INSPECTION
05737	142884	04/01/2011	04/01/2011	0019046	098	REPAIR AS NEEDED
05737	142884	04/01/2011	04/01/2011	0019046	A0009862150 9040	PAINT PIN
05737	142884	04/01/2011	04/01/2011	0019046	A2048202085 85	CONTROL UNIT
05759	553242	01/16/2010	02/26/2010	0010443	020	N/A
05759	553242	01/16/2010	02/26/2010	0010443	055	N/A
05759	553242	01/16/2010	02/26/2010	0010443	098	N/A
05759	553242	01/16/2010	02/26/2010	0010443	098	N/A
05737	685308	01/29/2010	01/29/2010	0006829	A0001802609	TS FILTER INSERT
05737	685308	01/29/2010	01/29/2010	0006829	A0019868071 17	WINDSHIELD WASHER FLUID
05737	685308	01/29/2010	01/29/2010	0006829	N007603014106	SEAL RING,VLRUB
05759	553242	01/16/2010	01/16/2010	0010443	20	DRIVE IN VEHICLE--INCLUDES COMPLIMENTARY CAR WASH
05759	553242	01/16/2010	01/16/2010	0010443	55	CHECK AND CORRECT ALL 5 TIRES FOR PRESSURE
05759	553242	01/16/2010	01/16/2010	0010443	98	-----WAITER-----
05759	553242	01/16/2010	01/16/2010	0010443	98	QUALITY CONTROL
05737	685308	07/18/2009	07/18/2009	0006829	25	"A" SERVICE
05737	685308	07/18/2009	07/18/2009	0006829	ASVC	
05737	685308	07/18/2009	07/18/2009	0006829	A0001802609	TS FILTER INSERT
05737	685308	07/18/2009	07/18/2009	0006829	A0019868071 17	WINDSHIELD WASHER FLUID
05737	685308	07/18/2009	07/18/2009	0006829	N007603014106	SEAL RING,VLRUB
05734	586462	07/03/2008	07/03/2008	0000009	38	NEW CAR DETAIL
05734	586462	07/03/2008	07/03/2008	0000009	38	PDI,PERFORM

EXHIBIT 18



U.S. Department of Transportation
**National Highway Traffic Safety
 Administration**

May 11, 2022

Mr. Greg Gunther
 Department Manager VCA
 Mercedes-Benz USA, LLC
 13470 International Parkway
 Jacksonville, FL 32218

1200 New Jersey Avenue SE
 Washington, DC 20590

NEF-107ES
 22V-315

Subject: Brake Booster Corrosion May Impair Braking

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/AMG R63/2007
 MERCEDES BENZ/GL320/2007-2009
 MERCEDES BENZ/GL350/2010-2012
 MERCEDES BENZ/GL450/2007-2012
 MERCEDES BENZ/GL550/2008-2012
 MERCEDES BENZ/ML320/2007-2009
 MERCEDES BENZ/ML350/2006-2011
 MERCEDES BENZ/ML450/2010-2011
 MERCEDES BENZ/ML500/2006-2007
 MERCEDES BENZ/ML550/2008-2011
 MERCEDES BENZ/R320/2007-2009
 MERCEDES BENZ/R500/2006-2007
 MERCEDES BENZ/AMG ML63/2007-2011
 MERCEDES BENZ/R350/2006-2012
 MERCEDES BENZ/R550/2008

Mfr's Report Date: May 9, 2022

NHTSA Campaign Number: 22V-315

Components:

SERVICE BRAKES, HYDRAULIC:POWER ASSIST:VACUUM

Potential Number of Units Affected: 292,287

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2006-2012 ML-Class, GL-Class, and R-Class vehicles. Please refer to MBUSA's recall report for specific vehicle model details. Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance or brake failure.

Consequence:

Reduced brake performance or brake failure can increase the risk of a crash.

Remedy:

Owners are advised not to drive their vehicles until the remedy has been performed. Dealers will remove the rubber sleeve, inspect the brake booster, and as necessary, replace the brake booster. All repairs will be performed free of charge. Owner notification letters are expected to be mailed May 27, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement

EXHIBIT 19

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBF71E39A493394**

VIN: 4JGBF71E39A493394 **Owner:** NONE **Engine No:** 27392330289053
FIN: 4JG1648711A493394 **Transmission No:** 72290402024539

Vehicle Info

Model/Year: GL450 2009 **Upholstery:** 104-Cashmere MB-Tex **Paint:** 650-Arctic White

Warranty & Sale

Warranty Start: 02/25/2009 **Retail Date:** 02/25/2009 **Selling Dealer:** 39142

Production Info

Radio Code: 42233 **Serial No:** 80925836 **Prod Date:** 11/12/2008

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
SD	SIRIUS TRAFFIC SERVICE HAS EXPIRED, CALL 888-465-8528 IF CUSTOMER WOULD LIKE TO RE-SUBSCRIBE.
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2022090006	22P4290007	10/13/2022	CLOSED	RECALL
2018100010	1810P91C96	10/29/2018	CLOSED	RECALL
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL
2009070002	0905P54B12	08/17/2009	CLOSED	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
MBCPO	BASE - CPO	11/06/2009	02/24/2014	9196	100000	59113	1245357
SIRI T	SIRI T	02/27/2009	08/27/2009	0	999999	G3	

Option Codes

Option	Description	Option	Description
-NJ		A05	
A05		A21	
A21		A22	
A22		A49	
A49		A52	
A52		A57	
A57		FV	
GA		H04	
H04		J58	
J58		K15	
K15		L	
M46		M46	
P02		R02	
R02		R55	
R55		U10	
U10		U12	
U12		U40	
U40		U71	
U71		U80	
U80		V43	
V43		067	
100		104	
182		182	
218		218	
220		220	



Option	Description	Option	Description
232		232	
242		242	
249		249	
275		275	
280		280	
293		293	
294		294	
299		299	
301		301	
345		345	
359		359	
414		414	
427		427	
438		438	
441		441	
461		461	
470		470	
489		489	
494		494	
500		500	
512		512	
517		517	
518		518	
524		524	
551		551	
581		581	
582		582	
600		600	
615		615	
619		619	
636		636	
650		666	
666		673	
673		690	
690		705	
720		720	
723		723	
763		763	
7XX		809	
809		810	
810		840	
840		845	
845		848	
848		864	
864		873	
873		889	
889		890	
890		904	
904		941	
941		951	
951		989	
989			

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 42900 07 7	???	17319	52540M	A	072583508	11/17/2022	11/21/2022	165626	02-KDM (Campaign)	
0 91931 02 7	Campaign 2018100010 - Replace Driver-Side Airbag	17319	145462	1	064786210	11/27/2018	11/27/2018	158411	02-KDM (Campaign)	
0 59900 02 7	Campaign 201207002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	17319	145462	2	064786210	11/27/2018	11/27/2018	158411	02-KDM (Campaign)	
0 46501 36 7	P/S pump, power /hydraulic steering Noise	59122	702304	2	051689214	08/24/2012	08/24/2012	60882	08-POW/ELW	




Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 09149 04 7	O-ring/seal, flange, crankcase ventilation system Leaks	59122	702304	7	051696985	08/24/2012	08/24/2012	60882	08-POW/ELW	
0 82283 73 7	Light source, brake light Electrical fault	59113	471089	4	050351601	11/10/2011	11/10/2011	45873	03-Warranty	
0 35477 36 7	Double-row angular contact ball-bearing Noise	59113	471089	6	050351601	11/10/2011	11/10/2011	45873	03-Warranty	
0 54553 90 8	Control unit, transmission Software status	59113	471089	1	050359163	11/10/2011	11/10/2011	45873	03-Warranty	
0 82282 73 7	Light source, taillight Electrical fault	59113	451292	4	048723619	11/30/2010	11/30/2010	26984	03-Warranty	
0 82283 73 7	Light source, brake light Electrical fault	59113	451292	1	048723619	11/30/2010	11/30/2010	26984	03-Warranty	
0 82282 73 7	Light source, taillight Electrical fault	59113	451176	1	048713883	11/27/2010	11/27/2010	26841	03-Warranty	
0 59812 74 8	K/Z* Door lock, front door Contact fault/open circuit	59113	429991	6	046798680	10/31/2009	10/31/2009	9178	03-Warranty	
0 54952 44 8	Campaign 2009 070002, Update Rear SAM Software (164.8)	59113	429991	3	046798680	10/31/2009	10/31/2009	9178	02-KDM (Campaign)	


Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
17319	52540M	11/17/2022	08/28/2023	0165628	098	THANK YOU FOR YOUR BUSINESS
17319	43989M	06/21/2022	08/09/2022	0165623	098	THANK YOU FOR YOUR BUSINESS
59122	702304	08/24/2012	08/24/2012	0060879	010	*SUSPENSION CONCERN
59122	702304	08/24/2012	08/24/2012	0060879	057	ELECT SYS BODY/INTER
59122	702304	08/24/2012	08/24/2012	0060879	057	ELECT SYS BODY
59122	702304	08/24/2012	08/24/2012	0060879	072	*INTERIOR/TRIM ITEMS
59122	702304	08/24/2012	08/24/2012	0060879	072	INTERIOR TRIM
59122	702304	08/24/2012	08/24/2012	0060879	A2519060000	MONITOR
59113	471089	11/10/2011	11/10/2011	0045868	055	TIRE PATCH REPAIR
59113	471089	11/10/2011	11/10/2011	0045868	070	*EXTERIOR TRIM
59113	471089	11/10/2011	11/10/2011	0045868	070	EXTERIOR TRIM
59113	471089	11/10/2011	11/10/2011	0045868	073	RENTAL CAR
59113	471089	11/10/2011	11/10/2011	0045868	098	*CUSTOMER REQUEST
59113	451292	11/30/2010	11/30/2010	0026982	061	N/A
59113	451292	11/30/2010	11/30/2010	0026982	073	N/A
59113	451292	11/30/2010	11/30/2010	0026982	61	STEERING SYS
59113	451292	11/30/2010	11/30/2010	0026982	73	LOANER
59113	451176	11/27/2010	11/27/2010	0026840	008	N/A
59113	451176	11/27/2010	11/27/2010	0026840	08	EMISSION INSPECTION
59113	451176	11/27/2010	11/27/2010	0026840	097	N/A
59113	451176	11/27/2010	11/27/2010	0026840	97	COURTESY INSPECTION
59113	430383	11/06/2009	11/06/2009	0009178	020	N/A
59113	430383	11/06/2009	11/06/2009	0009178	20	PRE-OWN DEL SPIFF
59113	430227	11/04/2009	11/04/2009	0009178	098	N/A
59113	430227	11/04/2009	11/04/2009	0009178	98	PHILS LEATHER
59113	430081	11/02/2009	11/02/2009	0009178	072	N/A
59113	430081	11/02/2009	11/02/2009	0009178	72	CPO DETAIL
59113	429991	10/31/2009	10/31/2009	0009175	007	N/A
59113	429991	10/31/2009	10/31/2009	0009175	008	N/A
59113	429991	10/31/2009	10/31/2009	0009175	025	N/A
59113	429991	10/31/2009	10/31/2009	0009175	039	N/A
59113	429991	10/31/2009	10/31/2009	0009175	042	N/A
59113	429991	10/31/2009	10/31/2009	0009175	07	ROTATE TIRES D
59113	429991	10/31/2009	10/31/2009	0009175	08	EMISSION INSPECTION
59113	429991	10/31/2009	10/31/2009	0009175	25	PERFORM A SERVICE
59113	429991	10/31/2009	10/31/2009	0009175	39	CPO INSPECTION
59113	429991	10/31/2009	10/31/2009	0009175	42	WIPER/WASHER SYS
59113	429991	10/31/2009	10/31/2009	0009175	A0001802609	TS FILTER INSERT
59113	429991	10/31/2009	10/31/2009	0009175	A0019868071 17	WINDSHIELD WASHER FLUID
59113	429991	10/31/2009	10/31/2009	0009175	A1698200445	WIPER BLADE
59113	429991	10/31/2009	10/31/2009	0009175	A2518200745	WIPER BLADE
59113	429991	10/31/2009	10/31/2009	0009175	B6551	
59113	429991	10/31/2009	10/31/2009	0009175	BQ1090144	Mobil 1 Formula M 5w40 Bu
59113	429991	10/31/2009	10/31/2009	0009175	MISC	
59113	429991	10/31/2009	10/31/2009	0009175	N007603014106	SEAL RING,VLRUB
39106	135573	02/24/2009	02/24/2009	0000001	098	N/A
39106	135573	02/24/2009	02/24/2009	0000001		
39106	135481	02/23/2009	02/23/2009	0000000	038	N/A
39106	135481	02/23/2009	02/23/2009	0000000	38	PDI DEL CERTIFICATIO
39106	135481	02/23/2009	02/23/2009	0000000	BOLT	Bolt
39106	135481	02/23/2009	02/23/2009	0000000	SOLV	

EXHIBIT 20

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF7BE2AA580139									
523340	1/21/2013				2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid---		harness connectors		2012070002-DONE. INSTALL PIGTAILS.;
		52767971	05765	4626273	Ignition lock--- Electrical fault	46	Steering	44,861	CUSTOMER STATES: CUST STATES THAT IT TAKES A LONG TIME TO START THE CAR; ; 44861 REPLACE EIS 000 C/S IT TAKES TOO LONG TO START CAR *AT TIMES-VERIFIED, WHEN TURNING KEY CLUSTER STAYS BLACK AND NOTHING HAPPENS. PERFORM SHORT TEST-CODE C426ÝSTART ENABLE/DRIVE AUTH NOT; **
524324	2/5/2013	52843459	05765	5800UZZ	Connecting cable, media interface (accessories)--- Special cost settlement	58	Tools	45,283	CUSTOMER STATES IPOD CABLE WILL NOT WORK.; F; 45283 REPLACED IPOD CABLE;
498161	9/10/2018	64381230	51140	9193101	Campaign 2018060011 - Replace Driver Airbag---	91	Seats, Bunks, Restraint Systems	130,543	CHECK AIRBAG CAMPAIGN 2018060011;CAMPAIGN;130452 CAMPAIGN REPLACED DRIVER SIDE AIRBAGS PER RECALL CAMPAIGN 2018060011 ID NUMBER 01 3125
899325	8/10/2022	70819503	51114	4290005	UNDEFINED---	42	Brakes	163,508	PERFORM MB RECALL 2022050014 OR 2022050015 AS PER MB WORK INSTRUCTIONS. THIS RECALL RELATED TO THE BRAKE BOOSTER ONLY. OTHER COMPONENTS IN NEED OF REPAIRS ARE NOT COVERED BY THIS RECALL. ASSUMPTION OF RISK FOR REMOVAL OF VEHICLE I UNDERSTAND THAT MY VEHICLE IS SUBJECT TO A STOP DRIVE RECALL AND THAT CONTINUING TO DRIVE MY VEHICLE INVOLVES INHERENT RISKS AND DANGERS OF ACCIDENTS, PROPERTY DAMAGE, OR LOSS, AND SERIOUS PERSONAL INJURY TO ME AND OTHERS AS WELL AS POTENTIAL FINANCIAL LOSSES. I HAVE CAREFULLY CONSIDERED THE EXTENT OF THE RISKS INVOLVED, AND I VOLUNTARILY AND FREELY CHOOSE TO ASSUME THESE RISKS.;DC-42900057;THERE WAS RUST SPOTS ON THE RUBBER SLEEVE THAT EXCEEDED 15MM, THEREFORE THE XENTRY TEST HAD TO BE CARRIED OUT. THE RESULT OF TEST IS THAT BRAKE BOOSTER IS OK.

EXHIBIT 21



VIN: 4JGBF7BE2AA580139 **Owner:** NONE **Engine No:** 27392330341962
FIN: 4JG1648711A580139 **Transmission No:** 72290402507547

Vehicle Info

Model/Year: GL450 2010 **Upholstery:** 151 **Paint:** 040

Warranty & Sale

Warranty Start: 02/02/2010 **Retail Date:** 02/02/2010 **Selling Dealer:** 05765

Production Info

Radio Code: 36214 **Serial No:** 91101341 **Prod Date:** 12/23/2009

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2018060011	1806P91B84	06/22/2018	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL
2022090006	22P4290007	10/13/2022	OPEN	RECALL

Option Codes

Option	Description	Option	Description
-CA	Wholesale state CA	A05	
A21		A22	
A49		A52	
J1A		J58	CONTROL CODE
K15		K22	SOFTWARE CONTROL F.LOW BEAM LI
K24		M46	CAPACITY 4,6 LITRE
P01	INVALID / SALES CODE FOR PRICE	R02	All season tyres
R33	5-twin-spoke light-alloy wheel	R66	Run-flat tyres (MOExtended)
U10	Front passenger seat with weig	U12	Velour floor mats
U38	Bumpers with scratch guard	U71	DVD-PLAYER WITH REGIONAL-CODE
U80	115 V socket in load area	V71	
182	CONVERTER WITH DEV. CHARACTERI	218	Reversing camera
220	PARKTRONIC system (PTS)	232	Garage door opener
236	daytime driving lights	249	Automatically dimming ext. and
275	Memory package el.adjust.drive	280	Leather steering wheel
293	Sidebag in rear left and right	294	Kneebag driver's side
299	PRE-SAFE b -System	301	Ashtray package
335		345	Windscreen wiper with rain sen
359	Teleaid Low Cost	414	Electric sunroof, glass versio
427	7-speed automatic transmission	438	Neck-Pro head restraints, 1st
441	Steering column electr. adjust	461	Instrument with mileage readin
475	Tyre pressure control	489	Airmatic package
494	US version	500	Electrically folding exterior
512	COMAND APS with DVD-changer	517	HD - Radio
518	Media Interface including cons	524	Paint protection - preservatio
550	trailer coupling	551	Anti-theft warning system
580	Automatic air conditioning	636	Omission of warning triangle
666	Prod. prot. f. freight pkgng	673	High-capacity battery
690	Emergency wheel (mini spare)	720	Roof rails/pre-installation fo
723	EASY-PACK load compartment cov	731	Wood finish, burr walnut trim
763	Radio remote control with pani	800	Technical modifications
840	Dark-tinted rear windscr./rear	845	Electrically folding 3rd seat
846	Aluminium-look running boards	848	Side window rear el. hinged
866	Pre-installation f. rear seat	873	Heated front seats
890	EASY-PACK-tailgate	900	Chrome package



Option	Description	Option	Description
981		989	Identification label under win

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 42900 05 7		51114	899325	2	070819503	08/10/2022	08/10/2022	000163508	02-KDM (Campaign)	0001
0 91931 01 7	Campaign 2018060011 - Replace	51140	498161	B	064381230	09/10/2018	09/10/2018	000130543	02-KDM (Campaign)	0001
0 5800U ZZ 7	Connecting cable, media interf	05765	524324	A	052843459	02/05/2013		000045283	03-Warranty	0001
0 59900 02 7	"Campaign 2012070002, Retrofit	05765	523340	F	052767971	01/21/2013		000044861	02-KDM (Campaign)	0002
0 46262 73 7	Ignition lock Electrical fault	05765	523340	A	052767971	01/21/2013		000044861	03-Warranty	0001
0 82123 73 7	Light source, headlamp Electri	05765	521466	A	052615290	12/29/2012		000044040	03-Warranty	0001
0 54001 73 7	Battery Electrical fault	05765	511501	A	052172159	07/29/2012		000037714	03-Warranty	0001
0 54001 P3 8	Battery On the Spot Help	05765	511501	B	051576618	07/29/2012		000037714	03-Warranty	0002
1 21402 00 0	ROADSIDE-JUMP START - (DAY-TI)	05765	511502	A	051576619	07/31/2012	07/29/2012		RAPS	0001
1 21864 00 0	MB Service Welcome, first tire	05765	465112	A	048151721	08/02/2010	08/02/2010		RAPS	0001
0 33112 36 7	Transverse control arm bearing	05765	460213	B	047822442	05/19/2010		000003846	03-Warranty	0002
0 81A13 06 7	Sun visor holder/bearing left	05765	460213	A	047822442	05/19/2010		000003846	03-Warranty	0001

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51114	899325	08/10/2022	08/10/2022	0163508	012	PERFORM SERVICE
51114	899325	08/10/2022	08/10/2022	0163508	098	CLIENT IS WAITING
51140	547522	04/05/2021	04/07/2021	0154415	015	TEST AND REPLACE BATTERY R-CLASS, ML-CLASS, GL-CLASS
51140	547522	04/05/2021	04/07/2021	0154415	039	PERFORM QUICK TEST
51140	547522	04/05/2021	04/07/2021	0154415	068	REPLACE ALTERNATOR
51140	547522	04/05/2021	04/07/2021	0154415	097	MPI
51140	547522	04/05/2021	04/07/2021	0154415	098	CUSTOMER STATES:
51140	547522	04/05/2021	04/07/2021	0154415	A0019828208	STARTER BATTERY
51140	547522	04/05/2021	04/07/2021	0154415	A0019828208	STARTER BATTERY
51140	547522	04/05/2021	04/07/2021	0154415	A0039937296	V-RIBBED BELT
51140	547522	04/05/2021	04/07/2021	0154415	A0141540402 80	REMAN-ALTERNATOR
51140	519840	09/20/2019	09/25/2019	0143469	009	FOUR WHEEL ALIGNMENT TRUCK
51140	519840	09/20/2019	09/25/2019	0143469	073	
51140	519840	09/20/2019	09/25/2019	0143469	098	GROUP 32 - NO OPERATION NO. AND TIME GIVEN USE ACTUAL TIME (PUNCH CARD) WITH 32-0000/01 AS OPERATION NO.
51140	519840	09/20/2019	09/25/2019	0143469	A0019909154	UNION NUT
51140	519840	09/20/2019	09/25/2019	0143469	A0029900954	NUT
51140	519840	09/20/2019	09/25/2019	0143469	A1643560201	WHEEL HUB
51140	519840	09/20/2019	09/25/2019	0143469	A1644016002 80	EXCHANGE MB 5TWIN SPOKE
51140	519840	09/20/2019	09/25/2019	0143469	A1649810206	BARREL-TYPE BEARING
51140	519840	09/20/2019	09/25/2019	0143469	B66470131	EXCHANGE MB 5TWIN SPOKE W
51140	519840	09/20/2019	09/25/2019	0143469	N000472098000	LOCK RING
51140	519495	09/16/2019	09/18/2019	0143337	010	BOTH FRONT STRUTS FOR AIR SUSPENSION (AIRMATIC) REPLACE
51140	519495	09/16/2019	09/18/2019	0143337	073	
51140	519495	09/16/2019	09/18/2019	0143337	A0019909154	UNION NUT
51140	519495	09/16/2019	09/18/2019	0143337	A0029900954	NUT
51140	519495	09/16/2019	09/18/2019	0143337	A1643206113 80	REMAN AIR SUSPENSION STRU
51140	519495	09/16/2019	09/18/2019	0143337	N000000003250	WASHER
51140	519495	09/16/2019	09/18/2019	0143337	N000000003277	NUT


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGBF7BE2AA580139**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51140	519495	09/16/2019	09/18/2019	0143337	N000000003343	NUT
51140	519495	09/16/2019	09/18/2019	0143337	N000000003905	NUT
51140	519495	09/16/2019	09/18/2019	0143337	N000000005533	HEXAGON HEAD BOLT
51140	513135	06/03/2019	06/03/2019	0140000	098	CUSTOMER STATES:
51140	498161	09/10/2018	09/10/2018	0130543	055	CUSTOMER REQUEST REPAIR ONE TIRE (PATCH) INCLUDING REBALANCE
51140	498161	09/10/2018	09/10/2018	0130543	A0004001000	TIRE VALVE
51140	464011	01/23/2017	01/25/2017	0106870	001	LUBE-OIL-GREASE CHARGES
51140	464011	01/23/2017	01/25/2017	0106870	010	COMPRESSOR FOR AIR SUSPENSION REMOVE/INSTALL AND, IF NECESSARY, REPLACE
51140	464011	01/23/2017	01/25/2017	0106870	028	20,000 MILES / B MAINTENANCE SERVICE OR 2 YEAR - REQUIRED
51140	464011	01/23/2017	01/25/2017	0106870	073	
51140	464011	01/23/2017	01/25/2017	0106870	083	BRAKE FLUID SERVICE
51140	464011	01/23/2017	01/25/2017	0106870	098	MISC. SHOP CHARGES
51140	464011	01/23/2017	01/25/2017	0106870	A0001802609	TS FILTER INSERT
51140	464011	01/23/2017	01/25/2017	0106870	A0009862000 09	WINDSHIELD WASHER FLUID
51140	464011	01/23/2017	01/25/2017	0106870	A0009890807 01	BRAKE FLUID
51140	464011	01/23/2017	01/25/2017	0106870	A0025427619	RELAY
51140	464011	01/23/2017	01/25/2017	0106870	A1643201204 80	REMAN COMPRESSOR
51140	464011	01/23/2017	01/25/2017	0106870	A1648300218 64	COMBINATION FILTER
51140	464011	01/23/2017	01/25/2017	0106870	NA	
51140	464011	01/23/2017	01/25/2017	0106870	N000000004215	FUSE LINK
51140	464011	01/23/2017	01/25/2017	0106870	N007603014106	SEAL RING,VLRUB
51140	458410	10/10/2016	10/15/2016	0102909	057	PROGRAM AND PARAMETERIZE CONTROL UNIT (AFTER QUICK TEST)
51140	458410	10/10/2016	10/15/2016	0102909	098	CUSTOMER STATES:
51140	458410	10/10/2016	10/15/2016	0102909	098	GROUP 15 - NO OPERATION NO. AND TIME GIVEN USE ACTUAL TIME (PUNCH CARD) WITH 15-0000/01 AS OPERATION NO.
51140	458410	10/10/2016	10/15/2016	0102909	A0007669606 9999	ORANGE KEY
51140	458410	10/10/2016	10/15/2016	0102909	A0061515901 87	REMAN STARTER MOTOR
51140	458410	10/10/2016	10/15/2016	0102909	A1649051600	IGNITION STARTER SWITCH
51140	457908	10/01/2016	10/03/2016	0102616	055	CHECK TIRE CONDITION AND ROTATE
51140	457908	10/01/2016	10/03/2016	0102616	056	REPLACE ONE NEW TIRE (MOUNT AND BALANCE)
51140	457908	10/01/2016	10/03/2016	0102616	073	
51140	457908	10/01/2016	10/03/2016	0102616	087	COMPLIMENTARY 27 POINT VISUAL SERVICE INSPECTION
51140	457908	10/01/2016	10/03/2016	0102616	098	CUSTOMER STATES:
51140	457908	10/01/2016	10/03/2016	0102616	098	MISC. SHOP CHARGES
51140	457908	10/01/2016	10/03/2016	0102616	BQ8401336	PIRELLI 275/50R20 SKU, 21
51140	445561	03/07/2016	03/08/2016	0093718	011	REPLACE FRONT BRAKE PADS (TRUCK)
51140	445561	03/07/2016	03/08/2016	0093718	011	BRAKE ROTORS ON FRONT AXLE REMOVE/INSTALL AND, IF NECESSARY, REPLACE (WITH BRAKEPADS REMOVED)
51140	445561	03/07/2016	03/08/2016	0093718	073	
51140	445561	03/07/2016	03/08/2016	0093718	098	MISC. SHOP CHARGES
51140	445561	03/07/2016	03/08/2016	0093718	A0179908201	SCREW
51140	445561	03/07/2016	03/08/2016	0093718	A1644202620	TS DISK BRAKE PAD
51140	445561	03/07/2016	03/08/2016	0093718	A1644211412	BRAKE DISK, VENTED
51140	445561	03/07/2016	03/08/2016	0093718	A1645401017	SENSOR
51140	445561	03/07/2016	03/08/2016	0093718	A2204210171	PAN HEAD FIT BOLT
51140	437455	10/07/2015	10/30/2015	0088745	073	
51140	437455	10/07/2015	10/30/2015	0088745	098	GROUP 32 - NO OPERATION NO. AND TIME GIVEN USE ACTUAL TIME (PUNCH CARD) WITH 32-0000/01 AS OPERATION NO.
51140	437455	10/07/2015	10/30/2015	0088745	A1643206113	EXCHANGE AIR SUSPENSION S
05253	433427	09/12/2014	09/12/2014	0078079	055	Perform Complimentary Tire Pressure Inspection, correction and reset monitor
05253	433427	09/12/2014	09/12/2014	0078079	057	Miscellaneous Body Electrical - Repair
05253	433427	09/12/2014	09/12/2014	0078079	070	Miscellaneous Body - Repair
05253	433427	09/12/2014	09/12/2014	0078079	072	Miscellaneous Body Interior - Repair
05253	433427	09/12/2014	09/12/2014	0078079	073	Alternative Transportation - Complimentary Loaner Vehicle.
05253	426401	04/28/2014	04/28/2014	0070040	001	LUBE-OIL-GREASE CHARGES
05253	426401	04/28/2014	04/28/2014	0070040	009	Wheels, Chassis, Alignment
05253	426401	04/28/2014	04/28/2014	0070040	028	Service at 70,000 miles or 7 years - Required
05253	426401	04/28/2014	04/28/2014	0070040	055	Perform Complimentary Tire Pressure Inspection, correction and reset monitor
05253	426401	04/28/2014	04/28/2014	0070040	057	Electrical System - Equipment and Instruments



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05253	426401	04/28/2014	04/28/2014	0070040	073	Alternative Transportation - Complimentary Loaner Vehicle.
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	098	*** OPCODE NOT ON REPORT ***
05253	426401	04/28/2014	04/28/2014	0070040	A0001802609	TS FILTER INSERT
05253	426401	04/28/2014	04/28/2014	0070040	A0019868071 17	WINDSHIELD WASHER FLUID
05253	426401	04/28/2014	04/28/2014	0070040	N400809000007	BULB
05253	419783	12/17/2013	12/18/2013	0062525	001	LUBE-OIL-GREASE CHARGES
05253	419783	12/17/2013	12/18/2013	0062525	016	Spark Plugs - Replace
05253	419783	12/17/2013	12/18/2013	0062525	019	Transmission Service (Automatic) - Replace Gasket and Filter
05253	419783	12/17/2013	12/18/2013	0062525	039	Tire Pressure Inspection and Correction
05253	419783	12/17/2013	12/18/2013	0062525	047	Air Filter Element - Replace
05253	419783	12/17/2013	12/18/2013	0062525	056	Wheel(s)/Tire(s) - Mount and Balance
05253	419783	12/17/2013	12/18/2013	0062525	073	Alternative Transportation - Loafer Car
05253	419783	12/17/2013	12/18/2013	0062525	098	*** OPCODE NOT ON REPORT ***
05253	419783	12/17/2013	12/18/2013	0062525	098	Miscellaneous
05253	419783	12/17/2013	12/18/2013	0062525	098	MISC. SHOP CHARGES
05253	419783	12/17/2013	12/18/2013	0062525	A0009880152	MAGNET
05253	419783	12/17/2013	12/18/2013	0062525	A0041594903	SPARK PLUG
05253	419783	12/17/2013	12/18/2013	0062525	A0049903512	SCREW
05253	419783	12/17/2013	12/18/2013	0062525	A2202710380	GASKET
05253	419783	12/17/2013	12/18/2013	0062525	A2212770195	OIL FILTER
05253	419783	12/17/2013	12/18/2013	0062525	A2512710097	PIPE
05253	419783	12/17/2013	12/18/2013	0062525	A2730940404	TS AIR FILTER ELEMENT
05253	419783	12/17/2013	12/18/2013	0062525	BQ8400603	GOODYEAR 275/50R20 SKU 70
05253	419783	12/17/2013	12/18/2013	0062525	N007603012102	RING,GENERAL,METAL
05253	417795	11/06/2013	11/06/2013	0060356	039	Tire Pressure Inspection and Correction
05253	417795	11/06/2013	11/06/2013	0060356	057	Electrical System - Body
05253	417795	11/06/2013	11/06/2013	0060356	A1648203664	TAILLAMP
05253	417644	11/04/2013	11/04/2013	0060285	001	LUBE-OIL-GREASE CHARGES
05253	417644	11/04/2013	11/04/2013	0060285	011	Brake Pads, Front (Factory) - Replace
05253	417644	11/04/2013	11/04/2013	0060285	013	Disc Pads, Rear - Replace
05253	417644	11/04/2013	11/04/2013	0060285	028	Maintenance Service Type II
05253	417644	11/04/2013	11/04/2013	0060285	039	Tire Pressure Inspection and Correction
05253	417644	11/04/2013	11/04/2013	0060285	057	Electrical System - Equipment and Instruments
05253	417644	11/04/2013	11/04/2013	0060285	073	Alternative Transportation - Loafer Car
05253	417644	11/04/2013	11/04/2013	0060285	098	Miscellaneous
05253	417644	11/04/2013	11/04/2013	0060285	098	MISC. SHOP CHARGES
05253	417644	11/04/2013	11/04/2013	0060285	A0001802609	TS FILTER INSERT
05253	417644	11/04/2013	11/04/2013	0060285	A0019868071 17	WINDSHIELD WASHER FLUID
05253	417644	11/04/2013	11/04/2013	0060285	A0019899451	BRAKE PASTE
05253	417644	11/04/2013	11/04/2013	0060285	A0019899451	BRAKE PASTE
05253	417644	11/04/2013	11/04/2013	0060285	A1644201820	BRAKE PAD
05253	417644	11/04/2013	11/04/2013	0060285	A1644201920	BRAKE PAD
05253	417644	11/04/2013	11/04/2013	0060285	A1645401017	SENSOR
05253	417644	11/04/2013	11/04/2013	0060285	A1645401017	SENSOR
05253	417644	11/04/2013	11/04/2013	0060285	A1648300218 64	COMBINATION FILTER
05253	417644	11/04/2013	11/04/2013	0060285	N007603014106	SEAL RING,VLRUB
05765	524324	02/05/2013	02/05/2013	0045283	020	COMPLIMENTARY EXTERIOR CAR WASH AND INTERIOR VACUUM AT NO CHARGE (\$14.95VALUE)
05765	524324	02/05/2013	02/05/2013	0045283	039	PERFORM MERCEDES-BENZ VEHICLE INSPECTION. INCLUDES SETTING TIRE PRESSURE ACCORDING TO MANUFACTURER'S SPECIFICATIONS AND REACTIVATING TIRE PRESSURE MONITOR SYSTEM.
05765	524324	02/05/2013	02/05/2013	0045283	057	INSPECT AND ADJUST TIRES PRESSURE AND RESET MONITORING SYSTEM
05765	524324	02/05/2013	02/05/2013	0045283	098	NO INTERVAL DUE
05765	523340	01/24/2013	01/24/2013	0044861	020	COMPLIMENTARY EXTERIOR CAR WASH AND INTERIOR VACUUM AT NO CHARGE (\$14.95VALUE)



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05765	523340	01/24/2013	01/24/2013	0044861	039	PERFORM MERCEDES-BENZ VEHICILE INSPECTION. INCLUDES SETTING TIRE PRESSUREACCORDING TO MANUFACTURER'S SPECIFICATIONS AND REACTIVATING TIRE PRESSURE MONITOR SYSTEM.
05765	523340	01/24/2013	01/24/2013	0044861	057	INSPECT AND ADJUST TIRES PRESSURE AND RESET MONITORING SYSTEM
05765	523340	01/24/2013	01/24/2013	0044861	098	NO INTERVAL DUE
05765	521466	12/29/2012	12/29/2012	0044040	039	PERFORM MERCEDES-BENZ VEHICILE INSPECTION. INCLUDES SETTING TIRE PRESSUREACCORDING TO MANUFACTURER'S SPECIFICATIONS AND REACTIVATING TIRE PRESSURE MONITOR SYSTEM.
05765	511502	07/31/2012	07/31/2012	0037702	039	PERFORM MERCEDES-BENZ VEHICLE INSPECTION,INCLUDING SETTING TIRE PRESSUREACCORDING TO MANUFACTURER'S SPECIFICATION
05765	511501	07/31/2012	07/31/2012	0037714	039	PERFORM MERCEDES-BENZ VEHICLE INSPECTION,INCLUDING SETTING TIRE PRESSUREACCORDING TO MANUFACTURER'S SPECIFICATION
05765	484316	05/23/2011	05/23/2011	0019922	012	(MBF1R)REPLACE BRAKE FLUID
05765	484316	05/23/2011	05/23/2011	0019922	020	COMPLIMENTARY EXTERIOR CAR WASH AND INTERIOR VACUUM AT NO CHARGE (\$14.95 VALUE)
05765	484316	05/23/2011	05/23/2011	0019922	026	(MFBFS8)PERFORM FLEXIBLE SERVICE SYSTEM "B"
05765	484316	05/23/2011	05/23/2011	0019922	039	PLEASE REFER TO TECHNICIANS STORY FOR DIAGNOSIS AND REPAIR
05765	484316	05/23/2011	05/23/2011	0019922	039	MERCEDES-BENZ VEHICLE INSPECTION
05765	484316	05/23/2011	05/23/2011	0019922	079	(MCFR)REPLACE CABIN AIR FILTER
05765	484316	05/23/2011	05/23/2011	0019922	098	^^
05765	484316	05/23/2011	05/23/2011	0019922	A0001802609	TS FILTER INSERT
05765	484316	05/23/2011	05/23/2011	0019922	A0009862150 9040	PAINT PIN
05765	484316	05/23/2011	05/23/2011	0019922	A0009890807 01	BRAKE FLUID
05765	484316	05/23/2011	05/23/2011	0019922	A1648300218 64	COMBINATION FILTER
05765	484316	05/23/2011	05/23/2011	0019922	N007603014106	SEAL RING,VLRUB
05765	479115	03/01/2011	03/01/2011	0016193	020	N/A
05765	479115	03/01/2011	03/01/2011	0016193	039	N/A
05765	479115	03/01/2011	03/01/2011	0016193	056	N/A
05765	479115	03/01/2011	03/01/2011	0016193		
05765	479115	03/01/2011	03/01/2011	0016193	BQ8400603	GOODYEAR 275/50R20 SKU 70
05765	469224	11/18/2010	11/18/2010	0009866	020	N/A
05765	469224	11/18/2010	11/18/2010	0009866	025	N/A
05765	469224	11/18/2010	11/18/2010	0009866	039	N/A
05765	469224	11/18/2010	11/18/2010	0009866	073	N/A
05765	469224	11/18/2010	11/18/2010	0009866	098	N/A
05765	469224	11/18/2010	11/18/2010	0009866	N007603014106	SEAL RING,VLRUB
05765	465112	11/18/2010	11/18/2010	0006415	039	N/A
05765	465112	11/18/2010	11/18/2010	0006415	098	N/A
05765	464347	11/18/2010	11/18/2010	0005839	020	N/A
05765	464347	11/18/2010	11/18/2010	0005839	039	N/A
05765	464347	11/18/2010	11/18/2010	0005839	039	N/A
05765	464347	11/18/2010	11/18/2010	0005839	098	N/A
05765	460213	11/18/2010	11/18/2010	0003846	020	N/A
05765	460213	11/18/2010	11/18/2010	0003846	020	N/A
05765	460213	11/18/2010	11/18/2010	0003846	039	N/A
05765	460213	11/18/2010	11/18/2010	0003846	098	N/A
05765	452852	11/18/2010	11/18/2010	0000003	072	N/A
05765	469224	10/04/2010	10/04/2010	0009866	20	COMPLIMENTARY EXTERIOR CAR WASH AND INTERIOR VACUUM AT NO CHARGE (\$14.95 VALUE)
05765	469224	10/04/2010	10/04/2010	0009866	25	(MFAFS8)PERFORM SERVICE SYSTEM "A"
05765	469224	10/04/2010	10/04/2010	0009866	39	COURTESY INSPECTION PERFORMED AT NO CHARGE (\$77.50 VALUE)
05765	469224	10/04/2010	10/04/2010	0009866	73	COMPLIMENTARY RENTAL VEHICLE PROVIDED FOR ONE DAY AT NO CHARGE(\$89.95 VALUE)
05765	469224	10/04/2010	10/04/2010	0009866	98	^^
05765	469224	10/04/2010	10/04/2010	0009866	ANWW	
05765	469224	10/04/2010	10/04/2010	0009866	AN007603014 106	
05765	469224	10/04/2010	10/04/2010	0009866	AN2609	
05765	469224	10/04/2010	10/04/2010	0009866	AN5080784	
05765	469224	10/04/2010	10/04/2010	0009866	MFAFS	




Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05765	465112	08/02/2010	08/02/2010	0006414	39	COURTESY INSPECTION PERFORMED AT NO CHARGE (\$77.50 VALUE)
05765	465112	08/02/2010	08/02/2010	0006414	98	DO NOT WASH VEHICLE
05765	464347	07/21/2010	07/21/2010	0005839		
05765	460213	05/19/2010	05/19/2010	0003846		
05765	452852	02/02/2010	02/02/2010	0000003		
05138	123657	01/29/2010	01/29/2010	0000014	001	N/A
05138	123657	01/29/2010	01/29/2010	0000014	038	N/A
05138	123657	01/29/2010	01/29/2010	0000014		

EXHIBIT 22

Vehicle History Detail

RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF7BE8CA765427									
445810	1/12/2016				Newer---Special regulation		CODES		
		59476821	14316	3250504	Spring strut/air spring, front---Leaks	32	Suspension	66,529	ADDED LINE FOR L/FRONTING; DURING SERVICE FIND L/F AIRMATIC STRUT LEAKING; 66529 DURING SERVICE FIND L/F AIRMATIC STRUT LEAKING DURING SERVICE FIND L/F AIRMATIC STRUT LEAKING, REPLACED L/FAIRMATIC STRUT, RRETEST FIND OPERATING AS DESIGNED
465089	5/2/2016	60265152	14316	3250504	Spring strut/air spring, front---Leaks	32	Suspension	71,100	CUSTOMER STATES CAR LEANS TO THE RIGHT; F; 71099 TRACED LEAK TO R/F STRUT. REPLACED DEFECTIVE R/F STRUT
		60265152	14316	8288273	Push button, service/break-down service---Electrical fault	82	Electrical System - Body	71,100	CUSTOMER STATES CAR DIALED SOS ON ITS OWN, THEN DISPLAY SHOWED SOS INOP; F; 71099 SHORT TEST FOUND FAULT FOR ROAD SIDE BUTTON CALL BU TTON STICKING, CAUSING FALSE CALLS TO MBRACE. REPLACED DEFECTIVE BUTTON GROUP IN CONSOLE
515211	2/14/2017	61944632	14316	1500173	Starter motor--- Electrical fault	15	Electrical System - Engine	82,555	CUSTOMER STATES THE CAR HAS A SLUGGISH START; F; 82555 VERIFIED COMPLAINT OF VEHICLE SLOW TO START. AFTER REPLACEMENT OF SYSTEM BATTERY ON LINE H DUE TO FAILED MIDTRONC TET, FOUND VEHICLE IS STILL SLOW TO START. FOUND START HAS EXCESSIVE DRAW WHEN
		61944632	14316	3251104	Spring strut/air spring, rear---Leaks	32	Suspension	82,555	CUSTOMER STATES THE REAR OF THE CAR DROPS AFTER SITTING FOR A FEW HOURS; F; 82555 VERIFIED COMPLAINT OF REAR OF VEHICLE IS LOW. INSPE CTED AND FOUND LR AIRMATIC AIR SPRING IS LEAKING. REPLACED LR AIRMATIC AIR SPRING, CONNECTED SDS AND SET VEHICLE TO CALIBRATED RIDE **
535697	6/12/2017	62359617	14316	3251104	Spring strut/air spring, rear---Leaks	32	Suspension	88,164	CUSTOMER STATES THE REAR SUSPENSION IS DROPPING; F; 88162 VERIFIED COMPLAINT. LEAK TEST AIRMATIC SYSTEM FOUND R/R AIR BELLOW LEAKING. ALSO NOTICED AIRMATIC PUMP EXCESSIVELY NOISY DUE TO OVER RUNNING FROM LEAKING AIR BAG, REPLACED R/R AIR BELLOW. REPLACED DEFECTIVE AIRMATIC PUMP.
2051205	5/23/2019	65720061	14316	9194002	Campaign 2019030018 - Replace Driver-Side Airbag---	91	Seats, Bunks, Restraint Systems	119,625	PERFORM RECALL CAMPAIGN 2019030018 REPLACE DRIVER-SIDE AIRBAG; F; 119623 REPLACE DRIVER AIRBAG PER RECALL 2019030018. REPLACE DRIVER AIRBAG (02-2941). MB SCAN ID: 04DD03.
289932	7/21/2022	70768929	14118	4290005	UNDEFINED---	42	Brakes	170,210	MANUFACTURER SAFETY RECALL ISSUED NHTSA #22V315 RECALL #2022050015 RECALL - SAFETY TITLE/ TOPIC: BRAKE BOOSTER - NO BRAKE PEDAL RE- WORK MY: 2006-2013 MODELS: VARIOUS STATUS: REMEDY AVAILABLE; ; 170210 2022050015 INSPECT BOOSTER RUBBER SLEEVE. DISPATCH RUBBER SLEEVE. CONNECT SDS AND CHARGER. PERFORM BRAKE POWER TEST. CHECKS OK.
290417	8/2/2022	70781128	14118	9930401	Technical retrofit as of B2007---Follow-up operations	99	Printed Matter	170,211	CLIENT REQUESTING REFUND FOR RENTAL BILL INCURRED UNTIL VEHICLE COULD GET IN FOR BRAKE BOOSTER INSPECTION; 170211 CLIENT SEEKING REFUND FOR RENTAL CHARGES INCURRED UNDER BRAKE BOOSTER RECALL. CLIENT WENT

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF7BE8CA765427					MY 2012		GL Class	Series 164	GL450
									INTO RENTAL ON 5/28/22 AT 11:03 AM, CLIENT RETURNED RENTAL ON 7/29/22 AT 10:00 AM. CLIENT WAS IN RENTAL FOR 63 DAYS. 63 X 80.00 PER DAY IS THE MAXIMUM REFUND=5040.00. HERTZ RENT A CAR AGREEMENT #579640165.

EXHIBIT 23



VIN: 4JGBF7BE8CA765427 **Owner:** NONE **Engine No:** 27392330442192
FIN: 4JG1648711A765427 **Transmission No:** 72290403512513

Vehicle Info

Model/Year: GL450 2012 **Upholstery:** 151 **Paint:** 040

Warranty & Sale

Warranty Start: 12/26/2011 **Retail Date:** 12/26/2011 **Selling Dealer:** 14316

Production Info

Radio Code: 21633 **Serial No:** B0891883 **Prod Date:** 08/23/2011

Status: 2-SCRAPPED

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2019030018	19P9194002	03/25/2019	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL
2022090006	22P4290007	10/13/2022	OPEN	RECALL

Service Packages


Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
MBCPO	BASE - CPO	01/31/2015	12/25/2016	0047994	0999999	14316	2694850
MBCPO	24 MO CPO - 36 TOTAL	12/26/2016	12/25/2018	0047994	0999999	14316	2694851
MBFS	WHEEL & TIRE	12/26/2011	12/26/2016	0000000	0999999		0010070080
MBR	MBRACE TRIAL NEW VEHICLES	12/27/2011	06/27/2012	0000000	0999999		1-2453241
MBR	MBRACE 1YR	06/27/2013	06/27/2013	0000000	0999999		1-4356531
MBR	MBRACE PLUS 3 MO TRIAL	12/27/2011	03/27/2012	0000000	0999999		1-2445091
MBR	MBRACE PLUS MONTH TO MONTH	03/27/2012	09/23/2015	0000000	0999999		1-2939735
MNT	STR PPMSC-2 Services - 2 Service Used Car PPM (For	01/31/2015	01/12/2016	0047994	0999000	14316	2694849
MNT	STAR MNT30K PPMS-3YR - 30,000 MILE PREPAID MAINTEN	12/26/2011	01/30/2015	0000000	0129999	14316	1619595

Option Codes


Option	Description	Option	Description
-FL	Wholesale state FL	A05	
A21		A22	
A49		A52	
A89		B12	Tyre-change tool kit
FV	SEDAN ELONGATED	GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE	J1A	
J58	CONTROL CODE	K15	
L	L.H.D	M46	CAPACITY 4,6 LITRE
R02	All season tyres	R33	5-twin-spoke light-alloy wheel
R66	Run-flat tyres (MOExtended)	U10	Front passenger seat with weig
U12	Velour floor mats	U38	Bumpers with scratch guard
U71	DVD-PLAYER WITH REGIONAL-CODE	U80	115 V socket in load area
VL	FRONT AXLE HALF SHAFT, LEFT	VR	FRONT AXLE HALF SHAFT, RIGHT
V71		040	Black
150	R.H.D.	151	Black ARTICO man-made leather
218	Reversing camera	220	PARKTRONIC system (PTS)
232	Garage door opener	234	Blind Spot Assist
240	LED-daytime running lights	242	Front seat right, electr.adju
249	Automatically dimming ext. and	275	Memory package el.adjust.drive

EXHIBIT 24

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBB86E79A488175					MY 2009	M Class		Series 164	ML350W4
132697	11/14/2008	44960236	39106	21852ZZ	DEALER PRE-DELIVERY (PDI)--- Special cost settlement	21	MBUSA SPECIAL DAMAGE CODES	1	PDI DELIVERY CERTIFICATION. NON TIME FOR PDI DELIVERY CERTIFICATION. SYSTEM DID NOT CREATE METHOD FOR PAYMENT
141128	9/30/2009	46627093	39106	5495241	"Campaign 2009 030003, Reposition LG Control Unit and Repl Tail Lamp Seals---	54	Electrical System, Equipment And Instruments	10,084	PERFORM RECALL CAMPAIGN BULLETIN 2009030003REPOSITION POWER LIFT GATE MODULE AND REPLACE RT AND LEFT TAILAMP UNIT SEALS; CAMPAIGN DUE ON VEHICLE.; COMPLETED;
058082	1/15/2010	47197234	22427	72E0606	Trim piece, door panel, front door, left---Broken	72	Doors (73. Rear Doors)	11,486	DIAGNOSE LEFT FRONT DOOR WOOD TRIM CRACKED.; LEFT FRONT DOOR WOOD TRIM CRACKED.; REMOVED AND RE- INSTALLED DRIVER'S DOOR PANEL. REPLACED LEFT FRONT DOOR WOOD TRIM;
65671	3/30/2010	47578428	22427	5410X73	Additional battery, park pawl, transmission---Electrical fault	54	Electrical System, Equipment And Instruments	11,507	C/S BATTERY LIGHT COMES ON.; AUXILLARY BATTERY6 G1/7 DOES NOT HOLD CHARGE.; PERFORMED SHORT TEST, FOUND DTC 9062 STORED. REPLACED AUXILLARY BATTERY;
86010	8/25/2011	49971456	22121	3221136	Front torsion bar linkage/plate--- Noise	32	Suspension	31,552	CUSTOMER STATES RATTLE HEARD FROM UNDER VEHOCLE WHILE DRIVING; NOISE FROM SWAY BAR END LINKS.; VEHICLE CHASSIS NOISE(S), LOCATE;
0181936	9/15/2014	56752120	22131	2120600	"SIGN AND DRIVE, "JUMPSTART"Prgrm Eligible"--- Special regulation	21	MBUSA SPECIAL DAMAGE CODES	31,561	;*
414131	1/28/2016	59643500	22427	5990002	"Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid---	59	Electrical harness connectors	73,237	PERFORM CAMPAIGN #2012070002 CAM SOLENOID;CAMPAIGN 2012070002;73237 CAMPAIGN 2012070002 20 INSTALL NEW WIRING HARNESSES FOR CAM SO LENOID MAGNETS.
436912	7/19/2017	100801763	22427	2140200	SIGN AND DRIVE, "JUMPSTART"---Special regulation	21	MBUSA SPECIAL DAMAGE CODES	80,471	ROADSIDE ASSISTANCE CASE # 1958318555 JUMP START;F;80471 3625 JUMP START
799254	7/25/2022	70995817	86111	4290005	UNDEFINED---	42	Brakes	161,847	PERFORM RECALL 2022050015;;161847 AS PER RECALL - 2022050015, INSPECTED BRAKE BOOSTER RUBBER. FOUND THAT CORROSION ON RUBBER PASSE D AND ONLY ONE SPOT WAS BIGGER THEN 15MM. TOOK PICTURE OF RUBBER NEXT TO VIN CARD AND SENT
		70995817	86111	9193101	Campaign 2018060011 - Replace Driver Airbag---	91	Seats, Bunks, Restraint Systems	161,847	PERFORM RECALL 2018060011;;161847 REMOVED AND REPLACED DRIVERS AIRBAGS PER CAMPAIGN - 2018060011. ID # 297DFF.
802152	9/20/2022	71012222	86111	9930401	Technical retrofit as of B2007---	99	Printed Matter	161,848	RENTAL RELATED TO BRAKE BOOSTER RECALL # 202205001

Vehicle History Detail

RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBB86E79A488175					MY 2009	M Class	Series 164	ML350W4	
					Follow-up operations			5.;.	

EXHIBIT 25

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBB86E79A488175**

VIN: 4JGBB86E79A488175 **Owner:** NONE **Engine No:** 27296731091040
FIN: 4JG1641861A488175 **Transmission No:** 72290602019211

Vehicle Info

Model/Year: ML350W4 2009 **Upholstery:** 151 **Paint:** 723

Warranty & Sale

Warranty Start: 11/24/2008 **Retail Date:** 11/24/2008 **Selling Dealer:** 75124

Production Info

Radio Code: 13321 **Serial No:** 80718845 **Prod Date:** 10/29/2008

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
SD	SIRIUS TRAFFIC SERVICE HAS EXPIRED, CALL 888-465-8528 IF CUSTOMER WOULD LIKE TO RE-SUBSCRIBE.
75	!! IGNORE UNLESS AEM!!Vehicle suspected to have mileage tampering. ONLY IF PART OF AEM OPEN TIPS CASE
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2009030003	0902P54A49	04/29/2009	CLOSED	RECALL
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2018060011	1806P91B84	06/22/2018	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI T	SIRI T	12/15/2008	06/15/2009	0000000	0999999	G3	029454031602

Option Codes

Option	Description	Option	Description
-NJ	Wholesale state NJ	A05	
A21		A54	
A57		H04	Wood finish, fineline bird's e
J58	CONTROL CODE	K15	
M35	CAPACITY 3,5 LITRE	P01	INVALID / SALES CODE FOR PRICE
P94	Appearance Package	R02	All season tyres
R39	5 spoke light-alloy wheel 48.3	U10	Front passenger seat with weig
U12	Velour floor mats	U71	DVD-PLAYER WITH REGIONAL-CODE
U80	115 V socket in load area	V59	
182	CONVERTER WITH DEV. CHARACTERI	218	Reversing camera
232	Garage door opener	280	Leather steering wheel
293	Sidebag in rear left and right	299	PRE-SAFE b -System
301	Ashtray package	324	
345	Windscreen wiper with rain sen	359	Teleaid Low Cost
414	Electric sunroof, glass versio	427	7-speed automatic transmission
438	Neck-Pro head restraints, 1st	461	Instrument with mileage readin
470	Tyre press monitoring system,	494	US version
512	COMAND APS with DVD-changer	517	HD - Radio
518	Media Interface including cons	524	Paint protection - preservatio
551	Anti-theft warning system	560	Electrically adjustable front
580	Automatic air conditioning	636	Omission of warning triangle
666	Prod. prot. f. freight pkging	673	High-capacity battery
690	Emergency wheel (mini spare)	691	Blue tint.gl.allr./single-l.sa
720	Roof rails/pre-installation fo	723	EASY-PACK load compartment cov
763	Radio remote control with pani	809	Technical modifications

EXHIBIT 26



VIN: 4JGBF8GE4BA757676 **Owner:** NONE **Engine No:** 27396330438215
FIN: 4JG1648861A757676 **Transmission No:** 72290403398933

Vehicle Info

Model/Year: GL550 2011 **Upholstery:** **Paint:**

Warranty & Sale

Warranty Start: 09/15/2011 **Retail Date:** 09/15/2011 **Selling Dealer:** 51114

Production Info

Radio Code: 12314 **Serial No:** B0587381 **Prod Date:** 06/25/2011

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2022050015	22P4290005	05/27/2022	CLOSED	RECALL
2019030018	19P9194002	03/25/2019	CLOSED	RECALL

EXHIBIT 27



VIN: 4JGBF7BE2AA567293 Owner: NONE Engine No: 27392330333703
FIN: 4JG1648711A567293 Transmission No: 72290402389259

Vehicle Info

Model/Year: GL 450 4MATIC 2010 Upholstery: Paint:

Warranty & Sale

Warranty Start: 12/05/2009 Retail Date: 12/05/2009 Selling Dealer: 05181

Production Info

Radio Code: 41132 Serial No: 90806424 Prod Date: 11/12/2009

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
C1A091101	HUGHES REDIRECT	11/10/2009	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL
2018120012	18P9193103	12/13/2018	CLOSED	RECALL
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
MBCPO	BASE - CPO	11/10/2012	12/04/2014	31680	100000	05181	1834137

Option Codes

Option	Description	Option	Description
-CA		A05	
A21		A22	
A49		A52	
F164		FV	
G904		GA	
HA		J1A	
J58		K15	Factory Code - Maintenance Interval
L		M273	
M46		R02	All Season Tires
R33	20" Twin 5-Spoke Alloy Wheel	R66	Extended Mobility Tires
U10	Weight Sensing System - WSS	U12	Floormats
U38	Chrome Plate (Rear Bumper) Scratch Protection	U71	
U80	115V AC Power Outlet	V71	Tire Rating
VL		VR	
150A		154A	
182		212B	
218	Dynamic Rear View Monitor	220	PARKTRONIC
232	Garage Door Opener	236	Daytime Running Lights
249	Autodimming Mirrors	275	Power Dr.Seat & Steering Col. w/ Memory
280	Leather Str Wheel/Shift Knob	284B	
293	Rear Side Airbags	294	50 State Certification
299	Pre Safe System	301	Ashtray
342B		345	Rain Sensor Wipers
359	Tele Aid	414	Glass Sunroof
427	7-Speed Automatic Transmission	438	Active Front Headrestraints
441	Telescoping Steering Column	461	English Inscriptions
475	Tire-Pressure Monitoring System	489	Air Suspension
494	Emission Equipment	500	Power Folding Mirrors
512	COMAND w/Navigation and Voice Control	517	HD Radio with SIRIUS Satellite Radio and Real Tim



Option	Description	Option	Description
518	iPod/MP3 Media Interface	524	Paint Protection
550	Trailer Hitch	551	Anti-Theft Alarm System
580	Climate Control-Manual	636	Collective Code
650U		666	Transportation Protection Foil
673	Heavy Duty Battery	690	Spare Wheel (Mini)
705L		720	Roof Rail
723	Cargo Cover	731	Burl Walnut Wood Trim
763	Remote Key w/Panic Button	7XXL	
800	2010 Registration Year	840	Privacy Glass
845	Elect.Folding 3rd Row Seat	846	Side Bars
848	Power Rear Quarter Windows	866	Pre-Wiring for Rear Seat Entertainment
873	Heated Front Seats	890	Power Liftgate
900	Exterior Chrome Trim	989	Vin Code

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 91931 03 7	Campaign 2018120012 - Replace Driver-Side Airbag	51201	522600	C	070962148	09/07/2022	09/09/2022	136280	02-KDM (Campaign)	
0 42900 05 8	???	51201	522600	A	070962148	09/07/2022	09/09/2022	136280	02-KDM (Campaign)	
0 74311 H2 7	Door lock /liftgate latch, rear-end door /liftgate Locks up	05749	579003	D	054622029	11/21/2013	11/21/2013	47958	03-Warranty	
0 75101 38 7	Cover, fuel filler flap Loose	05718	616737	1	051940221	09/28/2012	09/28/2012	31076	03-Warranty	
0 59900 02 7	Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	05718	616737	6	051940221	09/28/2012	09/28/2012	31076	02-KDM (Campaign)	
0 33224 36 7	Bearing, front wheel hub Noise	05718	605908	1	051370049	06/07/2012	06/07/2012	26089	03-Warranty	
0 33224 36 7	Bearing, front wheel hub Noise	05718	605908	6	051370049	06/07/2012	06/07/2012	26089	03-Warranty	
1 21606 ZZ 0	Telematics Changeover. By Signing Below, I Terminate My Tele Aid Account	05718	585606	2	050233359	10/20/2011	10/20/2011		RAPS	
0 21607 ZZ 8	Telematics Changeover. By signing below, I terminate my Tele Aid account Special cost settlement	05181	558608	A	047867576	05/21/2010	05/21/2010	5260	03-Warranty	
0 40214 B5 8	Wheel alignment front/rear Pulls to the right	05718	529730	1	047214943	01/21/2010	01/21/2010	1889	03-Warranty	
0 72P21 51 8	Lock striker, front door, right Incorrect setting	05718	529730	2	047214943	01/21/2010	01/21/2010	1889	03-Warranty	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51201	522600	09/07/2022	09/09/2022	0136280	075	I UNDERSTAND THAT MY VEHICLE IS SUBJECT TO A "STOP DRIVE" RECALL AND THAT CONTINUING TO DRIVE MY VEHICLE INVOLVES INHERENT RISKS AND DANGERS OF ACCIDENTS, PROPERTY LOSS OR DAMAGE.


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGBF7BE2AA567293**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51201	522600	09/07/2022	09/09/2022	0136280	097	PERFORM MULTI POINT INSPECTION
05749	626916	05/26/2016	05/27/2016	0083112	020	CHECK, RECORD, AND SET TIRE PRESSURES TO MANUFACTURES SPECS (EXCEPT SPARE AND AFTERMARKET TIRES/WHEELS). TIRE PRESSURES SET TO : L/F R/F R/R L/R
05749	626916	05/26/2016	05/27/2016	0083112	020	PERFORM COMPLIMENTARY CAR WASH.
05749	626916	05/26/2016	05/27/2016	0083112	057	GENERAL ELECTRICAL SYSTEM
05749	626916	05/26/2016	05/27/2016	0083112	073	
05749	626916	05/26/2016	05/27/2016	0083112	A1648203564	TAILLAMP
05749	626916	05/26/2016	05/27/2016	0083112	A1648203664	TAILLAMP
05749	625964	05/10/2016	05/25/2016	0083111	020	CHECK, RECORD, AND SET TIRE PRESSURES TO MANUFACTURES SPECS (EXCEPT SPARE AND AFTERMARKET TIRES/WHEELS). TIRE PRESSURES SET TO : L/F R/F R/R L/R
05749	625964	05/10/2016	05/25/2016	0083111	020	PERFORM COMPLIMENTARY CAR WASH.
05749	625964	05/10/2016	05/25/2016	0083111	020	GENERAL MAINTENANCE
05749	625964	05/10/2016	05/25/2016	0083111	026	CUST REQ SERVICE "B" FOR \$379.95. (\$419.95 FOR V12 EQUIPED VEHICLES.) ADBLUE EXTRA ON DIESEL VEH. DUST FILTER EXTRA IF NEEDED. (DOES NOT INCLUDE \$2.50 HAZARDOUS WASTE FEE OR TAX)
05749	625964	05/10/2016	05/25/2016	0083111	057	GENERAL ELECTRICAL SYSTEM
05749	625964	05/10/2016	05/25/2016	0083111	073	
05749	625964	05/10/2016	05/25/2016	0083111	098	MISC. SHOP CHARGES
05749	625964	05/10/2016	05/25/2016	0083111	099	THE CUSTOMER HAS CHOSEN NOT TO PERFORM THE FOLLOWING RECOMMENDED REPAIRSAT THIS TIME
05749	625964	05/10/2016	05/25/2016	0083111	A0001802609	TS FILTER INSERT
05749	625964	05/10/2016	05/25/2016	0083111	A0009862000 09	WINDSHIELD WASHER FLUID
05749	625964	05/10/2016	05/25/2016	0083111	A0009898301 USB9	MB Genuine Engine Oil 5w-
05749	625964	05/10/2016	05/25/2016	0083111	A0041591803 26	SPARK PLUG
05749	625964	05/10/2016	05/25/2016	0083111	A2731400701	EXCHANGE INTAKE MANIFOLD
05749	625964	05/10/2016	05/25/2016	0083111	A2731410880	GASKET
05749	625964	05/10/2016	05/25/2016	0083111	N0076030314106	SEAL RING,VLRUB
05749	605762	05/01/2015	05/01/2015	0068453	020	CHECK, RECORD, AND SET TIRE PRESSURES TO MANUFACTURES SPECS (EXCEPT SPARE AND AFTERMARKET TIRES/WHEELS). TIRE PRESSURES SET TO : L/F R/F R/R L/R
05749	605762	05/01/2015	05/01/2015	0068453	020	PERFORM COMPLIMENTARY CAR WASH.
05749	605762	05/01/2015	05/01/2015	0068453	020	GENERAL MAINTENANCE
05749	605762	05/01/2015	05/01/2015	0068453	026	CUST REQ SERVICE "B" FOR \$379.95. (\$419.95 FOR V12 EQUIPED VEHICLES.) ADBLUE EXTRA ON DIESEL VEH. DUST FILTER EXTRA IF NEEDED. (DOES NOT INCLUDE \$2.50 HAZARDOUS WASTE FEE OR TAX)
05749	605762	05/01/2015	05/01/2015	0068453	073	
05749	605762	05/01/2015	05/01/2015	0068453	098	MISC. SHOP CHARGES
05749	605762	05/01/2015	05/01/2015	0068453	099	THE CUSTOMER HAS CHOSEN NOT TO PERFORM THE FOLLOWING RECOMMENDED REPAIRSAT THIS TIME
05749	605762	05/01/2015	05/01/2015	0068453	A0001802609	TS FILTER INSERT
05749	605762	05/01/2015	05/01/2015	0068453	A0009898301 USB9	MB Genuine Engine Oil 5w-
05749	605762	05/01/2015	05/01/2015	0068453	A0019868071 17	WINDSHIELD WASHER FLUID
05749	605762	05/01/2015	05/01/2015	0068453	N0076030314106	SEAL RING,VLRUB
05749	579003	11/21/2013	11/22/2013	0047958	020	CHECK, RECORD, AND SET TIRE PRESSURES TO MANUFACTURES SPECS (EXCEPT SPARE AND AFTERMARKET TIRES/WHEELS). TIRE PRESSURES SET TO : L/F R/F R/R L/R
05749	579003	11/21/2013	11/22/2013	0047958	020	PERFORM COMPLIMENTARY CAR WASH.
05749	579003	11/21/2013	11/22/2013	0047958	073	
05749	570124	06/03/2013	06/03/2013	0041469	020	CHECK, RECORD, AND SET TIRE PRESSURES TO MANUFACTURES SPECS (EXCEPT SPARE AND AFTERMARKET TIRES/WHEELS). TIRE PRESSURES SET TO : L/F R/F R/R L/R
05749	570124	06/03/2013	06/03/2013	0041469	020	PERFORM COMPLIMENTARY CAR WASH.
05749	570124	06/03/2013	06/03/2013	0041469	026	CUST REQ SERVICE "B" FOR \$369.95. (\$399.95 FOR V12 EQUIPED VEHICLES.) ADBLUE EXTRA ON DIESEL VEH. DUST FILTER EXTRA IF NEEDED. (DOES NOT INCLUDE \$2.50 HAZARDOUS WASTE FEE OR TAX)
05749	570124	06/03/2013	06/03/2013	0041469	073	
05749	570124	06/03/2013	06/03/2013	0041469	098	MISC. SHOP CHARGES



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
05749	570124	06/03/2013	06/03/2013	0041469	099	THE CUSTOMER HAS CHOSEN NOT TO PERFORM THE FOLLOWING RECOMMENDED REPAIRS AT THIS TIME
05749	570124	06/03/2013	06/03/2013	0041469	A0001802609	TS FILTER INSERT
05749	570124	06/03/2013	06/03/2013	0041469	A0019868071 17	WINDSHIELD WASHER FLUID
05749	570124	06/03/2013	06/03/2013	0041469	BQ1090162	Mobil 1 Formula M 5w40 6/
05749	570124	06/03/2013	06/03/2013	0041469	N007603014106	SEAL RING, VLRUB
05181	609611	11/06/2012	11/06/2012	0031665	007	MOUNT AND BALANCE 2 TIRES
05181	609611	11/06/2012	11/06/2012	0031665	011	Brake Pads, Front (Factory) - Replace
05181	609611	11/06/2012	11/06/2012	0031665	020	Miscellaneous Maintenance - Repair
05181	609611	11/06/2012	11/06/2012	0031665	039	COMPLETE ON-LINE INSPECTION
05181	609611	11/06/2012	11/06/2012	0031665	039	MERCEDES-BENZ OF ESCONDIDO VEHICLE INSPECTION PER ATTACHED LIST THAT
05181	609611	11/06/2012	11/06/2012	0031665	039	CERTIFIED PRE-OWNED MECHANICAL STANDARDS INSPECTION PER CERTIFICATION
05181	609611	11/06/2012	11/06/2012	0031665	072	USED CAR DETAIL
05181	609611	11/06/2012	11/06/2012	0031665	098	*** OPCODE NOT ON REPORT ***
05181	609611	11/06/2012	11/06/2012	0031665	098	LAST MAINTENANCE PERFORMED
05181	609611	11/06/2012	11/06/2012	0031665	098	*** OPCODE NOT ON REPORT ***
05181	609611	11/06/2012	11/06/2012	0031665	098	SUBLET FOR PAINTLESS DENT REPAIR PER ESTIMATE AND PURCHASE ORDER.
05181	609611	11/06/2012	11/06/2012	0031665	098	SUBLET REPAIR BUMPER PER ESTIMATE AND PURCHASE ORDER
05181	609611	11/06/2012	11/06/2012	0031665	098	MISC. SHOP CHARGES
05181	609611	11/06/2012	11/06/2012	0031665	098	SUBLET REPAIRS
05181	609611	11/06/2012	11/06/2012	0031665	A0019899451	BRAKE PASTE
05181	609611	11/06/2012	11/06/2012	0031665	A1644200820	PARTS KIT BRAKE PAD
05181	609611	11/06/2012	11/06/2012	0031665	A1645401017	SENSOR
05181	609611	11/06/2012	11/06/2012	0031665	A1646700101	WINDSHIELD
05181	609611	11/06/2012	11/06/2012	0031665	BQ8400603	GOODYEAR 275/50R20 SKU 70
05718	616737	09/28/2012	10/03/2012	0031076	001	AMG/MOBIL 1 (A)
05718	616737	09/28/2012	10/03/2012	0031076	014	CARB WITH SERVICE
05718	616737	09/28/2012	10/03/2012	0031076	073	MBSD RENTAL CAR
05718	616737	09/28/2012	10/03/2012	0031076	081	CENTRAL LOCKING SYS.
05718	616737	09/28/2012	10/03/2012	0031076	A0001802609	TS FILTER INSERT
05718	616737	09/28/2012	10/03/2012	0031076	A0009892545 12	GASOLINE FUEL ADDITIVES
05718	616737	09/28/2012	10/03/2012	0031076	A0019868071 17	WINDSHIELD WASHER FLUID
05718	616737	09/28/2012	10/03/2012	0031076	BQ1090144	Mobil 1 Formula M 5w40 Bu
05718	605908	06/07/2012	06/07/2012	0026089	020	ECONOMY CAR WASH
05718	605908	06/07/2012	06/07/2012	0026089	039	CARB TIRE PRESSURE
05718	605908	06/07/2012	06/07/2012	0026089	073	MBSD RENTAL CAR
05718	605908	06/07/2012	06/07/2012	0026089	097	MULTI POINT INSPT
05718	585606	10/20/2011	10/20/2011	0019981	001	PENNZOIL (B)
05718	585606	10/20/2011	10/20/2011	0019981	007	ROADFORCE BALANCE 4
05718	585606	10/20/2011	10/20/2011	0019981	012	BRAKE FLUID
05718	585606	10/20/2011	10/20/2011	0019981	016	TUNE-UP:ENGINE ELECT
05718	585606	10/20/2011	10/20/2011	0019981	020	ECONOMY CAR WASH
05718	585606	10/20/2011	10/20/2011	0019981	039	CARB TIRE PRESSURE
05718	585606	10/20/2011	10/20/2011	0019981	073	MBSD RENTAL CAR
05718	585606	10/20/2011	10/20/2011	0019981	A0001802609	TS FILTER INSERT
05718	585606	10/20/2011	10/20/2011	0019981	A0009890807 01	BRAKE FLUID
05718	585606	10/20/2011	10/20/2011	0019981	A0019868071 17	WINDSHIELD WASHER FLUID
05718	585606	10/20/2011	10/20/2011	0019981	A1648300218 64	COMBINATION FILTER
05718	553291	10/13/2010	10/13/2010	0011349	020	N/A
05718	553291	10/13/2010	10/13/2010	0011349	028	N/A
05718	553291	10/13/2010	10/13/2010	0011349	039	N/A
05718	553291	10/13/2010	10/13/2010	0011349	20	ECONOMY CAR WASH
05718	553291	10/13/2010	10/13/2010	0011349	28	SERVICE
05718	553291	10/13/2010	10/13/2010	0011349	39	CARB TIRE PRESSURE
05718	553291	10/13/2010	10/13/2010	0011349	A0001802609	TS FILTER INSERT
05718	553291	10/13/2010	10/13/2010	0011349	A0019868071 17	WINDSHIELD WASHER FLUID
05718	553291	10/13/2010	10/13/2010	0011349	BQ1090144	Mobil 1 Formula M 5w40 Bu
05181	558608	05/21/2010	05/21/2010	0005260	039	N/A
05181	558608	05/21/2010	05/21/2010	0005260	070	N/A
05181	558608	05/21/2010	05/21/2010	0005260	39	VEHICLE WAS IN RECENTLY AND RECEIVED A VEHICLE INSPECTION - PERFORM COURTESY CHECK PER ATTACHED LIST
05181	558608	05/21/2010	05/21/2010	0005260	70	DOORS, TRUNK 2
05747	535944	02/25/2010	02/25/2010	0000010	038	N/A
05747	535944	11/30/2009	11/30/2009	0000010	38	PDI,PERFORM

EXHIBIT 28

Boca Raton, FL
Reference Number: LN_251867.00083-K. FREDERICK



Vehicle History Report™

2010 MERCEDES-BENZ GL-CLASS GL 450 4MATIC

VIN: 4JGBF7BE2AA567293
4 DOOR WAGON/SPORT
UTILITY
4.6L V8 F DOHC 32V
GASOLINE
ALL WHEEL DRIVE

No accidents or damage reported to CARFAX

6 Service history records

6 Previous owners

Types of owners: Lease, Personal

Last owned in New Jersey

162,772 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/18/24 at 10:17:15 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History		Owners 1-4	Owner 5	Owner 6
Not all accidents / issues are reported to CARFAX				
Total Loss No total loss reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.		<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.		<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Mercedes-Benz dealer for any open recalls.		<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported

Basic Warranty	Warranty Expired	Warranty Expired	Warranty Expired
Original warranty estimated to have expired.			

CARFAX Title History	Owners 1-4	Owner 5	Owner 6
CARFAX guarantees the information in this section			
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms			

CARFAX Ownership History	Owners 1-4	Owner 5	Owner 6
The number of owners is estimated			
Year purchased	2009	2019	2022
Type of owner	See Details	Personal	Personal
Estimated length of ownership	9 years	2 yrs. 7 mo.	2 yrs. 5 mo.
Owned in the following states/provinces	See Details	Maryland, New Jersey	New Jersey
Estimated miles driven per year	See Details	7,538/yr	13,086/yr
Last reported odometer reading	110,201	130,726	162,772

CARFAX Detailed History				
 Owner 1 Purchased: 2009		Low mileage! This owner drove less than the industry average of 15,000 miles per year.		Lease Vehicle 11,069 mi/yr
Date	Mileage	Source	Comments	
12/05/2009	61	Dealer Inventory	Vehicle offered for sale	
12/05/2009	67	California Motor Vehicle Dept. San Diego, CA	Odometer reading reported	

12/23/2009	California Motor Vehicle Dept. San Diego, CA	Title issued or updated - First owner reported - Loan or lien reported - Titled or registered as lease vehicle
05/21/2010	Mercedes-Benz of Escondido Escondido, CA 760-233-5160  4.3 / 5.0 595 Verified Reviews  11,534 Customer Favorites	 Vehicle serviced
11/01/2012 31,661	Mercedes-Benz Financial Services California	Lease vehicle returned to dealer
11/01/2012	Mercedes-Benz Certified Pre-Owned Dealer Escondido, CA	Offered for sale as a Mercedes-Benz Certified Pre-Owned Vehicle
	Mercedes-Benz 	
11/06/2012	Mercedes-Benz of Escondido Escondido, CA 760-233-5160  4.3 / 5.0 595 Verified Reviews  11,534 Customer Favorites	 Vehicle serviced - Recommended maintenance performed - Front brake pads replaced - Sensor replaced - Four wheel alignment performed - Two tires mounted - Two tires balanced - Windshield replaced - Tire(s) replaced

 Owner 2 Purchased: 2012		Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 14,021 mi/yr
Date	Mileage	Source	Comments
11/10/2012 31,680	California Motor Vehicle Dept. Carlsbad, CA		Odometer reading reported
11/30/2012	California Motor Vehicle Dept. Carlsbad, CA		Title issued or updated - New owner reported - Loan or lien reported

09/03/2013	California Motor Vehicle Dept. Carlsbad, CA	Registration updated when owner moved the vehicle to a new location
11/28/2016 88,494	Auto Auction	Listed as a dealer vehicle - Vehicle sold
		 <div style="border: 1px solid #ccc; padding: 5px; margin-top: 10px;"> Millions of used vehicles are bought and sold at auction every year. </div>
11/29/2016	Dealer Inventory	Vehicle offered for sale
12/08/2016 88,501	California Inspection Station	Passed emissions inspection

 Owner 3 Purchased: 2016		Personal Vehicle
Date	Mileage	Source
12/17/2016	88,567	California Motor Vehicle Dept. Glendale, CA
12/22/2016		California Motor Vehicle Dept. Glendale, CA
01/29/2017	89,742	Valvoline Instant Oil Change Glendale, CA 818-500-9698  Vehicle serviced - Oil and filter changed  4.7 / 5.0 135 Verified Reviews
09/04/2017	94,796	Vehicle offered for sale
09/04/2017		Vehicle sold
09/08/2017	94,799	Passed emissions inspection
09/12/2017		Title issued or updated - Loan or lien reported
10/03/2017	94,801	Vehicle offered for sale
 Owner 4 Purchased: 2017		Lease Vehicle

Date	Mileage	Source	Comments
11/15/2017		California Motor Vehicle Dept. Sacramento, CA	Title issued or updated - New owner reported - Loan or lien reported
06/07/2018	105,234	Eurotech Automotive Rancho Cordova, CA 916-631-4118  4.9 / 5.0 145 Verified Reviews  421 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Steering/suspension checked
10/31/2018		California Motor Vehicle Dept. Sacramento, CA	Title issued or updated - Loan or lien reported
12/20/2018	110,200	Auto Auction	Vehicle sold
01/23/2019		Michigan Motor Vehicle Dept. Lewisville, TX Title #601H0210031	Title issued or updated - Titled or registered as lease vehicle
02/14/2019	110,201	Auto Auction	 Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another.
 Owner 5 Purchased: 2019		 Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 7,538 mi/yr
Date	Mileage	Source	Comments
06/27/2019	110,807	Maryland Motor Vehicle Dept. Temple Hills, MD Title #51842126	Title or registration issued - New owner reported - Loan or lien reported
08/28/2019	114,686	Magic Benz Services Hyattsville, MD 301-985-2676  4.7 / 5.0 114 Verified Reviews  398 Customer Favorites	 Vehicle serviced - Rear brake pads replaced - Brake pads replaced
10/15/2019		Maryland Inspection Station	Passed emissions inspection

Clinton, MD

10/16/2021	Maryland Inspection Station Clinton, MD	Passed emissions inspection
12/27/2021	Maryland Motor Vehicle Dept. Temple Hills, MD Title #55427495	Title issued or updated - Duplicate title issued - Loan or lien reported
01/31/2022	130,407 Auto Auction	Listed as a dealer vehicle - Vehicle sold
03/17/2022	New Jersey Motor Vehicle Dept. Vineland, NJ	Registration issued or renewed - Vehicle color noted as White
03/18/2022	130,726 Service Plan Co. Vineland, NJ	Service contract issued

**Owner 6**

Purchased: 2022



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
13,086 mi/yr

Date	Mileage	Source	Comments
03/29/2022		New Jersey Motor Vehicle Dept. Vineland, NJ Title #HH20220880009	Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as White
04/05/2022	131,688	New Jersey Inspection Station	Passed emissions inspection
09/09/2022	136,280	Mercedes-Benz of Atlantic City Eagle Harbor Township, NJ 609-645-9000 ⭐ 4.6 / 5.0 117 Verified Reviews ❤️ 2,845 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Brakes checked
01/18/2023		New Jersey Motor Vehicle Dept. Vineland, NJ	Registration issued or renewed - Vehicle color noted as White
02/16/2024		New Jersey Motor Vehicle Dept. Vineland, NJ	Registration issued or renewed - Vehicle color noted as White
06/12/2024	161,516	New Jersey	Passed emissions inspection

Inspection Station

06/15/2024	New Jersey Motor Vehicle Dept. Vineland, NJ	Registration issued or renewed - Vehicle color noted as White
08/19/2024	162,772 New Jersey Motor Vehicle Dept. Millville, NJ Title #DA20242321225	Dealer took registration of this vehicle - Title issued or updated - Dealer took title of this vehicle while it was in inventory - Vehicle color noted as White
09/04/2024	Online Listing	Vehicle offered for sale

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Lease

When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company. The leasing company then collects payments for the vehicle from the new owner for 24, 36, 48 or more months. A leasing company can be an independent car dealer or a car manufacturer.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



[About CARFAX](https://www.carfax.com)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
9/18/24 10:17:15 AM (CDT)

EXHIBIT 29

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBB86E57A294421**

VIN: 4JGBB86E57A294421 **Owner:** NONE **Engine No:** 27296730659931
FIN: 4JG1641861A294421 **Transmission No:** 72290601247229

Vehicle Info

Model/Year: ML350 2007 **Upholstery:** **Paint:**

Warranty & Sale

Warranty Start: 07/27/2007 **Retail Date:** 07/27/2007 **Selling Dealer:** 55109

Production Info

Radio Code: 21314 **Serial No:** 70648510 **Prod Date:** 06/25/2007

Status: 0-NORMAL

Status Need Authorization Mileage Discrepancies Warranty < 30 Days Review History

Informational Status

Status Code	Status Description
S0	SIRIUS AUDIO SERVICE NOT ACTIVATED, CALL 888-465-8528 TO ACTIVATE FOR THE CUSTOMER.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2012070002	1101P59A14	09/06/2012	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	OPEN	RECALL

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	12/31/2999	12/31/2999	0	999999	G3	
WTY EXT	SEAT HEATER WARR EXT	05/16/2018	05/16/2020	0	180000		

Option Codes

Option	Description	Option	Description
-NY		A05	
A21		A39	
H04	Wood Birds Eye Trim	J58	
K12	Factory Code	K14	Factory Code
M35		P01	P1: Premium I
R02	All Season Tires	R44	17" 7-Spoke Wheels
U12	Floormats	V34	Speed and Load Index
167	167 Standard Non-Sport Pkg.	182	
232	Garage Door Opener	280	
293	Rear Side Airbags	301	Ashtray
345	Rain Sensor Wipers	359	TeleAid Digital
389	Phone Prewiring	414	Glass Sunroof
427	7-Speed Automatic Transmission	438	Active Front Headrestraints
461	English Inscriptions	470	Low Tire Pressure Sys
494	Emission Equipment	524	
530	DVD COMAND Navigation	536	SIRIUS Satellite Radio
551	Anti-Theft Alarm System	560	Elect.Adj. Front Seats
580	Climate Control-Manual	636	Collective Code
666	Transportation Protection Foil	673	Heavy Duty Battery
690	Spare Wheel (Mini)	720	Roof Rail
723	Cargo Cover	763	Remote Key w/Panic Button
807	2007 Registration Year	810	Harman/Kardon Sound System
819	6-Disc CD Changer	840	Privacy Glass
846	Side Bars	873	Heated Front Seats
890	Power Liftgate	904	Basic Optics Exterior
989			



Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 59900 02 7	Campaign 2012070002, Retrofit Adapter Wiring Harness on Cam Adjustment Solenoid	14316	277561	C	052981092	02/22/2013	02/22/2013	93351	02-KDM (Campaign)	
0 82283 73 7	Light source, brake light Electrical fault	55109	300073	B	049758560	07/06/2011	07/06/2011	48684	03-Warranty	
0 05A03 73 7	Solenoid, intake camshaft, left Electrical fault	14132	187073	A	049627723	06/10/2011	06/10/2011	47043	03-Warranty	
0 05N04 73 7	Solenoid, exhaust camshaft, right Electrical fault	14132	187073	F	049627723	06/10/2011	06/10/2011	47043	03-Warranty	
1 21606 ZZ 0	Telematics Changeover. By Signing Below, I Terminate My Tele Aid Account	55109	294413	A	049540903	05/19/2011	05/19/2011		RAPS	
0 40002 47 7	Wheel bolt Corroded /oxidized	55109	254029	C	047974765	06/23/2010	06/23/2010	34827	03-Warranty	
0 05N04 73 7	Solenoid, exhaust camshaft, right Electrical fault	55109	253200	A	047949646	06/16/2010	06/16/2010	34652	03-Warranty	
0 82148 52 8	Seat occupancy recognition control unit, weight detection system Does not operate correctly	55109	235131	C	047156533	01/12/2010	01/12/2010	27488	03-Warranty	
0 82380 74 7	Socket, light source, taillamp Contact fault /open circuit	55109	233245	A	047076464	12/23/2009	12/23/2009	26742	03-Warranty	
0 81P18 38 8	Housing, outside mirror, right Loose	55109	180536	A	044590025	09/17/2008	09/17/2008	15066	03-Warranty	
0 51185 74 7	K/Z* Electric motor, outside mirror, folding Contact fault /open circuit	55109	180643	A	044597625	09/17/2008	09/17/2008	15070	03-Warranty	
0 21327 00 8	???	55109	134310	A	042174488	08/24/2007	08/24/2007	1382	03-Warranty	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
14124	197611	12/06/2013	12/16/2013	0117886	025	
14124	197611	12/06/2013	12/16/2013	0117886	039	USED CAR SAFETY INSPECTION
14124	197611	12/06/2013	12/16/2013	0117886	042	INSTALL WIPERS
14124	197611	12/06/2013	12/16/2013	0117886	070	BUMPER-DOC
14124	197611	12/06/2013	12/16/2013	0117886	072	USED CAR FULL DETAIL
14124	197611	12/06/2013	12/16/2013	0117886	098	GENERAL REPAIRS
14124	197611	12/06/2013	12/16/2013	0117886	A0001802609	TS FILTER INSERT
14124	197611	12/06/2013	12/16/2013	0117886	A0009904907	RADIUS SEAT BOLT
14124	197611	12/06/2013	12/16/2013	0117886	A0009982921	COVERING
14124	197611	12/06/2013	12/16/2013	0117886	A0019868071 17	WINDSHIELD WASHER FLUID
14124	197611	12/06/2013	12/16/2013	0117886	A1698201745	WIPER BLADE
14124	197611	12/06/2013	12/16/2013	0117886	A2518200845 64	TS WIPER BLADE
14124	197611	12/06/2013	12/16/2013	0117886	BQ1090144	Mobil 1 Formula M 5w40 Bu
14124	197611	12/06/2013	12/16/2013	0117886	N000000000853	BULB
14124	197611	12/06/2013	12/16/2013	0117886	N000000003598	BULB
14124	197611	12/06/2013	12/16/2013	0117886	N007603014106	SEAL RING_VLRUB



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
14316	317618	11/22/2013	11/22/2013	0116452	058	*** OPCODE NOT ON REPORT ***
14316	317618	11/22/2013	11/22/2013	0116452	097	MPI WORLD CLASS INSPECTION
14316	317618	11/22/2013	11/22/2013	0116452	N40080900000764	BULB
14316	299235	07/29/2013	07/29/2013	0107205	026	B Service
14316	299235	07/29/2013	07/29/2013	0107205	098	*** OPCODE NOT ON REPORT ***
14316	299235	07/29/2013	07/29/2013	0107205	A0001802609	TS FILTER INSERT
14316	299235	07/29/2013	07/29/2013	0107205	A0019868071 17	WINDSHIELD WASHER FLUID
14316	299235	07/29/2013	07/29/2013	0107205	A1110180080	GASKET,OIL FILTER,VLRUB
14316	299235	07/29/2013	07/29/2013	0107205	A1648300218 64	COMBINATION FILTER
14316	299235	07/29/2013	07/29/2013	0107205	A1698201745	WIPER BLADE
14316	299235	07/29/2013	07/29/2013	0107205	A2518200845 64	TS WIPER BLADE
14316	277561	02/22/2013	02/23/2013	0093354	001	C Service
14316	277561	02/22/2013	02/23/2013	0093354	019	*** OPCODE NOT ON REPORT ***
14316	277561	02/22/2013	02/23/2013	0093354	054	Belt, Supercharger - Replace
14316	277561	02/22/2013	02/23/2013	0093354	056	*** OPCODE NOT ON REPORT ***
14316	277561	02/22/2013	02/23/2013	0093354	057	Miscellaneous Body Electrical - Repair
14316	277561	02/22/2013	02/23/2013	0093354	097	MPI WORLD CLASS INSPECTION
14316	277561	02/22/2013	02/23/2013	0093354	098	*** OPCODE NOT ON REPORT ***
14316	277561	02/22/2013	02/23/2013	0093354	098	*** OPCODE NOT ON REPORT ***
14316	277561	02/22/2013	02/23/2013	0093354	A0001802609	TS FILTER INSERT
14316	277561	02/22/2013	02/23/2013	0093354	A0009985690	EXPANSION PLUG
14316	277561	02/22/2013	02/23/2013	0093354	A0009986590	CLOSING COVER
14316	277561	02/22/2013	02/23/2013	0093354	A0019868071 17	WINDSHIELD WASHER FLUID
14316	277561	02/22/2013	02/23/2013	0093354	A0019896803 13	GEAR OIL
14316	277561	02/22/2013	02/23/2013	0093354	A0049903512	SCREW
14316	277561	02/22/2013	02/23/2013	0093354	A1110180080	GASKET,OIL FILTER,VLRUB
14316	277561	02/22/2013	02/23/2013	0093354	A1648300218 64	COMBINATION FILTER
14316	277561	02/22/2013	02/23/2013	0093354	A1698201745	WIPER BLADE
14316	277561	02/22/2013	02/23/2013	0093354	A2202710380	GASKET
14316	277561	02/22/2013	02/23/2013	0093354	A2212770195	OIL FILTER
14316	277561	02/22/2013	02/23/2013	0093354	A2512710097	PIPE
14316	277561	02/22/2013	02/23/2013	0093354	A2518200845 64	TS WIPER BLADE
14316	277561	02/22/2013	02/23/2013	0093354	A2720510177	MAGNET
14316	277561	02/22/2013	02/23/2013	0093354	A2730940404	TS AIR FILTER ELEMENT
14316	277561	02/22/2013	02/23/2013	0093354	BQ8401290	MICHELIN 235/65R17 SKU, 3
14316	277561	02/22/2013	02/23/2013	0093354	N007603012102	RING,GENERAL,METAL
14132	6002420	08/16/2011	08/16/2011	0052198	009	PLEASE CHECK ALIGNMENT, PERFORM 4-WHEEL ALIGNMENT IF NEEDED FOR \$99.95.
14132	6002420	08/16/2011	08/16/2011	0052198	020	COMPLIMENTARY EXTERIOR WASH
14132	6002420	08/16/2011	08/16/2011	0052198	025	PERFORM FLEXIBLE A SERVICE PER MERCEDES-BENZ, INCLUDING ENGINE OIL AND FILTER,RESET FSS REMINDER, B
14132	6002420	08/16/2011	08/16/2011	0052198	098	CUSTOMER STATES
14132	6002420	08/16/2011	08/16/2011	0052198	A0001802609	TS FILTER INSERT
14132	6002420	08/16/2011	08/16/2011	0052198	A0019868071 17	WINDSHIELD WASHER FLUID
14132	6002420	08/16/2011	08/16/2011	0052198	BQ1090135	MOBILE 1 ESP FORMULA MB 5
14132	6002420	08/16/2011	08/16/2011	0052198	N007603014106	SEAL RING,VLRUB
55109	300073	07/06/2011	07/06/2011	0048684	007	MOUNT AND BALANCE ONE (1) TIRE
55109	300073	07/06/2011	07/06/2011	0048684	020	NO PROBLEM FOUND AT THIS TIME
55109	300073	07/06/2011	07/06/2011	0048684	073	LOANER VEHICLE
55109	300073	07/06/2011	07/06/2011	0048684	BQ8400357	TIRE MICH 235/65R17 SKU 3
14132	187073	06/10/2011	06/10/2011	0047043	020	PERFORMED SERVICE OR REPAIRS
14132	187073	06/10/2011	06/10/2011	0047043	020	COMPLIMENTARY EXTERIOR WASH
14132	187073	06/10/2011	06/10/2011	0047043	039	PERFORM COURTESY INSPECTION AT NO CHARGE TO CLIENT
55109	294413	05/19/2011	05/19/2011	0045195	007	MOUNT AND BALANCE ONE (1) TIRE
55109	294413	05/19/2011	05/19/2011	0045195	020	NO PROBLEM FOUND AT THIS TIME
55109	294413	05/19/2011	05/19/2011	0045195	073	LOANER VEHICLE
55109	294413	05/19/2011	05/19/2011	0045195	0Z9	NOT TO BE DONE AT THIS TIME
55109	294413	05/19/2011	05/19/2011	0045195	BQ8400357	TIRE MICH 235/65R17 SKU 3
55109	274913	12/13/2010	12/13/2010	0039372	019	N/A
55109	274913	12/13/2010	12/13/2010	0039372	020	N/A
55109	274913	12/13/2010	12/13/2010	0039372	026	N/A
55109	274913	12/13/2010	12/13/2010	0039372	055	N/A
55109	274913	12/13/2010	12/13/2010	0039372	073	N/A
55109	274913	12/13/2010	12/13/2010	0039372		
55109	274913	12/13/2010	12/13/2010	0039372	A0001802609	TS FILTER INSERT
55109	274913	12/13/2010	12/13/2010	0039372	A0019868071 17	WINDSHIELD WASHER FLUID
55109	274913	12/13/2010	12/13/2010	0039372	A0019896803 10	TRANSMISSION OIL
55109	274913	12/13/2010	12/13/2010	0039372	A1648300218 64	COMBINATION FILTER
55109	274913	12/13/2010	12/13/2010	0039372	A2518200745	WIPER BLADE


**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**
**Dealer : 00030
VIN:4JGBB86E57A294421**

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
55109	274913	12/13/2010	12/13/2010	0039372	BQ1090152	Bulk - Equip. Package # 7
55109	274913	12/13/2010	12/13/2010	0039372	NA	
55109	260036	08/11/2010	08/11/2010	0036551	039	N/A
55109	260036	08/11/2010	08/11/2010	0036551	098	N/A
55109	260036	08/11/2010	08/11/2010	0036551	39	N.Y.STATE LOW ENHANCED INSPECTION IDLE TEST
55109	260036	08/11/2010	08/11/2010	0036551	98	CUSTOMER WAITING
55109	254029	06/23/2010	06/23/2010	0034827	007	N/A
55109	254029	06/23/2010	06/23/2010	0034827	007	N/A
55109	254029	06/23/2010	06/23/2010	0034827	009	N/A
55109	254029	06/23/2010	06/23/2010	0034827	020	N/A
55109	254029	06/23/2010	06/23/2010	0034827	07	MOUNT AND BALANCE ONE (1) TIRE
55109	254029	06/23/2010	06/23/2010	0034827	07	MOUNT TWO (2) TIRES AND BALANCE
55109	254029	06/23/2010	06/23/2010	0034827	073	N/A
55109	254029	06/23/2010	06/23/2010	0034827	09	FOUR WHEEL ALIGNMENT
55109	254029	06/23/2010	06/23/2010	0034827	20	FILL ALL FOUR TIRES WITH >95% PURE NITROGEN, INCLUDES \$200 ROAD HAZARD WAARANTY FOR ONE YEAR /MUST REGISTER AT NITROFILL.COM AT TIME OF PURCHASE/ \$69
55109	254029	06/23/2010	06/23/2010	0034827	73	LOANER VEHICLE
55109	254029	06/23/2010	06/23/2010	0034827	BQ8400357	TIRE MICH 235/65R17 SKU 3
55109	254029	06/23/2010	06/23/2010	0034827	NITRO	
55109	254029	06/23/2010	06/23/2010	0034827	TIRETAX	
55109	254029	06/23/2010	06/23/2010	0034827	WEIGHT	Wheel weight
55109	253200	06/16/2010	06/16/2010	0034651	071	N/A
55109	253200	06/16/2010	06/16/2010	0034651	073	N/A
55109	253200	06/16/2010	06/16/2010	0034651	098	N/A
55109	253200	06/16/2010	06/16/2010	0034651	71	BI-COUNTY WINDSHIELD REPAIR (SUBLET)
55109	253200	06/16/2010	06/16/2010	0034651	73	LOANER VEHICLE
55109	253200	06/16/2010	06/16/2010	0034651	98	*** OPCODE NOT ON REPORT ***
55109	249496	05/18/2010	05/18/2010	0034185	071	N/A
55109	249496	05/18/2010	05/18/2010	0034185	071	N/A
55109	249496	05/18/2010	05/18/2010	0034185	071	N/A
55109	249496	05/18/2010	05/18/2010	0034185	098	N/A
55109	249496	05/18/2010	05/18/2010	0034185	098	N/A
55109	249496	05/18/2010	05/18/2010	0034185	71	REFINISH
55109	249496	05/18/2010	05/18/2010	0034185	71	REPAIR AND REFINISH FRONT DAMAGE
55109	249496	05/18/2010	05/18/2010	0034185	71	REPAIR AND REFINISH REAR DAMAGE
55109	249496	05/18/2010	05/18/2010	0034185	98	*** OPCODE NOT ON REPORT ***
55109	244759	04/07/2010	04/07/2010	0032936	020	N/A
55109	244759	04/07/2010	04/07/2010	0032936	098	N/A
55109	244759	04/07/2010	04/07/2010	0032936	098	N/A
55109	244759	04/07/2010	04/07/2010	0032936	098	N/A
55109	244759	04/07/2010	04/07/2010	0032936	20	COMPLIED WITH CUSTOMERS REQUEST
55109	244759	04/07/2010	04/07/2010	0032936	98	*** OPCODE NOT ON REPORT ***
55109	244759	04/07/2010	04/07/2010	0032936	98	CLEAN AND POLISH VEHICLE FOR DELIVERY
55109	235131	02/26/2010	02/26/2010	0027488	012	N/A
55109	235131	02/26/2010	02/26/2010	0027488	020	N/A
55109	235131	02/26/2010	02/26/2010	0027488	025	N/A
55109	235131	02/26/2010	02/26/2010	0027488	073	N/A
55109	235131	02/26/2010	02/26/2010	0027488	098	N/A
55109	235131	02/26/2010	02/26/2010	0027488	A0001802609	TS FILTER INSERT
55109	235131	02/26/2010	02/26/2010	0027488	A0019868071 17	WINDSHIELD WASHER FLUID
55109	235131	02/26/2010	02/26/2010	0027488	A0019899451	BRAKE PASTE
55109	235131	02/26/2010	02/26/2010	0027488	A0044205220	SET OF BRAKEPADS
55109	235131	02/26/2010	02/26/2010	0027488	A1644200820	PARTS KIT BRAKE PAD
55109	235131	02/26/2010	02/26/2010	0027488	A1645401017	SENSOR
55109	235131	02/26/2010	02/26/2010	0027488	A1645401017	SENSOR
55109	235131	02/26/2010	02/26/2010	0027488	BQ1090152	Bulk - Equip. Package # 7
55109	235131	02/26/2010	02/26/2010	0027488	NA	
55109	233245	02/26/2010	02/26/2010	0026742	098	N/A
55109	233245	02/26/2010	02/26/2010	0026742	098	N/A
55109	235131	01/12/2010	01/12/2010	0027488	12	REPLACE ALL BRAKE PADS
55109	235131	01/12/2010	01/12/2010	0027488	20	MERCEDES
55109	235131	01/12/2010	01/12/2010	0027488	25	FLEX SERVICE "A" - SPECIAL PRICE \$199.99
55109	235131	01/12/2010	01/12/2010	0027488	73	LOANER VEHICLE
55109	235131	01/12/2010	01/12/2010	0027488	98	*** OPCODE NOT ON REPORT ***
55109	235131	01/12/2010	01/12/2010	0027488	A0001802609	TS FILTER INSERT
55109	235131	01/12/2010	01/12/2010	0027488	A0019868071 17	WINDSHIELD WASHER FLUID
55109	235131	01/12/2010	01/12/2010	0027488	A0019899451	BRAKE PASTE
55109	235131	01/12/2010	01/12/2010	0027488	A0044205220	SET OF BRAKEPADS



Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
55109	235131	01/12/2010	01/12/2010	0027488	A1644200820	PARTS KIT BRAKE PAD
55109	235131	01/12/2010	01/12/2010	0027488	A1645401017	SENSOR
55109	235131	01/12/2010	01/12/2010	0027488	BQ1090152	Bulk - Equip. Package # 7
55109	235131	01/12/2010	01/12/2010	0027488	SOLVENT	Solvent
55109	233245	12/23/2009	12/23/2009	0026742	98	CUSTOMER WAITING
55109	233245	12/23/2009	12/23/2009	0026742	98	SET TIRE PRESS.
55109	218147	08/12/2009	08/12/2009	0022548	020	N/A
55109	218147	08/12/2009	08/12/2009	0022548	039	N/A
55109	218147	08/12/2009	08/12/2009	0022548	098	N/A
55109	218147	08/12/2009	08/12/2009	0022548	20	COMPLIED WITH CUSTOMERS REQUEST
55109	218147	08/12/2009	08/12/2009	0022548	39	N.Y.STATE LOW ENHANCED INSPECTION IDLE TEST
55109	218147	08/12/2009	08/12/2009	0022548	98	TIRE CONDITION GREEN, TIRES SAFE
55109	206505	04/30/2009	04/30/2009	0020561	007	N/A
55109	206505	04/30/2009	04/30/2009	0020561	027	N/A
55109	206505	04/30/2009	04/30/2009	0020561	027	N/A
55109	206505	04/30/2009	04/30/2009	0020561	07	ROTATE AND BALANCE FRONT WHEELS
55109	206505	04/30/2009	04/30/2009	0020561	073	N/A
55109	206505	04/30/2009	04/30/2009	0020561	079	N/A
55109	206505	04/30/2009	04/30/2009	0020561	083	N/A
55109	206505	04/30/2009	04/30/2009	0020561	098	N/A
55109	206505	04/30/2009	04/30/2009	0020561	27	FLEX.SERV.PLUS-OIL/FILTER CHANGE, PERF.
55109	206505	04/30/2009	04/30/2009	0020561	27	FLEXIBLE SERVICE PLUS-MAJOR MAINTENANCE
55109	206505	04/30/2009	04/30/2009	0020561	73	LOANER VEHICLE
55109	206505	04/30/2009	04/30/2009	0020561	79	VENTILATION DUST FILTER, R & R / REPL. IF REQ.
55109	206505	04/30/2009	04/30/2009	0020561	83	FLUSH BRAKE FLUID
55109	206505	04/30/2009	04/30/2009	0020561	98	TIRE CONDITION GREEN, TIRES SAFE
55109	206505	04/30/2009	04/30/2009	0020561	A0001802609	TS FILTER INSERT
55109	206505	04/30/2009	04/30/2009	0020561	A0009890807 01	BRAKE FLUID
55109	206505	04/30/2009	04/30/2009	0020561	A0019868071 17	WINDSHIELD WASHER FLUID
55109	206505	04/30/2009	04/30/2009	0020561	A1648300218 64	COMBINATION FILTER
55109	206505	04/30/2009	04/30/2009	0020561	BQ1090144	Mobil 1 Formula M 5w40 Bu
55109	206505	04/30/2009	04/30/2009	0020561	N007603014106	SEAL RING,VLRUB
55109	206505	04/30/2009	04/30/2009	0020561	NA	
55109	206505	04/30/2009	04/30/2009	0020561	SOLVENT	Solvent
55109	180536	09/17/2008	09/17/2008	0015066	73	LOANER VEHICLE
55109	179627	09/08/2008	09/08/2008	0015035	07	MOUNT AND BALANCE ONE (1) TIRE
55109	179627	09/08/2008	09/08/2008	0015035	BQ8400357	TIRE MICH 235/65R17 SKU 3
55109	179627	09/08/2008	09/08/2008	0015035	TIRETAX	
55109	179627	09/08/2008	09/08/2008	0015035	WEIGHT	Wheel weight
55109	177247	08/18/2008	08/18/2008	0014678	39	N.Y.SAFETY INSPECTION FOR NEW, DIESEL & EXEMPT CARS
55109	177247	08/18/2008	08/18/2008	0014678	98	TIRE CONDITION GREEN, TIRES SAFE
55109	162421	04/17/2008	04/17/2008	0009284	07	ROTATE WHEELS AND BALANCE FRONT WHEELS
55109	162421	04/17/2008	04/17/2008	0009284	20	NO PROBLEM FOUND AT THIS TIME
55109	162421	04/17/2008	04/17/2008	0009284	27	FLEX.SERV.PLUS-OIL/FILTER CHANGE, PERF.
55109	162421	04/17/2008	04/17/2008	0009284	27	FLEXIBLE SERVICE PLUS-MINOR MAINTENANCE
55109	162421	04/17/2008	04/17/2008	0009284	98	CUSTOMER WAITING
55109	162421	04/17/2008	04/17/2008	0009284	A0001802609	TS FILTER INSERT
55109	162421	04/17/2008	04/17/2008	0009284	A0019868071 14	WINDSHIELD WASHER FLUID
55109	162421	04/17/2008	04/17/2008	0009284	BQ1090015	MOBIL 1 OIL, 0W40, 1 CASE
55109	162421	04/17/2008	04/17/2008	0009284	N007603014106	SEAL RING,VLRUB
55109	162421	04/17/2008	04/17/2008	0009284	SOLVENT	Solvent
55109	162421	04/17/2008	04/17/2008	0009284	WEIGHT	Wheel weight

EXHIBIT 30



VIN: 4JGBB72E58A328603 **Owner:** NONE **Engine No:** 27396330181865
FIN: 4JG1641721A328603 **Transmission No:** 72290401375576

Vehicle Info

Model/Year: ML550 2008 **Upholstery:** **Paint:**

Warranty & Sale

Warranty Start: 12/03/2008 **Retail Date:** 12/03/2008 **Selling Dealer:** 51147

Production Info

Radio Code: 31114 **Serial No:** 70815145 **Prod Date:** 09/19/2007

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
S6	SIRIUS TRAFFIC SERVICE NOT ACTIVATED, CALL 888-465-8528 TO ACTIVATE FOR THE CUSTOMER.
65	Vehicle eligible for extended emissions coverage based on the retail state. If an emission part is listed in the Serv & Warr booklet and shows not covered, open a OneTrac case.

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2022050015	22P4290005	05/27/2022	OPEN	RECALL
2008110009	0807P54A67	11/21/2008	CLOSED	SERVICE
2008050004	0805P31A42	06/04/2008	CLOSED	RECALL
2012070002	1101P59A14	09/06/2012	CLOSED-NA	SERVICE

Service Packages

Type	Description	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
SIRI A	SIRI A	12/31/2008	07/01/2009	0	999999	G3	
WTY EXT	UPSTREAM OXYGEN SENSOR	12/03/2008	12/02/2018	0	UNLM	N/A	

Option Codes

Option	Description	Option	Description
-NJ		A05	
A21		A22	
A38		A44	
A49		J58	
K14		M55	
P02		R02	
U10		U12	
U40		V59	
057		218	
232		242	
249		267	
275		280	
293		301	
321		324	
345		359	
389		414	
427		438	
441		461	
470		494	
500		519	
524		530	
536		550	
551		580	
600		615	
619		636	



Option	Description	Option	Description
666		673	
690		691	
720		723	
731		763	
772		787	
808		810	
819		840	
846		873	
890		900	
951		989	

Damage History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	RO Open Date	RO Close Date	Miles	Service Type Desc	Seq No
0 82380 74 7	Socket, light source, taillamp Contact fault /open circuit	51147	284183	E	050396343	11/15/2011	11/15/2011	26371	03-Warranty	
0 82490 73 7	Contact switch, closing assist, rear-end door /liftgate Electrical fault	51147	284183	C	050396343	11/15/2011	11/15/2011	26371	03-Warranty	
0 32211 36 7	Front torsion bar linkage /plate Noise	51147	284183	D	050396343	11/15/2011	11/15/2011	26371	03-Warranty	
0 01332 04 7	Cover, front, cylinder head Leaks	51147	284183	B	050469592	11/15/2011	11/15/2011	26371	03-Warranty	
1 21402 00 0	ROADSIDE-JUMP START - (DAY-TIME)	51147	254300	A	046862871	11/15/2009	11/15/2009		RAPS	
0 81B01 H2 8	Outside mirror, left Locks up	51147	243890	B	045615566	03/09/2009	03/09/2009	1840	03-Warranty	
0 21327 00 7	???	51147	243890	A	045615566	03/09/2009	03/09/2009	1840	03-Warranty	
0 54951 41 8	Campaign 2008 110009, Update rear SAM software	51147	219609	B	045062260	12/03/2008	12/03/2008	163	02-KDM (Campaign)	
0 31900 32 7	Campaign 2008 050004, Weld trailer hitch, model 164	51147	231815	A	044031246	06/11/2008	06/11/2008	15	02-KDM (Campaign)	

Customer Pay Data

Dealer Code	RO Number	Repair Open Date	Repair Close Date	RO Mileage	OP Code/Part #	Description
51147	284183	11/15/2011	11/15/2011	0026371	073	MERCEDES LOANER CAR & CAR WASH PROVIDED TO OWNER AT NO CHARGE (\$60.00 VALUE).
51147	219609	12/03/2008	12/03/2008	0000162	20	GROUP 82 - NO OPERATION NO. AND TIME GIVEN USE ACTUAL TIME (PUNCH CARD) WITH 82-0000/01 AS OPERATION NO.

EXHIBIT 31

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGCB2FE0BA127152									
320041	9/4/2015						System		REPLACE D*EGR VALVE, REASSEMBLED WITH NEW SEALS. REMOVED CHARGE AIR PIPE FROM RIGHT SIDE OF INTER COOLER, REMOVED EGR TUBE FROM EGR COOLER, *AND CLEANED CARBON FROM ORIFICE. CLEARED STORED FAULTS AND PERFORMED ROAD TEST, VERIFIED REPAIRS.
361232	5/18/2017	62293637	84116	1442973	NOx sensor--- Electrical fault	14	Exhaust Manifold, Engine Brake, Emission Control System	67,055	CLIENT STATES THE CHECK ENGINE LIGHT IS ON. CHECK AND ADVISE; F; 67055 UPSTREAM NOX SENSOR IS FAULTY 0 VERIFIED COMPLAINT CONNECTED A BATTERY CHARGER AND SDS THEN RAN A SHORT TEST AND FOUND CODE 106100 THE UPPER LIMIT VALUE FOR LONG-TERM ADAPTATION OF THE SCR
678176	7/21/2022	70811958	44102	4290005	UNDEFINED---	42	Brakes	97,878	CUST. STATES RECALL # 2022050015; ; 97221 PERFORMED BRAKE BOOSTER RECALL PER MERCEDES INSTRUCTIONS. NO REPAIR NEEDED AT THIS TIME. S UBMITTED PHOTO WITH VIN
		70811958	44102	4992015	"Campaign 2020050024, Emissions Modification---	49	Exhaust System	97,878	CUST. STATES RECALL # 2020050024; ; 97878 PERFORMED DIESEL EMISSIONS MODIFICATION PER MERCEDES INSTRUCTIONS
		70811958	44102	9194002	Campaign 2019030018 - Replace Driver- Side Airbag---	91	Seats, Bunks, Restraint Systems	97,878	CUST. STATES RECALL # 2019030018; ID 27EEBE; 97221 PERFORMED DRIVERS SIDE AIR BAG RECALL PER MERCEDES INSTRUCTIONS. SCANNED VIN, OLD P ART AND NEW PART. SUBMITTED THROUGH PARTS SCAN. REFERENCE NUMBER 27EEBE

EXHIBIT 32

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGCB2FE0BA127152**

VIN: 4JGCB2FE0BA127152 **Owner:** NONE **Engine No:** 64287041085205
FIN: 4JG2511251A127152 **Transmission No:** 72290203152563

Vehicle Info

Model/Year: R350BTC 2011 **Upholstery:** 151 **Paint:** 040

Warranty & Sale

Warranty Start: 07/29/2011 **Retail Date:** 07/29/2011 **Selling Dealer:** 51121

Production Info

Radio Code: 14134 **Serial No:** A0903475 **Prod Date:** 02/11/2011

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state
63	Vehicle has Extended Emission Modification Warranty Coverage, damage code 4901M 01 to be used for claiming (Status R & 9 included)

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2011110002	1109P47B82	11/22/2011	CLOSED	RECALL
2012070004	1204P54A82	08/02/2012	CLOSED	SERVICE
2019030018	19P9194002	03/25/2019	CLOSED	RECALL
2020050024	19P4992015	01/12/2022	CLOSED	SERVICE
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages


Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
WTY EXT	BLUETEC UPDATE 2 - 4901M 01	07/21/2022	07/21/2026	0097878	0145878	44102	
WTY EXT	BLUETEC UPDATE 1 - 4901M 01	07/21/2022	07/29/2021	0000000	0120000	44102	

Option Codes

Option	Description	Option	Description
-NJ	Wholesale state NJ	A05	
A21		A22	
A49		A52	
A89		B12	Tyre-change tool kit
FV	SEDAN ELONGATED	F25	
GA	AUTOMATIC TRANSMISSION	G90	
HA	REAR AXLE	J52	
K15		K22	SOFTWARE CONTROL F.LOW BEAM LI
L	L.H.D	M01	
M30	DISPLACEMENT 3.0 LITRE	M64	
NC0		O12	
PPM		P01	INVALID / SALES CODE FOR PRICE
R02	All season tyres	R39	5 spoke light-alloy wheel 48.3
R66	Run-flat tyres (MOExtended)	U10	Front passenger seat with weig
U12	Velour floor mats	U41	Fuel/water separator and lubri
U42	Addition to BLUETEC	U71	DVD-PLAYER WITH REGIONAL-CODE
U80	115 V socket in load area	VL	FRONT AXLE HALF SHAFT, LEFT
VR	FRONT AXLE HALF SHAFT, RIGHT	V59	
030		040	Black
040	Black	060	
130		150	R.H.D.
150	R.H.D.	151	Black ARTICO man-made leather

EXHIBIT 33

Vehicle History Detail



RO #	Repair Date	Claim #	Dlr	Dmg Code	Description	Dmg Group	Description	Miles	Dealer Text
VIN: 4JGBF7BE8CA770773					MY 2012	GL Class	Series 164	GL450	
					Driver-Side Airbag---	Systems			
63471	7/14/2022	70699319	51146	4290005	UNDEFINED---	42	Brakes	86,362	Open Campaign 2022050015 - 22P4290005; the function of the brake booster might be affected due to advanced corrosion in the joint area of its housing. After extended time in the field and in conjunction with prolonged water exposure, this corrosion might lead to a vacuum leak at the brake booster. If this were to occur, the brake force support might be reduced, leading to an increase in the brake pedal forces required to decelerate the vehicle, and/or increased stopping distances. Additionally, in rare cases of very severe corrosion, it might be possible for a particularly strong or hard brake application to cause mechanical damage in the brake booster, whereby the connection between brake pedal and brake system would fail. In such a very rare case, it would not be possible to accelerate the vehicle via the brake pedal. The risk of a crash or injury would be increased. The function of the parking brake is not affected by this issue. Before the issue occurs, the driver might notice a change in the brake pedal feel and/or hissing/airflow noises when applying the brake pedal. MBUSA will conduct a voluntary recall DC 42900057; performed recall by inspecting rubberband and found no rust points on the band. From there recall is done and passed no further testing required. put a white mark on booster and took picture of rubber band next to the VIN

EXHIBIT 34

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY****Dealer : 00030
VIN:4JGBF7BE8CA770773**

VIN: 4JGBF7BE8CA770773 **Owner:** NONE **Engine No:** 27392330445088
FIN: 4JG1648711A770773 **Transmission No:** 72290403584589

Vehicle Info

Model/Year: GL450 2012 **Upholstery:** 151 **Paint:** 040

Warranty & Sale

Warranty Start: 11/30/2011 **Retail Date:** 11/30/2011 **Selling Dealer:** 56113

Production Info

Radio Code: 35413 **Serial No:** B0995040 **Prod Date:** 10/03/2011

Status: 0-NORMAL

[Status Need Authorization](#) [Mileage Discrepancies](#) [Warranty < 30 Days](#) [Review History](#)

Informational Status

Status Code	Status Description
65	Vehicle eligible for extended emissions coverage based on the retail state

Campaigns/C1 Action

No	Brief Desc	Start Date	Status	Campaign Type
2013040001	1211P54C34	04/18/2013	CLOSED	SERVICE
2019030018	19P9194002	03/25/2019	CLOSED	RECALL
2022050015	22P4290005	05/27/2022	CLOSED	RECALL

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #
MBCPO	BASE - CPO	08/30/2014	11/29/2016	0032799	0999999	67116	2504599
MNT	PPMSU-2 Services - 2 Service Used Car PPM (For 200	08/30/2014	08/29/2019	0032799	0999000	67116	2500617
MNT	STAR MNT30K PPMS-3YR - 30,000 MILE PREPAID MAINTEN	11/30/2011	08/29/2014	0000012	0129999	56113	1602319

Option Codes

Option	Description	Option	Description
-NY	Wholesale state NY	A05	
A21		A22	
A49		A52	
A89		B12	Tyre-change tool kit
FV	SEDAN ELONGATED	GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE	J1A	
J58	CONTROL CODE	K15	
L	L.H.D	M46	CAPACITY 4,6 LITRE
R02	All season tyres	R33	5-twin-spoke light-alloy wheel
R66	Run-flat tyres (MOExtended)	U10	Front passenger seat with weig
U12	Velour floor mats	U38	Bumpers with scratch guard
U71	DVD-PLAYER WITH REGIONAL-CODE	U80	115 V socket in load area
VL	FRONT AXLE HALF SHAFT, LEFT	VR	FRONT AXLE HALF SHAFT, RIGHT
V71		040	Black
150	R.H.D.	151	Black ARTICO man-made leather
218	Reversing camera	220	PARKTRONIC system (PTS)
232	Garage door opener	234	Blind Spot Assist
240	LED-daytime running lights	242	Front seat right, electr.adjust
249	Automatically dimming ext. and	275	Memory package el.adjust.drive
280	Leather steering wheel	293	Sidebag in rear left and right
294	Kneebag driver's side	299	PRE-SAFE b -System
301	Ashtray package	345	Windscreen wiper with rain sen
359	Teleaid Low Cost	414	Electric sunroof, glass versio

EXHIBIT 35



Service and Warranty Information 2011



Mercedes-Benz

QUICK REFERENCE TO WARRANTY COVERAGE

(Complete warranty coverage starts on (► Page 11)

BASIC WARRANTY	4 Years/50,000 Miles
TIRES, WHEEL ALIGNMENT AND BALANCING, BRAKE DISCS AND PADS, GLASS, WIPER BLADES AND INSERTS	1 Year/12,000 Miles
EMISSION PERFORMANCE/CONTROL (Federal)	2 Years/24,000 Miles
EMISSION PERFORMANCE/CONTROL (Federal)	8 Years/80,000 Miles (Limited Coverage - please refer to text)
ELECTRO-HYDRAULIC BRAKE SYSTEM (SL-Class only)	10 Years/Unlimited Miles (Limited Coverage - please refer to text)
EMISSION PERFORMANCE (California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington)	3 Years/50,000 Miles
EMISSION CONTROL (California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington)	7 Years/70,000 Miles (Limited Coverage - please refer to text)
EMISSION PERFORMANCE Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only (Oregon, Pennsylvania and Washington)	3 Years/50,000 Miles
EMISSION CONTROL Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only (Oregon, Pennsylvania and Washington)	7 Years/70,000 Miles (Limited Coverage - please refer to text)
EMISSION PERFORMANCE/CONTROL Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only (California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island and Vermont)	15 Years/150,000 Miles (Limited Coverage - please refer to text)
EMISSION PERFORMANCE/CONTROL High Voltage Battery - S400 HYBRID Only (California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island and Vermont)	10 Years/150,000 Miles

Dear Mercedes-Benz Owner:

As an authorized Mercedes-Benz Center, we are dedicated to providing you with unparalleled Commitment to Excellence in Sales and Service.

We will always do everything possible to live up to this commitment.

Authorized Mercedes-Benz Center's Signature and Stamp

Authorized Mercedes-Benz Center Information

Name: _____

Address: _____

City, State, ZIP Code: _____

Sales Department Hours: _____

Telephone: _____ Fax: _____ E-mail: _____

Service Department Hours: _____

Telephone: _____ Fax: _____ E-mail: _____

Parts Department Hours: _____

Telephone: _____ Fax: _____ E-mail: _____

Additional Customer Assistance/Services: _____

Vehicle Warranty Information

Model _____

Serial Number _____

VIN _____

Owner _____

Address _____

City/State/ZIP _____

European Delivery

Domestic Delivery

Delivery/Warranty: Mo. _____ Day _____ Yr. _____

Selling authorized Mercedes-Benz Center Code: _____

LIMITED WARRANTY TERMS: The first to occur of 4 Years or 50,000 miles from date of delivery or when put into service. (See details starting on (▷ Page 11) of this booklet.)

OTHER: _____

Owner's Signature

New Vehicle Systems Checkout Inspection/Delivery

NEW VEHICLE PRE-DELIVERY INSPECTION PERFORMED

Month _____ Day _____ Year _____

Service Manager's Signature

Delivery and Owner Instructions

Owner instructed in operation of vehicle per Mercedes-Benz
New Vehicle Delivery Program

Service and Warranty Information Booklet, Operator Manuals
and Maintenance Booklet reviewed with owner

Owner introduced to Service Department Staff

Owner instructed on:

- Maintenance Schedule
- Tire Rotation
- mbrace
- Roadside Assistance

Mercedes-Benz Sales Representative's Signature

To the Owner	6
New Vehicle Limited Warranty	11
Emission Control System Maintenance	20
Emission Systems Warranty (Federal)	21
Emission Performance Warranty (Federal).....	23
Warranted Emission Related Components - Gasoline or Flexible Fuel Engine.....	28
Warranted Emission Related Components - BlueTEC Diesel Engine with DEF	30
Emission Control System Warranty	
(CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)	32
Notice of Address Change or Pre-Owned Vehicle Purchase	Centerfold
Defect Warranty Coverage - Gasoline or Flexible Fuel Engine	
(CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)	40
Defect Warranty Coverage - BlueTEC Diesel Engine with DEF	
(CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)	44
Defect Warranty Coverage - PZEV (OR, PA and WA)	45
Emission Control System Warranty PZEV and S400 HYBRID	
(CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT)......	46
Warranty Emission Related Components PZEV and S400 HYBRID	54
Warranty Enforcement Laws (Lemon Laws).....	56
Important Notice for CA Retail Buyers and Lessees of Mercedes-Benz Vehicles.	59
Questions, Loss of Warranty Booklet, Address Change.....	60
To Purchasers of Pre-Owned Mercedes-Benz Vehicles	61

To the Owner

General

The subsequent pages of this Service and Warranty Information booklet describe some service requirements and the warranties you receive as a Mercedes-Benz owner.

Your vehicle is covered under the terms of these "Warranties" and your authorized Mercedes-Benz Center will exchange or repair any defective parts in accordance with the terms of such warranties within stated limits.

Please keep this booklet together with the Operator's Manual, Maintenance Booklet and other documents concerning your vehicle so that future owners will have access to this literature if you should sell the vehicle.

See (▷ Page 64) for a list of models covered in this edition.

Replacement Parts for Your Mercedes-Benz

Genuine Mercedes-Benz parts, exchange units and factory approved accessories are the recommended replacement parts for your Mercedes-Benz vehicle and are available through your authorized Mercedes-Benz Center.

These parts meet the same exacting quality control standards as the original equipment on your vehicle and comply with all applicable Federal and State safety regulations.

Consult your authorized Mercedes-Benz Center for warranty and other details. Also ask your Center about exchange parts under the Mercedes-Benz Exchange Program. These parts cost less than new parts but carry the same warranty terms.



As a MERCEDES-BENZ OWNER you deserve service unparalleled in the industry.

To meet your service needs, your authorized Mercedes-Benz Center employs a specially factory trained staff using the latest diagnostic and service techniques. Whether it is a small adjustment or major service, your authorized Mercedes-Benz Center will work to accommodate you quickly and efficiently.

Finally, should you ever experience an emergency repair situation, our 24-Hour Roadside Assistance Program is only a toll free call away. (1-800-FOR-MERCedes)

Notes

***THANK YOU... for the confidence you have placed in us.
We will always do everything possible
to continue to earn your trust and goodwill.***



Limited Warranty - 2011 Registration Year Vehicles

Items Which Are Covered:

DEFECTS: Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a new Mercedes-Benz vehicle that any authorized Mercedes-Benz Center will make any repairs or replacements necessary, to correct defects in material or workmanship arising during the warranty period.

ANY AUTHORIZED MERCEDES-BENZ CENTER: Any authorized Mercedes-Benz Center of the owner's choice will perform warranty repairs or replacements. The vehicle should be delivered to an authorized Mercedes-Benz Center during normal service hours. A reasonable time should be allowed after taking the vehicle to an authorized Mercedes-Benz Center for performance of the repair.

WARRANTY PERIOD: This warranty is for 48 months or 50,000 miles, whichever occurs first.

WARRANTY STARTS: The warranty period starts on the date the vehicle is delivered to the first retail purchaser or put in service as an authorized Mercedes-Benz Center demonstrator or Mercedes-Benz USA, LLC (MBUSA) or Mercedes-Benz U.S. International, Inc. (MBUSI) or Mercedes-Benz Research & Development North America, Inc. (MBRDNA) company vehicle.

WHEEL ALIGNMENT AND BALANCING: Wheel alignment and wheel balancing as a result of a manufacturing defect are covered during the first 12 months or 12,000 miles, whichever occurs first, and will be performed by any authorized Mercedes-Benz Center. (▷ Page 14)

TIRES: The tires supplied on your vehicle are covered against defects in material or workmanship for the period of 12 months and/or 12,000 miles from date of delivery or when the vehicle was put in service.

Should the tire become unserviceable for either of the above reasons, the tire will be replaced free of charge, including mounting and balancing, provided 1.6 mm of tread depth remains over the entire tread surface. (▷ Page 14)

The tire manufacturer's warranty coverage may extend beyond the Mercedes-Benz coverage. See tire manufacturer's warranty booklet in the owner's literature package or consult with the tire manufacturer's dealer for specific details.

Tire rotations, if applicable to your vehicle's tire configuration, are a required maintenance service. Not performing tire rotations may void the Mercedes-Benz tire warranty coverage.

Limited Warranty - 2011 Registration Year Vehicles

Items Which Are Covered: (cont'd)

BRAKE PADS AND DISCS: Brake pads and discs are covered against defects in material or workmanship for 12 months or 12,000 miles, whichever occurs first.

(▷ Page 14)

GLASS: Glass is warranted against stress cracks for 12 months or 12,000 miles, whichever occurs first. (▷ Page 15)

WIPER BLADES AND INSERTS: Wiper blades and wiper blade inserts are covered against defects in material or workmanship for 12 months or 12,000 miles, whichever occurs first. (▷ Page 14)

PORTABLE/REMOVABLE ELECTRONIC DEVICES: Original and replacement Mercedes-Benz mobile phone handsets, cradles, Bluetooth® adaptors, and batteries are covered for 12 months from the date of purchase or replacement.

NO CHARGE: Warranty repairs will be made at no charge for parts and labor.

WARRANTY AVAILABLE: This warranty is applicable only in the United States and Puerto Rico. If you take your vehicle to Canada temporarily, such as on vacation, warranty service may be requested from any authorized Mercedes-Benz Center.

In all other countries defects in material and workmanship will be handled in accordance with the terms and limitations of a Limited Warranty of 24 months with unlimited miles.

Limited Warranty - 2011 Registration Year Vehicles

This warranty gives you specific legal rights and you may also have other rights which vary from state to state.

EXCEPT FOR THE EMISSION SYSTEMS WARRANTIES, THIS IS THE ONLY WARRANTY GIVEN WITH THE PURCHASE OF A MERCEDES-BENZ VEHICLE. THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE LIMITED TO THE FIRST TO OCCUR OF 48 MONTHS OR 50,000 MILES FROM THE DATE OF INITIAL OPERATION OR ITS RETAIL DELIVERY, WHICHEVER EVENT SHALL FIRST OCCUR. DAIMLER AG, MERCEDES-BENZ USA, LLC, MERCEDES-BENZ U.S. INTERNATIONAL, INC, MERCEDES-BENZ RESEARCH & DEVELOPMENT NORTH AMERICA, INC. OR THE AUTHORIZED MERCEDES-BENZ CENTER NEITHER ASSUME NOR AUTHORIZE ANY PERSON TO ASSUME FOR THEM ANY OTHER LIABILITY IN CONNECTION WITH SUCH VEHICLE. NO PAYMENT OR OTHER COMPENSATION WILL BE MADE FOR INDIRECT OR CONSEQUENTIAL DAMAGE SUCH AS DAMAGE OR INJURY TO PERSON OR PROPERTY OR LOSS OF REVENUE WHICH MIGHT BE PAID, INCURRED OR SUSTAINED BY REASON OF THE FAILURE OF ANY PART OR ASSEMBLY WHICH MAY BE REPAIRED OR REPLACED IN ACCORDANCE WITH THE TERMS OF THIS WARRANTY.

Some states do not allow the exclusion or limitation of incidental or consequential damages or limitation on how long an implied warranty lasts, so the above limitation may not apply to you.

Limited Warranty - 2011 Registration Year Vehicles

Items Which Are Not Covered:

TIRE DAMAGE: Damage to the tires such as punctures, cuts, snags, bruises, impact damage and breaks resulting from pothole impact, curb impact or from other objects, are not covered. Damage from incorrect inflation, excessive axle load, high speed spinning (when stuck in ice, mud or snow), tire chains, racing or competitive driving events, incorrect mounting or demounting, improper puncture repair, misuse, negligence, alteration and misapplication, are not covered. Rapid or irregular tread wear due to lack of tire rotation according to the recommended intervals specified in your vehicle's maintenance booklet or incorrect wheel alignment or tire balance is not covered. Tread wear out is also not covered.

WHEEL ALIGNMENT: Adjustments for road crown issues are not covered.

BRAKE PADS AND DISCS: Replacement due to normal wear or as part of regular maintenance is not covered.

WIPER BLADES AND INSERTS: Damaged or worn wiper blades and wiper blade inserts are not covered.

DAMAGE DUE TO ACCIDENTS, MISUSE OR NEGLIGENCE: Accidents or damage from objects striking the vehicle. Misuse of the vehicle such as driving over curbs, over-loading, improper operation, storage or transport (Proper use is described in the Operator's Manual).

DAMAGE DUE TO LACK OF MAINTENANCE: Lack of proper maintenance as described in the Maintenance Booklet. Use of service parts or fluids, such as paper oil filters or improper engine oil, which are non-approved by MBUSA, will cause engine damage not covered by the warranty.

NORMAL MAINTENANCE IS OWNER'S RESPONSIBILITY: Cleaning and polishing, lubrication and filters, engine tune-up, replacing worn wiper blades, wiper rubber inserts, brake pads and discs, and clutch discs and pressure plates are some of the normal maintenance services required and are not covered by this warranty.

See Maintenance Booklet for details.

Damage caused by the use of improper filters (including oil filters), engine oils, fluids, cleaners, polishes, or waxes is not covered. Original equipment remote control key batteries are covered for the first 90 days from the vehicle warranty start date.

Limited Warranty - 2011 Registration Year Vehicles

Items Which Are Not Covered: (cont'd)

DAMAGE DUE TO ALTERATIONS: Alterations by changing or adding to the vehicle can adversely affect its performance, reliability and longevity and are not covered by this warranty.

DAMAGE CAUSED BY REPAIR PARTS: Malfunctions caused by the use of other than Genuine Mercedes-Benz parts and accessories and damages or malfunctions resulting from poor fuel quality or from blending additional fuel additives other than those expressly approved for use in exceptional circumstances (see vehicle operator's manual) by MBUSA are not covered.

DAMAGE CAUSED BY IMPROPER BODY REPAIRS: Damage or malfunctions caused by body repairs not performed in accordance with Mercedes-Benz specified repair procedures or otherwise improperly performed are not covered by this warranty.

ALTERED ODOMETER: No warranty coverage shall apply to any vehicle on which the odometer has been altered and the actual mileage cannot be determined.

DAMAGE FROM THE ENVIRONMENT: Parts made from cloth or leather (upholstery, convertible tops, trim items), wood, paint or chrome which have been affected by airborne fallout, such as chemical and tree sap, or by road salt, hail, windstorm or other environmental factors are not covered by this warranty.

DAMAGE TO GLASS: Glass breakage or scratches are not covered unless positive physical proof of a manufacturing defect can be established.

EXTRA EXPENSES: This warranty does not cover payment for loss of use of the vehicle during warranty repairs nor lodging bills, substitute transportation rentals, or other travel costs, telephone calls, loss of pay, or other economic loss or consequential damages.

CHANGES IN DESIGN: The manufacturer has reserved the right to make any changes in design or to make additions to, or upon its products without incurring any obligations to install the same equipment on motor vehicles previously built.

RACING OR COMPETITIVE EVENTS: Your limited warranties do not cover the costs of repairing damage or conditions caused by racing, nor do they cover the repair of any defects that are found as the result of participating in a racing event.

Mercedes-Benz New Vehicle Limited Warranty - Things You Should Know

General

Our intention is to repair under warranty, without charge to you, anything that goes wrong with your vehicle during the warranty period which is our fault. All we ask is that you properly maintain and care for the vehicle and that you have warranty repairs performed by an authorized Mercedes-Benz Center.

Please note the difference between "defects" and "damage" as used in the warranty. Defects are covered since we, the distributor are responsible. Conversely, we have no control over damage caused by such things as, but not limited to collision, misuse, and lack of or improper maintenance. Therefore, damage for whatever reason is not covered by the warranty.

It is the owner's responsibility to maintain the vehicle according to the Maintenance Schedule provided. All maintenance services must be accomplished to keep your warranty coverage valid. When requesting service or repair work under warranty, the owner must present to the authorized Mercedes-Benz Center evidence that the periodic servicing requirements have been accomplished. Receipts covering completion of required servicing should be retained in the event a question arises concerning maintenance.

These receipts should be transferred to each subsequent owner of the vehicle. For your convenience, the Maintenance Booklet has been designed to incorporate the signature of your authorized Mercedes-Benz Center upon completion of the required maintenance services.

This signature is evidence of completion of the maintenance services and should be kept together with other receipts, repair orders and invoices.

If the owner has a warranty claim and can show through received invoices that the vehicle has received the required servicing, the authorized Mercedes-Benz Center will perform the warranty work without charging for parts and labor. It is the responsibility of the owner to prove and the authorized Mercedes-Benz Center to judge whether the required maintenance service has been performed.

MBUSA's obligation is limited to the authorization to exchange or repair at its option such parts which are acknowledged by it to be defective. In case of defective assemblies, factory rebuilt units can be used in exchange instead of their repair. The replaced defective parts or assemblies shall become the property of MBUSA. Warranty repairs do not constitute an extension of the original warranty period for the vehicle or a part thereof.

Mercedes-Benz New Vehicle Limited Warranty - Things You Should Know

Insurance Write-Off; or Repaired or Replaced Parts

Any vehicle which has been damaged to such an extent that the owner, insurer, financing institution or leasing company determined the vehicle to be a "total loss", "write off" or equivalent, is not covered by this warranty. This includes but is not limited to vehicles issued a "salvage", "scrap", "dismantled" or similar title under any state's law.

Any parts repaired or replaced under an insurance claim or required as a result of events which are not covered under this warranty (see "Items Which Are Not Covered", (▷ Page 14), for example, damages due to accidents, misuse, or negligence, and in either case, any subsequent consequential damage to the vehicle are not covered by this warranty.

Paint and Other Appearance Items

Defects in paint, trim or other appearance items are normally taken care of during our new vehicle preparation or by the authorized Mercedes-Benz Center during new vehicle inspection. We suggest that if you find any paint or appearance problems that you advise your authorized Mercedes-Benz Center as soon as possible since deterioration due to use and exposure is not covered by the warranty.

The instructions in your Operator's Manual regarding the care of paint, upholstery, trim items and convertible tops, as applicable, must be followed explicitly to maintain your warranty coverage.

Body Repair Information

Due to the materials and assembly procedures used in the production of Mercedes-Benz vehicles, it is strongly recommended that any paint work/body repairs be performed using Genuine Mercedes-Benz parts by repair facilities which have been certified by Mercedes-Benz USA as having the tools, equipment and training necessary to perform such repairs. Mercedes-Benz USA has certified a network of body repair facilities which are qualified to perform both cosmetic and structural repairs to your vehicle.

While the vehicle owner may elect to have repairs (collision damage/paint repair work) performed by any automobile body repair establishment or individual, damage or malfunction caused by body repairs not performed in accordance with Mercedes-Benz specified repair procedures are not covered by the Mercedes-Benz New Vehicle Limited Warranty.

Should your vehicle need paint work/body repair or if you have any questions please contact your authorized Mercedes-Benz Center or call 1-800-FOR-MERCedes.

Customer Repair Orders

Your servicing authorized Mercedes-Benz Center will give you a copy of the Repair Order on all warranty repairs performed. Please keep this copy with your vehicle records.

Mercedes-Benz New Vehicle Limited Warranty Coverage Addendum

Warranty Coverage Extension (Electro-Hydraulic Brake System Hydraulic Pump)

The following applies to all SL-Class vehicles equipped with the Electro-hydraulic brake system.

The Mercedes-Benz New Vehicle Limited Warranty coverage on the hydraulic pump within the Electro-hydraulic brake system is extended to 10 years with unlimited miles from the vehicle's warranty start date. Other components of the Electro-hydraulic brake system are not covered by this warranty extension.

This extension of the Mercedes-Benz New Vehicle Limited Warranty applies to these vehicles regardless of ownership. All of the other warranty terms apply to this extension.

Notes

Emission Control System Maintenance

General

The law requires your vehicle to conform to exhaust emission standards. To provide the best vehicle performance and lowest vehicle emissions, you are responsible to see that all recommended maintenance procedures detailed in the Maintenance Booklet are performed at the specified times and mileages. The emission control warranty does not cover failures due solely to owner abuse or lack of proper maintenance.

More frequent maintenance may be needed for vehicles under severe operating conditions such as dusty areas, very short trip driving or trailer towing.

While maintenance service can be performed by any qualified service outlet, we recommend that all maintenance services be performed by your authorized Mercedes-Benz Center who is equipped with the tools, instruments, and literature necessary for correct and systematic performance of these services. Although warranty obligations are not dependent upon the use of any particular brand of replacement parts and you may elect to use non-Genuine Mercedes-Benz parts for replacement purposes, we recommend the use of Genuine Mercedes-Benz parts for service and repairs, since they have been made according to the manufacturer's specifications. It is also important to use only fuels and lubricants meeting factory specifications, since the emission systems warranty does not cover repair or replacement of parts necessitated by failure of such items.

For detailed information concerning emission control system maintenance, please refer to your Maintenance Booklet. If you should desire further information concerning tune-up specifications or emission control system maintenance jobs, we recommend obtaining maintenance-related literature. Such literature is available from either your authorized Mercedes-Benz Center or directly from Mercedes-Benz USA, LLC.

Emission Systems Warranty (Federal)

General

In accordance with the requirements of the Federal Clean Air Act as amended, Mercedes-Benz USA, LLC warrants to the original and each subsequent owner of a new Mercedes-Benz vehicle that:

- (1) the vehicle was designed, built and equipped so as to conform, at the time of sale to the original owner, with the then applicable regulations issued by the Federal Environmental Protection Agency under authority of the Federal Clean Air Act as amended; and
- (2) the vehicle is free from defects in materials and workmanship at the time of sale which would cause it not to conform with those regulations within a period of two years or 24,000 miles from the date of initial operation of the vehicle, whichever occurs first; and
- (3) is free from defects in material and workmanship in specific emission related parts as specified in the lists shown on page (▷ Page 28) which would cause them not to conform with those requirements for a period of 8 years or 80,000 miles, whichever occurs first.

This Warranty Does Not Apply To:

1. The repair or replacement of warranted parts which are scheduled to be replaced prior to 80,000 miles. These parts are no longer covered once they have been replaced at the first required replacement interval during a regular maintenance service.
2. Any vehicle on which the odometer mileage has been altered and the vehicle's actual mileage cannot be readily determined.
3. Loss of time, inconvenience, loss of the use of the vehicle or similar incidental or consequential damages.

Emission Systems Warranty (Federal)

This warranty will be performed by any authorized Mercedes-Benz Center of the owner's choice - repairing, replacing or adjusting at the authorized Mercedes-Benz Center's discretion, upon delivery of the vehicle to the authorized Mercedes-Benz Center's place of business without charge for parts and labor (including diagnosis), using Genuine Mercedes-Benz parts to assure compliance with applicable regulations. Parts replaced under this warranty become the property of the warrantor.

This warranty is available on a vehicle purchased in the United States or in any U.S. possession governed by U.S. law.

In all other countries, defective parts will be repaired or replaced free of charge only in accordance with the terms and limitations of the warranty for new Mercedes-Benz vehicles in effect at the time in such countries.

WITH RESPECT TO EMISSION SYSTEMS, THIS WARRANTY AND THE EMISSIONS PERFORMANCE WARRANTY ARE EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES AND REPRESENTATIONS, EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND OF ALL OTHER OBLIGATIONS OR LIABILITIES ON THE PART OF THE WARRANTOR. DAIMLER AG, MERCEDES-BENZ USA, LLC, MERCEDES-BENZ U.S. INTERNATIONAL, INC, MERCEDES-BENZ RESEARCH & DEVELOPMENT NORTH AMERICA, INC. OR THE SELLING AUTHORIZED MERCEDES-BENZ CENTER NEITHER ASSUME NOR AUTHORIZE ANY OTHER PERSON TO ASSUME FOR THEM ANY OTHER LIABILITY IN CONNECTION WITH SUCH EMISSION SYSTEMS.

See (▷ Page 28, 30, 54) for components covered by this warranty.

Emission Performance Warranty (Federal) - Things You Should Know

General

You may present a claim under this warranty immediately after your vehicle has failed an EPA approved emission short test if, as a result of that failure, you are required by law to repair the vehicle to avoid the imposition of a penalty or sanction. You do not need to suffer the loss of the right to use the vehicle, pay a fine, or incur repair expenses before bringing this claim. Your warranty claim may be presented to any authorized Mercedes-Benz Center of your choice in the USA or its territories.

The authorized Mercedes-Benz Center will honor or deny your claim within a reasonable time not to exceed 30 days, from the time at which your vehicle is initially presented for repair or within any time period specified by local, State or Federal Law, whichever is shorter, except when a delay is caused by events not attributable to MBUSA or your authorized Mercedes-Benz Center. You will be notified in writing by your authorized Mercedes-Benz Center of the reason for any denial of your claim.

Your authorized Mercedes-Benz Center is required by law to honor your claim if such notice of denial is not received by you within said time period.

You may obtain further information concerning the emission performance warranty or report violations of the terms of the Emission Performance Warranty by contacting the Director, Field Operation and Support Division (EN-397F), Environmental Protection Agency, 401 "M" Street, SW., Washington, D.C. 20460.

Emission Performance Warranty (Federal)

NOTE: The Emission Performance Warranty is required by Federal Law, and is effective only to the extent required by that law. To the extent the underlying law is suspended or amended, this Warranty is automatically altered in the same manner, without further notice.

Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a new Mercedes-Benz vehicle that:

- a. if the vehicle is maintained and operated in accordance with MBUSA's written instructions for required maintenance and use, and
- b. if the vehicle fails to conform at any time during 8 years or 80,000 miles, whichever first occurs, to the applicable emission standards as ascertained by an EPA-approved emission short test, and
- c. if such non-conformity results or will result in the vehicle owner having to bear any penalty or other sanction (including the denial of the right to use the vehicle) under local, State or Federal law, then any authorized Mercedes-Benz Center during the first 24 months or 24,000 miles will make any repairs or replacements necessary to specified systems/components to correct the non-conformity or so that the vehicle will pass the smog check test at no charge for parts and labor (including diagnosis).

For the remainder of the 8 years or 80,000 miles the authorized Mercedes-Benz Center will correct only those deficiencies directly related to the specified components in the attached list which have been installed in or on the vehicle for the sole or primary purpose of reducing vehicle emissions and that were not in general use prior to Model Year 1968.

Emission Performance Warranty (Federal)

Parts replaced under this warranty become the property of the warrantor. The warranty period starts on the date the vehicle is delivered to the first retail purchaser or put into service as an authorized Mercedes-Benz Center demonstrator or MBUSI, MBUSA or MBRDNA company vehicle.

The emission control system of your new Mercedes-Benz vehicle was designed, built and tested using Genuine Mercedes-Benz parts and the vehicle is certified as being in conformity with Federal emission control regulations and requirements. Accordingly, it is recommended that any replacement parts used for maintenance, repair or replacement of emission related components be Genuine Mercedes-Benz Parts, including Remanufactured Parts.

The owner may elect to have maintenance, replacement or repair of the emission control devices and systems performed by any automotive repair establishment or individual, and may elect to use other than Genuine Mercedes-Benz Parts, including Remanufactured Parts for such maintenance, replacement or repair without invalidating this warranty; the cost of such service or parts, however, will not be covered under the warranty except in the case of an emergency.

Use of replacement parts which are not of equivalent quality and design may impair the effectiveness of the emission control systems.

If other than Genuine Mercedes-Benz Parts, including Remanufactured Parts are being used for maintenance, replacement or repair of components affecting emission control, the owner should obtain assurances that such parts are warranted by their manufacturer to be equivalent to Genuine Mercedes-Benz parts in performance and durability.

MBUSA, however, assumes no liability under this warranty with respect to parts other than Genuine Mercedes-Benz Parts, including Remanufactured Parts except for consequential damage to a non-Mercedes-Benz warranted part caused by a failure of a Mercedes-Benz part. However, the use of non-Mercedes-Benz replacement parts does not invalidate the warranty on other components unless non-Mercedes-Benz parts cause damage to warranted parts.

Emission Performance Warranty (Federal)

MBUSA may deny an emission performance warranty claim if the failure of a part is the result of:

a. non-compliance with the written instructions for required maintenance and use. These written instructions, including time and mileage intervals at which maintenance is to be performed may be found in the Maintenance Booklet and Operator's Manual provided with your vehicle. You are advised to perform all recommended maintenance or repairs on your new Mercedes-Benz vehicle. MBUSA may deny a warranty claim if your failure to perform the required maintenance resulted in the failure of the warranted part in question. Receipts and service records covering the performance of regular maintenance should be retained in the event questions arise concerning maintenance. The receipts and service records should be transferred to each subsequent owner of this vehicle.

b. vehicle abuse or maintenance performed in such a manner that an emission component was improperly installed or adjusted substantially outside the manufacturer's specifications or which resulted in removing or rendering inoperative any component affecting the vehicle's emissions.

c. using non-EPA certified replacement parts in the maintenance or repair of the vehicle which ultimately proved to be defective in material or workmanship or not equivalent from an emission standpoint to the original equipment part and the owner is unable to prove otherwise.

Mercedes-Benz USA, LLC may deny an emission related warranty claim if it can establish that the failure or the malfunction of an emission control system part results directly from the use of:

- Gasoline engines
non-premium low octane gasoline with an anti-knock index of below 91

or

- Diesel engines
diesel fuel other than S15 ULTRA-LOW SULFUR HIGHWAY DIESEL FUEL (15 ppm SULFUR MAXIMUM)

Emission Performance Warranty (Federal)

This Warranty Does Not Cover:

- a. Malfunctions in any part caused by any of the following: misuse, improper adjustments, modification, alteration, tampering, disconnection, improper or inadequate maintenance, or use of leaded gasoline for catalyst equipped vehicles.
- b. Damage resulting from accident, acts of nature or other events beyond the control of MBUSA.
- c. The repair or replacement of warranted parts which are scheduled for replacement prior to 80,000 miles once these have been replaced at the first replacement interval as part of regular maintenance service.
- d. Loss of time, inconvenience, loss of use of the vehicle, or other incidental or consequential damages.
- e. Any vehicle on which the odometer mileage has been altered so that the vehicle's actual mileage cannot be determined.

This warranty is available on a vehicle purchased in the United States or in any U.S. possession governed by U.S. law.

In all other countries, defective parts will be repaired or replaced free of charge only in accordance with the terms and limitations of the warranty for new Mercedes-Benz vehicles in effect at the time in such countries.

EXCEPT FOR THE EMISSION CONTROL WARRANTY, THIS WARRANTY AND THE LIMITED WARRANTY FOR NEW MERCEDES-BENZ VEHICLES ARE EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES AND REPRESENTATION, EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND OF ALL OTHER OBLIGATIONS OR LIABILITIES ON THE PART OF THE WARRANTOR. DAIMLER AG, MERCEDES-BENZ USA, LLC, MERCEDES-BENZ U.S. INTERNATIONAL, INC, MERCEDES-BENZ RESEARCH & DEVELOPMENT NORTH AMERICA, INC. OR THE SELLING AUTHORIZED MERCEDES-BENZ CENTER NEITHER ASSUME NOR AUTHORIZE ANY OTHER PERSON TO ASSUME FOR THEM ANY OTHER LIABILITY IN CONNECTION WITH SUCH EMISSION SYSTEMS.

The lists shown on (▷ Page 28, 30, 54) set forth the emission related components which may be covered by the emissions performance warranty.

Mercedes-Benz Warranted Emission Related Components for MY 2011 - Gasoline or Flexible Fuel Engine

I. Air Induction System

Air Cleaner Housing
Air Cleaner with Integrated Hydrocarbon Trap
Charge Air Cooler
Camshaft Adjuster
Deceleration Air Switching Valve
Intake Manifold
Intake Manifold with Integrated Vacuum
 Reservoir (and Integrated Variable Intake
 System Actuator)
Supercharger
Supercharger Bypass Valve
Tumble Flap Switching Valve
Turbocharger
Variable Intake System Actuator
Variable Intake System Switching Valve

II. Fuel Metering System

Fuel Injector
Fuel Management System
Fuel Filter (with Integrated Pressure Regulator)
Fuel Pressure Regulator
Fuel Pressure Sensor
Fuel Pump
Fuel Pump Control Unit
Fuel Rail
Fuel System Control Module
High Pressure Pump
Throttle Actuator

II. Ignition System

Ignition Coil
Ignition Module
Spark Plug

IV. Positive Crankcase Ventilation

Crankcase Ventilation Line
Oil Filler Cap

V. Fuel Evaporative Control

EVAP Canister
EVAP Canister Purge Valve
EVAP Purge Line
EVAP Shutoff Valve
Expansion Tank
Fuel Filler Cap
Fuel Filler Neck (without Expansion Tank)
Fuel Tank
Fuel Tank Insulation Valve
Fuel Tank Leak Diagnostic Module
Fuel Tank Pressure Sensor
Fuel Tank Vent Valve

VI. Secondary Air Injection System

Air Combination Valve
Air Switching Valve
Air Vacuum Check Valve
Electric Air Pump
Electro-Pneumatic Transducer (Frequency
 Control)

VII. Exhaust

Exhaust Manifold
Exhaust Manifold with Catalyst*
Front Exhaust Pipe with Catalyst*
Three-Way-Catalyst*

Mercedes-Benz Warranted Emission Related Components for MY 2011 - Gasoline or Flexible Fuel Engine

VIII. Engine Emissions Control Systems/ Sensors

Accelerator Pedal Module
Camshaft Position Sensor
Charge Air Pressure Sensor
Crankshaft Position Sensor
Engine Control Module*
Engine Coolant Temperature Sensor
Intake Air Temperature Sensor
Intake Manifold Pressure Sensor
Knock Sensor
Manifold Air Pressure Sensor
Mass Air Flow Sensor (with Integrated Intake
 Air Temperature Sensor)
O₂ Sensor
Transmission Control Module
Vehicle Speed Sensor (Front Wheels)
Vehicle Speed Sensor (Rear Wheels)

XI. Related Parts w/ Above Systems

Automatic Transmission Mode Selector
Emission Related:
 Hoses, Clamps, Belts, Pulleys, Tubes, Fittings,
 Sealing Devices, Mounting Hardware
 included *

IX. On-Board Diagnostics

Data Link Connector (OBD)
Instrument Cluster (Malfunction Indicator
 Lamp)*

X. Hybrid System (ML450 4M HYBRID only)

Brake Pedal Module
Electric Motor
Electric Motor and Hybrid Control Processor
High Voltage Battery (with Control Module)
Recuperative Braking Controller

* These items are warranted for 8 years/80,000 miles (whichever occurs first).

All other items are warranted for (a) or (b):

- (a) 3 years/50,000 miles (whichever occurs first) for new vehicles which are first sold by an authorized
 Mercedes-Benz Center in CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA.
- (b) 2 years/24,000 miles (whichever occurs first) for new vehicles which are first sold by an authorized
 Mercedes-Benz Center in all other states.

Please reference the previous pages for additional emission warranty coverage.

Mercedes-Benz Warranted Emission Related Components for MY 2011 - BlueTEC Diesel Engine with DEF

I. Air Induction System

Air Cleaner Housing
Charge Air Cooler
Charge Air Distribution Line
Electric Intake Air Throttle (with Throttle Valve Step Motor)
Intake Port Shutoff
Turbocharger

II. Fuel Metering System

Fuel Filter
Fuel Injector
Fuel Pressure Regulator
Fuel Pump (Electric)
Fuel Rail
Fuel Rail Pressure Sensor
High Pressure Pump

III. Ignition System

Glow Plug
Glow Time Control Module

IV. Exhaust Gas Recirculation System

EGR Cooler
EGR Line
EGR Valve

V. Positive Crankcase Ventilation

Crankcase Ventilation Valve/Line
Oil Filler Cap

VI. Fuel Evaporative Control

Fuel Filler Neck (without Expansion Tank)
Fuel Tank
Fuel Tank Vent Valve

VII. Exhaust/Diesel Exhaust Fluid (DEF) System

DEF Delivery Pump (with Pressure Sensor)
DEF Injection Valve
DEF Tank (with Temperature Sensor and Fluid Level Gauge)
Diesel Oxidation Catalyst with Diesel Particulate Filter*
Exhaust Manifold
Front Exhaust Pipe (with Diesel Oxidation Catalyst and Diesel Particulate Filter)*
Selective Catalytic Reduction Catalyst*

VIII. Engine Emissions Control Systems/ Sensors

Accelerator Pedal Module
DEF Control Module
Camshaft Position Sensor
Charge Air Pressure Sensor
Charge Air Temperature Sensor
Crankshaft Position Sensor
Engine Control Module*
Engine Coolant Temperature Sensor
Exhaust Back Pressure Sensor
Exhaust Differential Pressure Sensor
Exhaust Gas Temperature Sensor
Fuel Temperature Sensor
Heated Cooling Water Thermostat
Manifold Air Pressure Sensor
Mass Air Flow Sensor (with Integrated Intake Air Temperature Sensor)
NO_x Sensor
O₂ Sensor
Transmission Control Module
Vehicle Speed Sensor (Front Wheels)
Vehicle Speed Sensor (Rear Wheels)

Mercedes-Benz Warranted Emission Related Components for MY 2011 - BlueTEC Diesel Engine with DEF

IX. On-Board Diagnostics

Data Link Connector (OBD)

Instrument Cluster (Malfunction Indicator
Lamp)*

X. Related Parts w/ Above Systems

Automatic Transmission Mode Selector

Emission Related:

Hoses, Clamps, Belts, Pulleys, Tubes, Fittings,
Sealing Devices, Mounting Hardware
included *

* These items are warranted for 8 years/80,000 miles (whichever occurs first).

All other items are warranted for (a) or (b):

(a) 3 years/50,000 miles (whichever occurs first) for new vehicles which are first sold by an authorized
Mercedes-Benz Center in CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA.

(b) 2 years/24,000 miles (whichever occurs first) for new vehicles which are first sold by an authorized
Mercedes-Benz Center in all other states.

Please reference the previous pages for additional emission warranty coverage.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty - Things You Should Know

Your Warranty Rights and Obligations:

The California Air Resources Board and Mercedes-Benz USA, LLC are pleased to explain the emission control system warranty on your Mercedes-Benz vehicle. In California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington, new motor vehicles must be designed, built and equipped to meet these states' stringent anti-smog standards. MBUSA must warrant the emission control system on your Mercedes-Benz vehicle for the periods of time listed below provided there has been no abuse, neglect or improper maintenance of your vehicle.

Your emission control system may include such parts as the fuel injection system, ignition system, catalytic converter and engine computers. Also included may be hoses, belts, connectors and other emission related assemblies.

Where a warrantable condition exists, MBUSA will repair your Mercedes-Benz vehicle at no cost to you including diagnosis, parts and labor.

Manufacturer's Warranty Coverage:

For 3 years or 50,000 miles, whichever first occurs:

1. If your Mercedes-Benz vehicle fails a Smog Check Inspection, all necessary repairs and adjustments will be made by MBUSA to ensure that your vehicle passes the inspection. This is your emission control system **PERFORMANCE WARRANTY**.
2. If any emission related part on your MB vehicle is defective, the part will be repaired or replaced by MBUSA. This is your short-term emission control system **DEFECTS WARRANTY**.

For 7 years or 70,000 miles, whichever first occurs:

1. If an emission related part listed in this warranty booklet specially noted with coverage for 7 years or 70,000 miles is defective, the part will be repaired or replaced by MBUSA. This is your long-term emission control system **DEFECTS WARRANTY**.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty - Things You Should Know

Owner's Warranty Responsibilities:

As the vehicle owner, you are responsible for the performance of the required maintenance listed in your Maintenance Booklet. MBUSA recommends that you retain all receipts covering maintenance on your vehicle, but MBUSA cannot deny emission control system warranty solely for the lack of receipts or for your failure to ensure the performance of all required maintenance.

You are responsible for presenting your Mercedes-Benz vehicle to an authorized Mercedes-Benz Center as soon as a problem exists. The warranty repairs should be completed in a reasonable amount of time, not to exceed 30 days.

As the vehicle owner, you should also be aware that MBUSA may deny you warranty coverage if your vehicle or a part has failed due to abuse, neglect, improper maintenance or unapproved modifications.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty - Things You Should Know

If you have any questions regarding your warranty rights and responsibilities, you should contact:

Mercedes-Benz USA, LLC
Customer Assistance Center
One Mercedes Drive
Montvale, NJ 07645-0350
1-800-FOR-MERCedes, or

State of California
Air Resources Board
Mobile Source Operations Division
P.O. Box 8001
El Monte, CA 91731-2990, or

State of Connecticut
Department of Environmental Protection
79 Elm Street
Hartford, CT 06106-5127, or

State of Maine
Department of Environmental Protection
17 State House Station Augusta,
Maine 04333, or

State of Maryland
Department of the Environment
Air & Radiation Management Administration
Mobile Sources Control Program
1800 Washington Blvd.
Baltimore, MD 21230

Commonwealth of Massachusetts
Department of Environmental Protection
Division of Air Quality Control
One Winter Street, Boston, MA 02108, or

State of New Jersey
New Jersey Department of Environmental Protection, 401 East State Street Trenton, New Jersey 08625, or

State of New Mexico
Air Quality Bureau
New Mexico Environment Department
1301 Siler Rd, Building B
Santa Fe, NM 87507

State of Oregon
Department of Environmental Quality
811 S.W. Sixth Avenue
Portland, OR 97204, or

Commonwealth of Pennsylvania
Department of Environmental Protection
Bureau of Air Quality
Rachel Carson State Office Building
12th Floor, P.O. Box 8468
Harrisburg, PA 17105-8468, or

State of Rhode Island
Department of Environmental Management, 235 Promenade Street
Providence, Rhode Island 02908, or

State of Vermont
Agency of Natural Resources
Department of Environmental Conservation, Air Pollution Control Division
Building 3 South, 103 Main Street, Waterbury, VT 05671-0402, or

State of Washington
Washington State Department of Ecology
P.O. Box 47600
Olympia, WA 98504-7600.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty

General

Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a 2011 Mercedes-Benz vehicle which is first sold by an authorized Mercedes-Benz Center in California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington that:

(1) such vehicle is free from defects in material and workmanship which would cause it to fail to conform with requirements of the California Air Resources Board (CARB) or to fail to pass a smog check test for a period of use of 3 years or 50,000 miles, whichever first occurs; and

(2) if any part which affects any regulated emission from your vehicle is defective during 3 years or 50,000 miles, whichever first occurs, the part will be repaired or replaced; and

(3) is free from defects in material and workmanship in specific emission related parts as specified in the attached list which would cause them not to conform with those requirements for a period of use of 7 years or 70,000 miles, whichever first occurs.

MBUSA further warrants that:

a. if the vehicle is maintained and operated in accordance with MBUSA's written instructions for required maintenance and use, and

b. if a part is defective during 3 years or 50,000 miles, whichever first occurs, which causes the vehicle not to conform to the applicable CARB requirement or to fail a smog check test, or

c. if an emission-related part covered by the 7 year or 70,000 mile, whichever first occurs, warranty term is defective during the warranty period,

then any authorized Mercedes-Benz Center of the owner's choice will make any adjustments, repairs or replacements (including diagnosis) necessary to correct the defect or so that the vehicle will pass the smog check test at no charge for parts, labor or diagnosis.

If your vehicle is between 3 to 8 years old and has been driven less than 80,000 miles, then your vehicle may be eligible for additional coverage under the Federal Emissions Warranty.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty

These warranty provisions shall begin on the date the vehicle is delivered to the first retail purchaser or, if the vehicle is first placed in service as a retail demonstrator or MBUSI, MBUSA or MBRDNA company vehicle prior to sale at retail, on the date the vehicle is first placed in such service.

The emission control system of your new Mercedes-Benz vehicle was designed, built and tested using Genuine Mercedes-Benz parts and the vehicle is certified as being in conformity with Federal, California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington emission control regulations and requirements. Accordingly, it is recommended that any replacement parts used for maintenance, repair or replacement of emission related components be Genuine Mercedes-Benz Parts, including Remanufactured Parts.

The owner may elect to have maintenance, replacement or repair of the emission control devices and systems performed by any automotive repair establishment or individual, and may elect to use other than Genuine Mercedes-Benz Parts, including Remanufactured Parts for such maintenance, replacement or repair without invalidating this warranty; the cost of such service or parts, however, will not be covered under the warranty except in the case of an emergency.

Use of replacement parts which are not of equivalent quality and design may impair the effectiveness of the emission control systems. If other than Genuine Mercedes-Benz Parts, including Remanufactured Parts are being used for maintenance, replacement or repair of components affecting emission control, the owner should obtain assurances that such parts are warranted by their manufacturer to be equivalent to Genuine Mercedes-Benz parts in performance and durability.

MBUSA, however, assumes no liability under this warranty with respect to parts other than Genuine Mercedes-Benz Parts, including Remanufactured Parts except for consequential damage to a non-Mercedes-Benz warranted part caused by a failure of a Mercedes-Benz part. However, the use of non-Mercedes-Benz replacement parts does not invalidate the warranty on other components unless non-Mercedes-Benz parts cause damage to warranted parts.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty

Repairs covered by this warranty will be performed by any authorized Mercedes-Benz Center at its place of business with no charge for parts or labor (including diagnosis), using Genuine Mercedes-Benz Parts, including Remanufactured Parts for any part covered by this warranty.

In the case of an emergency, when and where an authorized Mercedes-Benz Center is not available, repairs may be performed at any available service establishment or by the owner using any replacement part. The non-availability of a replacement part for warranty repair or a repair not completed within 30 days constitutes an emergency.

MBUSA will reimburse the owner for such repairs (including labor and diagnosis) that are covered under this warranty. Such reimbursement shall not exceed MBUSA suggested retail prices for warranted parts replaced and labor charges based on MBUSA recommended time allowances for warranty repairs at a geographically appropriate hourly labor rate. Replaced parts and paid invoices must be presented at an authorized Mercedes-Benz Center as a condition of reimbursement for emergency repairs not performed at an authorized Mercedes-Benz Center. Parts replaced under this warranty become the property of the warrantor.

The enclosed list sets forth some of the emission related components covered by the emission control system defects warranty. You are advised to perform all recommended maintenance or repairs on your new Mercedes-Benz vehicle. MBUSA will not deny an emissions system warranty claim solely because you have no record of maintenance; however, you are responsible for the performance of the required maintenance. MBUSA may deny a warranty claim if your failure to perform the required maintenance resulted in the failure of a warranted part. Receipts and service records covering the performance of regular maintenance should be retained in the event questions arise concerning maintenance. The receipts and service records should be transferred to each subsequent owner of this vehicle.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty

Mercedes-Benz USA, LLC may deny an emission related claim if it can establish that the failure or the malfunction of an emission control system part results directly from the use of non-premium low octane fuel in the engine (i.e. fuel with an anti-knock index of below 91 as displayed on the fuel pump).

What is not covered by the Emission Warranty

This warranty does not cover:

1. The repair or replacement of any "warranted part" otherwise eligible for warranty coverage shall be excluded from such warranty coverage if the vehicle or engine manufacturer demonstrates that the vehicle or engine has been abused, neglected or improperly maintained, and that such abuse, neglect, or improper maintenance was the direct cause of the need for the repair or replacement of the part.
2. Malfunctions in any part caused by any of the following: improper adjustments except for those done by an authorized Mercedes-Benz Center during warranty service work, modification, alteration, tampering, disconnection, or use of leaded gasoline (for catalyst equipped vehicles).
3. Damage resulting from accident, acts of nature or other events beyond the control of MBUSA.
4. The repair or replacement of warranted parts which are scheduled to be replaced prior to 50,000 miles once these have been replaced at the first replacement interval during a regular maintenance service.
5. Incidental or consequential damages such as loss of time, inconvenience, or loss of use of the vehicle.
6. Any vehicle on which the odometer mileage has been altered so that the vehicle's actual mileage cannot be determined.

CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA Emission Control System Warranty

This warranty is applicable to new vehicles which are first sold by an authorized Mercedes-Benz Center in the States of California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, Oregon, Pennsylvania, Rhode Island, Vermont and Washington. In all other states or countries, defective parts will be repaired or replaced in accordance with the terms and limitations of the warranty applicable to new Mercedes-Benz vehicles in effect at the time in such states or countries.

You may present a claim under the performance warranty immediately after your vehicle has failed a smog check test. You do not need to suffer the loss of the right to use the vehicle, pay a fine, or incur repair expenses before bringing this claim. After the 3 year/50,000 mile performance warranty period has passed, a smog check test failure due to a defect in a part which is warranted for 7 years/70,000 miles, is covered.

Your warranty claim may be presented to any authorized Mercedes-Benz Center of your choice. The authorized Mercedes-Benz Center will honor or deny your claim within a reasonable time not to exceed 30 days, from the time at which your vehicle is initially presented for repair. Exceptions are when you, the owner, request a delay, or a delay is caused by events not attributable to MBUSA or your authorized Mercedes-Benz Center.

You will be notified in writing by your authorized Mercedes-Benz Center of the reasons for any denial of your claim.

Your authorized Mercedes-Benz Center is required by law to honor your claim if such notice of denial is not received by you within said time period.

**WITH RESPECT TO EMISSION SYSTEMS,
THIS WARRANTY IS EXPRESSLY IN LIEU
OF ALL OTHER WARRANTIES AND REPRE-
SENTATIONS, EXPRESSED OR IM-
PLIED, INCLUDING, BUT NOT LIMITED
TO, IMPLIED WARRANTY OF MER-
CHANTABILITY OR FITNESS FOR A PAR-
TICULAR PURPOSE, AND OF ALL OTHER
OBLIGATIONS OR LIABILITIES ON THE
PART OF THE WARRANTOR. DAIMLER-
AG, MERCEDES-BENZ U.S. INTERNA-
TIONAL, INC., MERCEDES-BENZ USA,
LLC, MERCEDES-BENZ RESEARCH & DE-
VELOPMENT NORTH AMERICA, INC. OR
THE AUTHORIZED MERCEDES-BENZ
CENTER NEITHER ASSUME NOR AU-
THORIZE ANY OTHER PERSON TO AS-
SUME FOR THEM ANY OTHER LIABILITY
IN CONNECTION WITH SUCH EMISSION
SYSTEMS.**

Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles) for MY2011 - Gasoline or Flexible Fuel Engine (CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)

Parts Description	C300	C300 4M	C350	C63 AMG	GLK350	GLK350 4M	E350 Coupe	E550 Coupe	E350 Cabriolet	E550 Cabriolet	E350 4M Wagon
Brake Pedal Module											
Camshaft Adjuster											
Charge Air Cooler											
Electric Air Pump	•	•	•	•	•	•	•	•	•	•	•
Electric Motor											
Electric Motor and Hybrid Control Processor											
Engine Control Module*	•	•	•	•	•	•	•	•	•	•	•
EVAP Canister											
Exhaust Manifold	•	•	•	•	•	•	•	•	•	•	•
Exhaust Manifold with Catalyst*											
Front Exhaust Pipe with Catalyst*	•	•	•	•	•	•	•	•	•	•	•
Fuel Filler Neck (without Expansion Tank)											
Fuel Filter (with Integrated Pressure Regulator)											
Fuel Injector											
Fuel Management System											
Fuel Pump											
Fuel Rail							•	•			
Fuel System Control Module											
Fuel Tank	•	•	•	•	•	•	•	•	•	•	•
High Pressure Pump											
High Voltage Battery (with Control Module)											
Ignition Module											
Instrument Cluster (MIL)*	•	•	•	•	•	•	•	•	•	•	•
Intake Manifold						•					
Intake Manifold with Int. Vacuum Reservoir	•	•	•		•	•	•	•	•	•	•
Mass Air Flow Sensor (with Int. IAT Sensor)											
Recuperative Braking Controller											
Spark Plug											
Supercharger											
Supercharger Bypass Valve											
Three-Way-Catalyst (Close-Coupled)*	•	•	•		•	•	•	•	•	•	•
Three-Way-Catalyst (Underfloor)*					•						
Three-Way-Catalyst (Underhood)*					•						
Throttle Actuator	•	•	•	•	•	•	•	•	•	•	•
Transmission Control Module	•	•	•	•	•	•	•	•	•	•	•
Turbocharger											

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

**Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles)
for MY2011 - Gasoline or Flexible Fuel Engine (CA, CT, MA, MD, ME,
NJ, NM, OR, PA, RI, VT and WA)**

Parts Description	Models											
	E350	E350 4M	E550	E550 4M	E63 AMG	CLS550	CLS63 AMG	S550	S550 4M	S600	S63 AMG	S65 AMG
Brake Pedal Module												
Camshaft Adjuster												
Charge Air Cooler										•	•	•
Electric Air Pump	•	•	•	•	•	•	•	•	•	•	•	•
Electric Motor												
Electric Motor and Hybrid Control Processor												
Engine Control Module*	•	•	•	•	•	•	•	•	•	•	•	•
EVAP Canister												
Exhaust Manifold	•	•	•	•	•	•	•	•	•	•	•	•
Exhaust Manifold with Catalyst*	•	•	•	•	•	•	•	•	•	•	•	•
Front Exhaust Pipe with Catalyst*	•	•	•	•	•	•	•	•	•	•	•	•
Fuel Filler Neck (without Expansion Tank)												
Fuel Filter (with Integrated Pressure Regulator)												
Fuel Injector									•	•	•	
Fuel Management System						•						
Fuel Pump					•					•	•	
Fuel Rail								•	•	•	•	
Fuel System Control Module											•	
Fuel Tank	•	•	•	•	•	•	•	•	•	•	•	•
High Pressure Pump											•	
High Voltage Battery (with Control Module)												
Ignition Module								•		•	•	
Instrument Cluster (MIL)*	•	•	•	•	•	•	•	•	•	•	•	•
Intake Manifold						•	•			•	•	•
Intake Manifold with Int. Vacuum Reservoir	•	•	•	•	•	•	•	•	•	•	•	
Mass Air Flow Sensor (with Int. IAT Sensor)												
Recuperative Braking Controller												
Spark Plug									•		•	
Supercharger												
Supercharger Bypass Valve												
Three-Way-Catalyst (Close-Coupled)*	•	•	•	•	•	•	•	•	•	•	•	•
Three-Way-Catalyst (Underfloor)*								•				
Three-Way-Catalyst (Underhood)*							•					
Throttle Actuator	•	•	•	•	•	•	•	•	•	•	•	•
Transmission Control Module	•	•	•	•	•	•	•	•	•	•	•	•
Turbocharger									•	•	•	

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles) for MY2011 - Gasoline or Flexible Fuel Engine (CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)

Parts Description	Models
	CL550 4M CL600 CL63 AMG CL65 AMG SLK300 SLK350 SL550 SL600 SL63 AMG SL65 AMG SLS AMG R350 4M
Brake Pedal Module	
Camshaft Adjuster	
Charge Air Cooler	• • • •
Electric Air Pump	• • • • • • • •
Electric Motor	
Electric Motor and Hybrid Control Processor	
Engine Control Module*	• • • • • • • • • •
EVAP Canister	• •
Exhaust Manifold	• • • • • • • •
Exhaust Manifold with Catalyst*	•
Front Exhaust Pipe with Catalyst*	• • • • • • • • •
Fuel Filler Neck (without Expansion Tank)	•
Fuel Filter (with Integrated Pressure Regulator)	•
Fuel Injector	• • • • • • • •
Fuel Management System	
Fuel Pump	• • • • • • • •
Fuel Rail	• • • • • • • •
Fuel System Control Module	•
Fuel Tank	• • • • • • • • • •
High Pressure Pump	• •
High Voltage Battery (with Control Module)	
Ignition Module	• •
Instrument Cluster (MIL)*	• • • • • • • • •
Intake Manifold	• • • • • • • •
Intake Manifold with Int. Vacuum Reservoir	• •
Mass Air Flow Sensor (with Int. IAT Sensor)	•
Recuperative Braking Controller	
Spark Plug	• • • •
Supercharger	
Supercharger Bypass Valve	
Three-Way-Catalyst (Close-Coupled)*	• • • • • • • • •
Three-Way-Catalyst (Underfloor)*	• •
Three-Way-Catalyst (Underhood)*	• •
Throttle Actuator	• • • • • • • •
Transmission Control Module	• • • • • • • •
Turbocharger	• • • • • • • •

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

**Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles)
for MY2011 - Gasoline or Flexible Fuel Engine (CA, CT, MA, MD, ME,
NJ, NM, OR, PA, RI, VT and WA)**

Parts Description	Models									
	ML350	ML350 4M	ML450 4M	HYBRID	ML550 4M	ML63 AMG	GL450 4M	GL550 4M	G550	G55 AMG
Brake Pedal Module				●						
Camshaft Adjuster	●	●	●	●	●	●				
Charge Air Cooler										
Electric Air Pump	●	●	●	●	●	●	●	●	●	
Electric Motor			●							
Electric Motor and Hybrid Control Processor			●							
Engine Control Module*	●	●	●	●	●	●	●	●	●	●
EVAP Canister										
Exhaust Manifold	●	●	●	●	●	●	●	●	●	
Exhaust Manifold with Catalyst*	●	●	●	●	●	●	●	●	●	
Front Exhaust Pipe with Catalyst*	●	●	●	●	●	●	●	●	●	
Fuel Filler Neck (without Expansion Tank)	●	●	●	●	●	●	●	●	●	
Fuel Filter (with Integrated Pressure Regulator)	●	●	●	●	●	●	●	●		
Fuel Injector										
Fuel Management System										
Fuel Pump	●	●	●	●	●	●	●	●		
Fuel Rail			●		●	●	●	●	●	
Fuel System Control Module										
Fuel Tank	●	●	●	●	●	●	●	●	●	
High Pressure Pump										
High Voltage Battery (with Control Module)				●						
Ignition Module										
Instrument Cluster (MIL)*	●	●	●	●	●	●	●	●	●	
Intake Manifold					●					●
Intake Manifold with Int. Vacuum Reservoir	●	●	●	●	●	●	●	●	●	
Mass Air Flow Sensor (with Int. IAT Sensor)					●	●				
Recuperative Braking Controller				●						
Spark Plug										
Supercharger									●	
Supercharger Bypass Valve								●		
Three-Way-Catalyst (Close-Coupled)*	●	●	●	●	●	●	●	●	●	
Three-Way-Catalyst (Underfloor)*								●		
Three-Way-Catalyst (Underhood)*								●		
Throttle Actuator	●	●	●	●	●	●	●	●	●	
Transmission Control Module	●	●	●	●	●	●	●	●	●	
Turbocharger										

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

**Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles)
for MY2011 - BlueTEC Diesel Engine with DEF
(CA, CT, MA, MD, ME, NJ, NM, OR, PA, RI, VT and WA)**

Parts Description	Models				
	E350 BlueTEC	S350 4M BlueTEC	R350 4M BlueTEC	ML350 4M BlueTEC	GL350 4M BlueTEC
DEF Tank (with Temperature Sensor and Fluid Level Gauge)	●	●	●	●	●
Charge Air Cooler	●	●	●	●	●
Charge Air Distribution Line	●	●	●	●	●
Diesel Oxidation Catalyst with Diesel Particulate Filter*	●	●	●	●	●
Electric Intake Air Throttle (with Throttle Valve Step Motor)	●	●	●	●	●
Engine Control Module*	●	●	●	●	●
Exhaust Manifold	●	●	●	●	●
Front Exhaust Pipe (with Diesel Oxidation Catalyst and Diesel Particulate Filter)*	●				
Fuel Filler Neck (without Expansion Tank)			●		
Fuel Injector	●	●	●	●	●
Fuel Rail	●	●	●	●	●
Fuel Tank	●	●	●	●	●
High Pressure Pump	●	●	●	●	●
Instrument Cluster (Malfunction Indicator Lamp)*	●	●	●	●	●
Intake Port Shutoff	●	●	●	●	●
NO _x Sensor	●		●	●	●
Selective Catalytic Reduction Catalyst*	●	●	●	●	●
Transmission Control Module	●	●	●	●	●
Turbocharger	●	●	●	●	●

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

**Mercedes-Benz Defect Warranty Coverage (7 years / 70,000 miles)
for MY2011 - Partial Zero-Emission Vehicles (PZEV)
and S400 HYBRID Only (OR, PA, WA)**

Parts Description	Models							
	C300	C300 4M	C350	GLK350	GLK350 4M	E350 Coupe	E350	S400 HYBRID
Brake Pedal Module							●	
Direct Ozone Reduction (DOR) Radiator	●	●	●	●	●	●	●	●
Direct Ozone Reduction (DOR) Temperature Sensor	●	●	●	●	●	●	●	●
Electric Air Pump	●	●	●	●	●	●	●	●
Engine Control Module*	●	●	●	●	●	●	●	●
Exhaust Manifold	●	●	●	●	●	●	●	●
Front Exhaust Pipe with Catalyst*	●	●	●	●	●	●	●	●
Fuel Tank	●	●	●	●	●	●	●	●
High Voltage Battery								●
Instrument Cluster (MIL)*	●	●	●	●	●	●	●	●
Intake Manifold with Integrated Vacuum Reservoir (and Integrated Variable Intake System Actuator)	●	●	●	●	●	●	●	●
Three-Way-Catalyst (Close-Coupled)*	●	●	●	●	●	●	●	●
Three-Way-Catalyst (Underfloor)*	●	●	●	●	●	●	●	●
Throttle Actuator	●	●	●	●	●	●	●	●
Transmission Control Module	●	●	●	●	●	●	●	●

* These items are warranted for 8 years / 80,000 miles (whichever occurs first).

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only - Things You Should Know

Your Warranty Rights and Obligations:

The California Air Resources Board and Mercedes-Benz USA, LLC are pleased to explain the emission control system warranty on your Mercedes-Benz Partial Zero-Emission Vehicle (PZEV). In California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island and Vermont, new motor vehicles must be designed, built and equipped to meet these states' stringent anti-smog standards. MBUSA must warrant the emission control system on your Mercedes-Benz vehicle for the periods of time listed below provided there has been no abuse, neglect or improper maintenance of your vehicle.

Your emission control system may include such parts as the fuel injection system, ignition system, catalytic converter and engine computers. Also included may be hoses, belts, connectors and other emission related assemblies.

Where a warrantable condition exists, MBUSA will repair your Mercedes-Benz vehicle at no cost to you including diagnosis, parts and labor.

Identifying Partial Zero-Emission Vehicles (PZEV)

Being able to identify whether your vehicle meets the California Air Resources Board (CARB) Super Ultra-Low-Emission-Vehicle (SULEV) PZEV emission standard is an important part of understanding your emission warranty rights. To identify a vehicle that meets the PZEV emission standard please refer to the text description on the Vehicle Emission Control Information (VECI) label located in the engine compartment.

Please note the location of the VECI label will vary depending on model. Refer to your vehicle Operator's Manual for further information on identification labels and their locations.

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only - Things You Should Know

Manufacturer's Warranty Coverage:

For 15 years or 150,000 miles, whichever first occurs:

1. If your Mercedes-Benz vehicle fails a Smog Check Inspection, all necessary repairs and adjustments will be made by MBUSA to ensure that your vehicle passes the inspection. This is your emission control system **PERFORMANCE WARRANTY**.
2. If any emission related part on your Mercedes-Benz vehicle is defective, the part will be repaired or replaced by MBUSA. This is your emission control system **DEFECTS WARRANTY**.

Owner's Warranty Responsibilities:

As the vehicle owner, you are responsible for the performance of the required maintenance listed in your Maintenance Booklet. MBUSA recommends that you retain all receipts covering maintenance on your vehicle, but MBUSA cannot deny emission control system warranty solely for the lack of receipts or for your failure to ensure the performance of all required maintenance.

You are responsible for presenting your Mercedes-Benz vehicle to an authorized Mercedes-Benz Center as soon as a problem exists. The warranty repairs should be completed in a reasonable amount of time, not to exceed 30 days.

As the vehicle owner, you should also be aware that MBUSA may deny you warranty coverage if your vehicle or a part has failed due to abuse, neglect, improper maintenance or unapproved modifications.

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only - Things You Should Know

If you have any questions regarding your warranty rights and responsibilities, you should contact:

Mercedes-Benz USA, LLC
Customer Assistance Center
One Mercedes Drive
Montvale, NJ 07645-0350
1-800-FOR-MERCedes, or

State of California
Air Resources Board
Mobile Source Operations Division
P.O. Box 8001
El Monte, CA 91731-2990, or

State of Connecticut
Department of Environmental Protection
79 Elm Street
Hartford, CT 06106-5127, or

State of Maine
Department of Environmental Protection
17 State House Station Augusta,
Maine 04333, or

State of Maryland
Department of the Environment
Air & Radiation Management
Administration
Mobile Sources Control Program
1800 Washington Blvd.
Baltimore, MD 21230

Commonwealth of Massachusetts
Department of Environmental Protection
Division of Air Quality Control
One Winter Street, Boston, MA 02108, or

State of New Jersey
New Jersey Department of Environmental
Protection, 401 East State Street
Trenton, New Jersey 08625, or

State of New Mexico
Air Quality Bureau
New Mexico Environment Department
1301 Siler Rd
Building B
Santa Fe, NM 87507

State of New York
Department of Environmental
Conservation
625 Broadway, Albany, NY 12233

State of Rhode Island
Department of Environmental Manage-
ment, 235 Promenade Street
Providence, Rhode Island 02908, or

State of Vermont
Agency of Natural Resources
Department of Environmental Conserva-
tion, Air Pollution Control Division
Building 3 South, 103 Main Street, Water-
bury, VT 05671-0402, or

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

General

Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a 2011 Mercedes-Benz vehicle which is first sold by an authorized Mercedes-Benz Center in California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island or Vermont that:

- (1) such vehicle is free from defects in material and workmanship which would cause it to fail to conform with requirements of the California Air Resources Board (CARB) or to fail to pass a smog check test for a period of use of 15 years or 150,000 miles, whichever first occurs; and
- (2) if any part which affects any regulated emission from your vehicle is defective during 15 years or 150,000 miles, whichever first occurs, the part will be repaired or replaced; and

MBUSA further warrants that:

- a. if the vehicle is maintained and operated in accordance with MBUSA's written instructions for required maintenance and use, and
- b. if a part is defective during 15 years or 150,000 miles, whichever first occurs, which causes the vehicle not to conform to the applicable CARB requirement or to fail a smog check test,

then any authorized Mercedes-Benz Center of the owner's choice will make any adjustments, repairs or replacements (including diagnosis) necessary to correct the defect or so that the vehicle will pass the smog check test at no charge for parts, labor or diagnosis.

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

These warranty provisions shall begin on the date the vehicle is delivered to the first retail purchaser or, if the vehicle is first placed in service as a retail demonstrator or MBUSA or MBSC company vehicle prior to sale at retail, on the date the vehicle is first placed in such service.

The emission control system of your new Mercedes-Benz vehicle was designed, built and tested using Genuine Mercedes-Benz parts and the vehicle is certified as being in conformity with Federal, California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island and Vermont emission control regulations and requirements. Accordingly, it is recommended that any replacement parts used for maintenance, repair or replacement of emission related components be Genuine Mercedes-Benz Parts, including Remanufactured Parts.

The owner may elect to have maintenance, replacement or repair of the emission control devices and systems performed by any automotive repair establishment or individual, and may elect to use other than Genuine Mercedes-Benz Parts, including Remanufactured Parts for such maintenance, replacement or repair without invalidating this warranty; the cost of such service or parts, however, will not be covered under the warranty except in the case of an emergency.

Use of replacement parts which are not of equivalent quality and design may impair the effectiveness of the emission control systems. If other than Genuine Mercedes-Benz Parts, including Remanufactured Parts are being used for maintenance, replacement or repair of components affecting emission control, the owner should obtain assurances that such parts are warranted by their manufacturer to be equivalent to Genuine Mercedes-Benz parts in performance and durability.

MBUSA, however, assumes no liability under this warranty with respect to parts other than Genuine Mercedes-Benz Parts, including Remanufactured Parts except for consequential damage to a non-Mercedes-Benz warranted part caused by a failure of a Mercedes-Benz part. However, the use of non-Mercedes-Benz replacement parts does not invalidate the warranty on other components unless non-Mercedes-Benz parts cause damage to warranted parts.

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

Repairs covered by this warranty will be performed by any authorized Mercedes-Benz Center at its place of business with no charge for parts or labor (including diagnosis), using Genuine Mercedes-Benz Parts, including Remanufactured Parts for any part covered by this warranty.

In the case of an emergency, when and where an authorized Mercedes-Benz Center is not available, repairs may be performed at any available service establishment or by the owner using any replacement part. The non-availability of a replacement part for warranty repair or a repair not completed within 30 days constitutes an emergency.

MBUSA will reimburse the owner for such repairs (including labor and diagnosis) that are covered under this warranty. Such reimbursement shall not exceed MBUSA suggested retail prices for warranted parts replaced and labor charges based on MBUSA recommended time allowances for warranty repairs at a geographically appropriate hourly labor rate. Replaced parts and paid invoices must be presented at an authorized Mercedes-Benz Center as a condition of reimbursement for emergency repairs not performed at an authorized Mercedes-Benz Center. Parts replaced under this warranty become the property of the warrantor.

The enclosed list sets forth some of the emission related components covered by the emission control system defects warranty. You are advised to perform all recommended maintenance or repairs on your new Mercedes-Benz vehicle. MBUSA will not deny an emissions system warranty claim solely because you have no record of maintenance; however, you are responsible for the performance of the required maintenance. MBUSA may deny a warranty claim if your failure to perform the required maintenance resulted in the failure of a warranted part. Receipts and service records covering the performance of regular maintenance should be retained in the event questions arise concerning maintenance. The receipts and service records should be transferred to each subsequent owner of this vehicle.

Mercedes-Benz USA, LLC may deny an emission related claim if it can establish that the failure or the malfunction of an emission control system part results directly from the use of non-premium low octane fuel in the engine (i.e. fuel with an anti-knock index of below 91 as displayed on the fuel pump).

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

What is not covered by the Emission Warranty

This warranty does not cover:

1. The repair or replacement of any "warranted part" otherwise eligible for warranty coverage shall be excluded from such warranty coverage if the vehicle or engine manufacturer demonstrates that the vehicle or engine has been abused, neglected or improperly maintained, and that such abuse, neglect, or improper maintenance was the direct cause of the need for the repair or replacement of the part.
2. Malfunctions in any part caused by any of the following: improper adjustments except for those done by an authorized Mercedes-Benz Center during warranty service work, modification, alteration, tampering, disconnection, or use of leaded gasoline (for catalyst equipped vehicles).
3. Damage resulting from accident, acts of nature or other events beyond the control of MBUSA.
4. The repair or replacement of warranted parts which are scheduled to be replaced prior to 150,000 miles once these have been replaced at the first replacement interval during a regular maintenance service.
5. Incidental or consequential damages such as loss of time, inconvenience, or loss of use of the vehicle.
6. Any vehicle on which the odometer mileage has been altered so that the vehicle's actual mileage cannot be determined.

CA, CT, MA, MD, ME, NJ, NM, NY, RI and VT Emission Control System Warranty For Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

This warranty is applicable to new vehicles which are first sold by an authorized Mercedes-Benz Center in the States of California, Connecticut, Maine, Maryland, Massachusetts, New Jersey, New Mexico, New York, Rhode Island and Vermont. In all other states or countries, defective parts will be repaired or replaced in accordance with the terms and limitations of the warranty applicable to new Mercedes-Benz vehicles in effect at the time in such states or countries.

You do not need to suffer the loss of the right to use the vehicle, pay a fine, or incur repair expenses before bringing this claim.

Your warranty claim may be presented to any authorized Mercedes-Benz Center of your choice. The authorized Mercedes-Benz Center will honor or deny your claim within a reasonable time not to exceed 30 days, from the time at which your vehicle is initially presented for repair. Exceptions are when you, the owner, request a delay, or a delay is caused by events not attributable to MBUSA or your authorized Mercedes-Benz Center.

You will be notified in writing by your authorized Mercedes-Benz Center of the reasons for any denial of your claim.

Your authorized Mercedes-Benz Center is required by law to honor your claim if such notice of denial is not received by you within said time period.

WITH RESPECT TO EMISSION SYSTEMS, THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES AND REPRESENTATIONS, EXPRESSED OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND OF ALL OTHER OBLIGATIONS OR LIABILITIES ON THE PART OF THE WARRANTOR. DAIMLERAG, MERCEDES-BENZ U.S. INTERNATIONAL, INC., MERCEDES-BENZ USA, LLC, MERCEDES-BENZ RESEARCH & DEVELOPMENT NORTH AMERICA, INC. OR THE AUTHORIZED MERCEDES-BENZ CENTER NEITHER ASSUME NOR AUTHORIZE ANY OTHER PERSON TO ASSUME FOR THEM ANY OTHER LIABILITY IN CONNECTION WITH SUCH EMISSION SYSTEMS.

The warranty coverage for the High Voltage Battery of a S400 HYBRID vehicle is 10 years or 150,000 miles, whichever occurs first (▷ Page 54).

Mercedes-Benz Warranted Emission Related Components for MY 2011 - Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

I. Air Induction System

Air Cleaner with Integrated Hydrocarbon Trap
Camshaft Adjuster
Direct Ozone Reduction (DOR) Radiator
Intake Manifold with Integrated Vacuum Reservoir (and Integrated Variable Intake System Actuator)
Tumble Flap Switching Valve
Variable Intake System Switching Valve

II. Fuel Metering System

Fuel Injector
Fuel Management System
Fuel Filter (with Integrated Pressure Regulator)
Fuel Pressure Sensor
Fuel Pump (with Integrated Fuel Filter and Pressure Regulator)
Fuel Rail
Fuel System Control Module
Throttle Actuator

III. Ignition System

Ignition Coil
Spark Plug

IV. Positive Crankcase Ventilation

Crankcase Ventilation Line
Oil Filler Cap

V. Fuel Evaporative Control

EVAP Canister
EVAP Canister Purge Valve
EVAP Purge Line
EVAP Shutoff Valve
Fuel Filler Cap
Fuel Filler Neck (without Expansion Tank)
Fuel Tank
Fuel Tank Pressure Sensor

VI. Secondary Air Injection System

Air Combination Valve
Air Switching Valve
Air Vacuum Check Valve
Electric Air Pump

VII. Exhaust

Exhaust Manifold
Three-Way-Catalyst*
Front Exhaust Pipe with Catalyst*

VIII. Engine Emissions Control Systems/ Sensors

Accelerator Pedal Module
Camshaft Position Sensor
Crankshaft Position Sensor
Engine Control Module*
Engine Coolant Temperature Sensor
Knock Sensor
Manifold Air Pressure Sensor
Mass Air Flow Sensor (with Integrated Intake Air Temperature Sensor)
O₂ Sensor
Transmission Control Module
Vehicle Speed Sensor (Front Wheels)
Vehicle Speed Sensor (Rear Wheels)

IX. On-Board Diagnostics

Data Link Connector (OBD)
Direct Ozone Reduction (DOR) Temperature Sensor
Instrument Cluster (Malfunction Indicator Lamp)*

Mercedes-Benz Warranted Emission Related Components for MY 2011 - Partial Zero-Emission Vehicles (PZEV) and S400 HYBRID Only

X. Hybrid System

Brake Pedal Module

High Voltage Battery**

XI. Related Parts w/ Above Systems

Automatic Transmission Mode Selector

Emission Related:

Hoses, Clamps, Belts, Pulleys, Tubes, Fittings,
Sealing Devices, Mounting Hardware
included *

For new vehicles which are first sold by an authorized Mercedes-Benz Center in states other than CA, CT, MA, MD, ME, NJ, NY, NM, OR, PA, RI, VT and WA:

* These items are warranted for 8 years / 80,000 miles (whichever occurs first) and all other items are warranted for 2 years / 24,000 miles (whichever occurs first).

For new vehicles which are first sold by an authorized Mercedes-Benz Center in OR, PA and WA:

* These items are warranted for 8 years / 80,000 miles (whichever occurs first) and all other items are warranted for 3 years / 50,000 miles (whichever occurs first).

For new vehicles which are first sold by an authorized Mercedes-Benz Center in CA, CT, MA, MD, ME, NJ, NY, NM, RI, and VT:

** This item is warranted for 10 years / 150,000 miles (whichever occurs first) and all other items are warranted for 15 years / 150,000 miles (whichever occurs first).

Warranty Enforcement Laws (Lemon Laws)

Laws in many states and federal law permit owners and/or lessees to obtain a replacement vehicle or a refund of the purchase or lease price under certain circumstances. The provisions of these laws vary from state to state and vary from the federal law. To the extent allowed or not prohibited by applicable law, Mercedes-Benz USA, LLC requires that you first provide us with direct written notification of any alleged unrepainted defect or malfunction, or any other dissatisfaction you have experienced with your vehicle so that we have the opportunity to cure the problem or dissatisfaction ourselves. Giving MBUSA itself this direct notice and opportunity to cure enables us to supplement prior efforts by our authorized Mercedes-Benz Center so any ongoing problem can be resolved or the dissatisfaction addressed by us. In states that have not enacted Lemon Laws, we also require, without constituting any liability beyond the Mercedes-Benz new vehicle warranty, that you give us direct written notice of any service difficulty you have experienced. Written notifications, either required under an applicable Lemon Law or other written notifications should be sent to us, not one of our authorized Mercedes-Benz Center, at Mercedes-Benz USA, LLC, Customer Assistance Center, One Mercedes Drive, Montvale, New Jersey, 07645-0350.

Warranty Enforcement Laws (Lemon Laws)

NEW JERSEY LEMON LAW DISCLOSURE

IMPORTANT: IF THIS VEHICLE HAS A DEFECT THAT SUBSTANTIALLY IMPAIRS ITS USE, VALUE OR SAFETY, OR THAT IS LIKELY TO CAUSE DEATH OR SERIOUS BODILY INJURY IF DRIVEN, AND WAS PURCHASED, LEASED OR REGISTERED IN NEW JERSEY, YOU MAY BE ENTITLED UNDER NEW JERSEY'S LEMON LAW TO A REFUND OF THE PURCHASE PRICE OR YOUR LEASE PAYMENTS.

Here is a summary of your rights:

1. To qualify for relief under the New Jersey Lemon Law, you must give the manufacturer or its dealer the opportunity to repair or correct the defect in the vehicle within the Lemon Law's term of protection, which is the first 24,000 miles of operation or two years after the vehicle's original date of delivery, whichever is earlier.
2. If the manufacturer or its dealer is unable to repair or correct a defect within a reasonable time, you may be entitled to return the vehicle and receive a full refund, minus a reasonable allowance for vehicle use.
3. It is presumed that the manufacturer or its dealer is unable to repair or correct the defect if substantially the same defect continues to exist after the manufacturer has received written notice of the defect by certified mail, return receipt requested, and has had a final opportunity to correct the defect or condition within 10 calendar days after receipt of notice. This notice must be received by the manufacturer with the term of protection and may be given only after (i) the manufacturer or its dealer has had two or more attempts to correct the defect, (ii) the manufacturer or its dealer has had at least one attempt to correct the defect if the defect is one that is likely to cause death or serious bodily injury if the vehicle is driven; or (iii) the vehicle has been out of service for repair for a cumulative total of 20 or more calendar days, or in the case of a motorhome, 45 days or more.
4. If substantially the same defect continues to exist after the manufacturer has had the final opportunity to repair or correct the defect, you may file an application for relief under New Jersey's Lemon Law.

FOR COMPLETE INFORMATION REGARDING YOUR RIGHTS AND REMEDIES UNDER THE RELEVANT LAW, INCLUDING THE MANUFACTURER'S ADDRESS TO GIVE NOTICE OF THE DEFECT, CONTACT THE NEW JERSEY DEPARTMENT OF LAW AND PUBLIC SAFETY, DIVISION OF CONSUMER AFFAIRS, LEMON LAW UNIT, AT POST OFFICE BOX 45026, NEWARK, NEW JERSEY 07101, TEL. NO. (973) 504-6226.

Warranty Enforcement Laws (Lemon Laws)

NEW JERSEY LEMON LAW DISCLOSURE

IMPORTANTE: SI ESTE VEHICULO TIENE UN DEFECTO QUE SUBSTANCIALMENTE AFECTA SU USO, VALOR O SEGURIDAD, O QUE PUEDE CAUSAR MUERTE O SERIO DAÑO CORPORAL SI SE MANEJA, Y FUE COMPRADO, ARRENDADO O REGISTRADO EN NUEVA JERSEY, USTED PUEDE TENER EL DERECHO BAJO LA LEY DE LIMÓN DEL ESTADO DE NUEVA JERSEY A UN REEMBOLSO DEL PRECIO DE COMPRA O A LOS PAGOS DE SU ARRENDAMIENTO.

Aqui le damos un sumario de sus derechos:

1. Para calificar por compensación bajo la Ley de Limón de Nueva Jersey, usted debe darle al fabricante o a su concesionario la oportunidad de reparar o corregir el defecto del vehículo dentro del término de protección bajo la Ley de Limón, que son las 24,000 millas primeras de operación o dos años después de la fecha original de la entrega del vehículo o lo que suceda primero.
2. Si el fabricante o su concesionario no puede arreglar o corregir el defecto dentro de un tiempo razonable, usted puede tener el derecho de devolver el vehículo y recibir un reembolso completo, menos un descuento por el uso del vehículo.
3. Si se supone que el fabricante o su concesionario no puede reparar o corregir el defecto y si substancialmente el mismo defecto continúa existiendo después que el fabricante ha recibido un aviso del defecto, mandado por correo certificado con recibo de retorno, y ha tenido una oportunidad final para corregir el defecto o condición dentro de los 10 días naturales después de recibir el aviso. Este aviso tiene que ser recibido por el fabricante dentro del término de protección y solo se puede dar después que (i) el fabricante o su concesionario ha intentado dos o más veces de corregir el defecto; (ii) el fabricante o su concesionario ha intentado por lo menos una vez de corregir el defecto si el defecto es uno que puede causar la muerte o serio daño corporal si el vehículo se maneja; o (iii) el vehículo ha estado fuera de servicio por reparos por una acumulación total de 20 días naturales o más, o en el caso de una casa rodante motorizada (motorhome) de 45 días o más.
4. Si substancialmente el mismo defecto continua existiendo después que el fabricante ha tenido la ultima oportunidad de reparar o corregir el defecto, usted puede presentar una solicitud para compensación bajo la Ley de Limón de Nueva Jersey.

PARA INFORMACION COMPLETA ACERCA DE SUS DERECHOS Y RECURSOS BAJO ESTA LEY, INCLUYENDO LA DIRECCIÓN DEL FABRICANTE PARA NOTIFICARLE EL DEFECTO, PÓNGASE EN CONTACTO CON: NEW JERSEY DEPARTMENT OF LAW AND PUBLIC SAFETY, DIVISION OF CONSUMER AFFAIRS, LEMON LAW UNIT, POST OFFICE BOX 45026, NEWARK, NEW JERSEY 07101, NÚMERO DE TELÉFONO (973) 504-6226.

IMPORTANT NOTICE for California Retail Buyers and Lessees of Mercedes-Benz Vehicles

Under California law you may be entitled to a replacement of your vehicle or a refund of the purchase price or lease price, if Mercedes-Benz USA, LLC and/or its authorized repair or service facilities fail to fix one or more substantial defects or malfunctions in the vehicle that are covered by its express warranty after a reasonable number of repair attempts. During the period of 18 months from original delivery of the vehicle or the accumulation of 18 000 miles on the odometer of the vehicle, whichever first occurs, a reasonable number of repair attempts is presumed for a retail buyer or lessee if one or more of the following occurs: (1) the same substantial defect or malfunction results in a condition that is likely to cause death or serious bodily injury if the vehicle is driven, that defect or malfunction has been subject to repair two or more times, and you have directly notified Mercedes-Benz USA, LLC in writing of the need for its repair, (2) the same substantial defect or malfunction of a less serious nature than category (1) has been subject to repair four or more times and you have directly notified us in writing of the need for its repair, or (3) the vehicle is out of service by reason of repair of the same or different substantial defects or malfunctions for a cumulative total of more than 30 calendar days. Written direct notification should be sent to us, not an authorized Mercedes-Benz Center, at Mercedes-Benz USA, LLC, Customer Assistance Center, One Mercedes Drive, Montvale, NJ 07645-0350.

What To Do...

If You Have Questions Regarding Warranty or Service

The satisfaction and goodwill of Mercedes-Benz owners is of primary concern to authorized Mercedes-Benz Centers and MBUSA. In the event a warranty or service matter is not handled to your satisfaction, the following steps are suggested:

FIRST -

Discuss the problem with your authorized Mercedes-Benz Center management. Talk to the Service Manager, then if you still have questions, discuss them with the authorized Mercedes-Benz Center's owner.

THEN -

Request Clarification - If unanswered questions remain, contact Mercedes-Benz USA, LLC, Customer Assistance Center, One Mercedes Drive, Montvale, New Jersey 07645-0350. 1-800-FOR-MERCedes.

When you contact Mercedes-Benz USA, LLC please be sure to include the MODEL, and VEHICLE IDENTIFICATION NUMBER (VIN) of your vehicle. This is important to assure fast, efficient handling of your inquiry.

If You Have Lost the Service and Warranty Information Booklet

Should you lose your Service and Warranty Information booklet, have your local authorized Mercedes-Benz Center arrange for a replacement.

If You Have Changed Your Address

Should your address change, please do not fail to notify us by using the "Notice of Address Change" coupon also contained in the centerfold of this booklet, or you may call 1-800-FOR-MERCedes to provide the information.

SPECIAL ADJUSTMENT PROGRAMS

Sometimes Mercedes-Benz USA, LLC offers a special adjustment program to pay for all or part of the cost of certain repairs beyond the terms of the warranty. Check with your Authorized Mercedes-Benz Center to determine whether any adjustment program is applicable to your automobile.

To Purchasers of Pre-Owned Mercedes-Benz Vehicles

If you have purchased a pre-owned Mercedes-Benz vehicle before the expiration of its original warranty, you are entitled to any unexpired portion of the warranty provided you establish your ownership and the purchase date of the vehicle. Please mail the coupon contained in the centerfold of this booklet to the address shown, or you may call 1-800-FOR-MERCedes to provide the information.

Such notification is likewise necessary for your own safety after expiration of the original warranty.

The "National Traffic & Motor Vehicle Safety Act of 1966" requires Mercedes-Benz USA, LLC to be in a position to contact Mercedes-Benz owners when a correction of a product defect becomes necessary.

Notes

Notes

Internet

For further information you can find us on
the Mercedes-Benz web-site
www.mbusa.com

Service and Literature

Reprinting, translation and copying, even
of excerpts, are not permitted without our
prior authorization in writing.

Press time September, 2010

Printed in U. S. A.

Model

C300, C300 4M, C350, C63 AMG,
GLK350, GLK350 4M, E350 Coupe,
E550 Coupe, E350 Cabriolet,
E550 Cabriolet, E350 4M Wagon,
E350 BlueTEC, E350, E350 4M, E550,
E550 4M, E63 AMG, CLS550,
CLS63 AMG, S400 HYBRID,
S350 4M BlueTEC, S550, S550 4M, S600,
S63 AMG, S65 AMG, CL550 4M, CL600,
CL63 AMG, CL65 AMG, SLK300, SLK350,
SL550, SL600, SL63 AMG, SL65 AMG,
SLS AMG, R350 4M BlueTEC, R350 4M,
ML350 4M BlueTEC, ML350, ML350 4M,
ML450 4M HYBRID, ML550 4M,
ML63 AMG, GL350 4M BlueTEC,
GL450 4M, GL550 4M, G550, G55 AMG

EXHIBIT 36

CUSTOMER #: 45393675

347089

** PRE-INVOICE **
ACCOUNTING

ELLERY RICHARD
8908 GUARD HILL DR
FORT WORTH, TX 76123
ELLERYRICHARD67@GMAIL.COM
HOME: CONT: 817-689-9692
BUS: CELL: 817-689-9692

DUPLICATE 1
PAGE 1

ParkPlace
MOTORCARS FORT WORTH

Park Place Motorcars Ft. Worth
5601 Bryant Irvin Road
Ft. Worth, TX 76132
469-217-4030

SERVICE ADVISOR: 116730 Ernesto Rodriguez

PAINT TRIM	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	11	MB Truck GL550	4JGBF8GE4BA757676		131313/131314	TM458
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
15SEP11 DD			18:00 04OCT23		VARIABLE	CASH
R.O. OPENED	READY		OPTIONS: DLR: 75268 ENG: 5.5_Liter			
12:12 04OCT23	15:29 05OCT23					

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS	LIST	NET	TOTAL
------	--------	------	------	-------	-------	------	-----	-------

A CUSTOMER STATES PERFORM RECALL 2022050015

CAUSE: F

020053 OPERATIONS: CHECK BRAKE UNIT, ACC. NO.: 42

900 05, CODE: 22P4290005

100478	W08	0.69	0.20	680	3744	1	0	37.44	37.44
1	SLEEVE	SLEEVE				2	0	0.02	0.02

1 2 TPARTS

680 3744 TLABOR

VERSION 1 (EMP# 100478,05OCT23 10:08): WRO,,,100478,,CAMPAIGN

2022050015 performed campaign 2022050015Check/test procedure A Check
brake unit Remove rubber sleeve from brake unit and document test
result found corrosion measurements Does not exceed threshold-OK End
measure. performed repairs as per doc

B CUSTOMER STATES PLEASE WASH VEHICLE AFTER SERVICE

NC NO CHARGE

100478	INC	0.00	0.00	0	0		0.00	0.00
--------	-----	------	------	---	---	--	------	------

C CUSTOMER STATES BEST CONTACT 8176899692

BC BEST CONTACT #

100478	INC	0.00	0.00	0	0		0.00	0.00
--------	-----	------	------	---	---	--	------	------

D MULTI POINT INSPECTION

INSP INSP

100478	INC	0.00	0.00	0	0		0.00	0.00
--------	-----	------	------	---	---	--	------	------

VERSION 1 (EMP# 100478,05OCT23 12:51): 100478 TORQUE WHEELS TO
150NM

ESTIMATE: 0.00

04OCT23 12:12 SA: 116730

CONTACT: *www.ParkPlace.com*

DISCLAIMER OF WARRANTIES - Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser or agent for the purchaser, understand and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchases. The undersigned purchaser or agent for the purchaser further agrees that the warranties excluded by dealer, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

AUTHORIZATION FOR REPAIRS - I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The dealership is not responsible for damages from freezing due to lack of antifreeze.

Customer states no articles of personal property have been left in the vehicle and dealer is not responsible for inspection thereof.

**NOTICE PURSUANT TO
§ 70.001, TEXAS PROPERTY CODE**
I am the person or agent acting on behalf of the person, who is obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with §9.609, Texas Business and Commerce Code, if payment for the repair of the motor vehicle by a check, money order, or a credit card transaction is stopped, dishonored because of insufficient funds, no funds, or because the maker or drawer of the order of the credit card holder has no account or the account on which it is drawn or the credit card account has been closed.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE / COUPONS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Signature of Customer or Agent or Person Responsible for Payment

Signature of Customer or Agent or Person
Responsible for Payment

CUSTOMER #: 45393675

347089

** PRE-INVOICE **
*ACCOUNTING*ELLERY RICHARD
8908 GUARD HILL DR
FORT WORTH, TX 76123ELLERYRICHARD67@GMAIL.COM
HOME: CONT: 817-689-9692
BUS: CELL: 817-689-9692DUPLICATE 1
PAGE 2**Park Place**
MOTORCARS FORT WORTHPark Place Motorcars Ft. Worth
5601 Bryant Irvin Road
Ft. Worth, TX 76132
469-217-4030

SERVICE ADVISOR: 116730 Ernesto Rodriguez

PAINT TRIM	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	11	MB Truck GL550	4JGBF8GE4BA757676		131313/131314	TM458
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
15SEP11 DD			18:00 04OCT23		VARIABLE	CASH
R.O. OPENED	READY	OPTIONS: DLR: 75268 ENG: 5.5_Liter				
12:12 04OCT23	15:29 05OCT23					

LINE OPCODE TECH TYPE A/HRS S/HRS LIST NET TOTAL

#M458 CREATED 2023-10-04 We want to send a sincere "THANK YOU", from
 10:39:00AM TAKEN BY BE THAN Y each one of us in the Park Place Motorcars
 BADGER Service Department. We know you have a choice
 when servicing your vehicle and we thank you
 for being a Park Place client!

DATE	START	FINISH	DURATION	TYPE	TECH	LINE(S)	CHG
10-05-23	09:32	10:13	0.69	W	100478	A	

TRGT/ACCOUNT	SALE	COST	CONTROL	TRGT/ACCOUNT	SALE	COST	CONTROL
285/1462310	3744	680		285/1472010	2	1	
285/1463010	0	0		285/1121000	3746	*****	
285/1775003	0	*****					

www.parkplace.com

COST, SALE, & COMP TOTALS 681 3746 0

DISCLAIMER OF WARRANTIES - Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser or agent for the purchaser, understand and agrees that dealer makes no warranties of any kind, express or implied, and disclaims all warranties, including warranties of merchantability or fitness for a particular purpose, with regard to the parts and/or accessories purchased; and that in no event shall dealer be liable for incidental or consequential damages or commercial losses arising out of such purchase. The undersigned purchaser or agent for the purchaser further agrees that the warranties excluded by dealer, include, but are not limited to any warranties that such parts and/or accessories are of merchantable quality or that they will enable any vehicle or any of its systems to perform with reasonable safety, efficiency, or comfort.

AUTHORIZATION FOR REPAIRS - I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The dealership is not responsible for damages from freezing due to lack of antifreeze.

Customer states no articles of personal property have been left in the vehicle and dealer is not responsible for inspection thereof.

NOTICE PURSUANT TO**§ 70.001, TEXAS PROPERTY CODE**

I am the person or agent acting on behalf of the person, who is obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with §9.609, Texas Business and Commerce Code, if payment for the repair of the motor vehicle by a check, money order, or a credit card transaction is stopped, dishonored because of insufficient funds, no funds, or because the maker or drawer of the order of the credit card holder has no account or the account on which it is drawn on the credit card account has been closed.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE / COUPONS	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

Signature of Customer or Agent or Person Responsible for Payment

Signature of Customer or Agent or Person
Responsible for Payment